

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										<b>0.0009</b>			
										<b>NA</b>			
ASBESTOS-ST1-3/3/06	030606846-0001	Southwest Area (sidewalk bridge level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST2-3/3/06	030606846-0002	Southeast Area (sidewalk bridge level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST4-3/3/06	030606846-0003	Northwest Area (street-level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST5-3/3/06	030606846-0004	Firehouse #10 (roof level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST10-3/3/06	030606846-0005	North Side Sidewalk Bridge	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST11-3/3/06	030606846-0006	90 Trinity Place (roof level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST12-3/3/06	030606846-0007	110 Greenwich Street (roof level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST13-3/3/06	030606846-0008	Marriott Hotel, 38th Floor (roof level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST14-3/3/06	030606846-0009	West Face - South end at corner (scaffolding level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST15-3/3/06	030606846-0010	South Face - East end at corner (scaffolding level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST16-3/3/06	030606846-0011	East Face - North end at corner (scaffolding level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST17-3/3/06	030606846-0012	North Face - West end at corner (scaffolding level)	3/3/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST1-3/4/06	030606845-0001	Southwest Area (sidewalk bridge level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST2-3/4/06	030606845-0002	Southeast Area (sidewalk bridge level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST4-3/4/06	030606845-0003	Northwest Area (street-level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST5-3/4/06	030606845-0004	Firehouse #10 (roof level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST10-3/4/06	030606845-0005	North Side Sidewalk Bridge	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST11-3/4/06	030606845-0006	90 Trinity Place (roof level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST12-3/4/06	030606845-0007	110 Greenwich Street (roof level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST13-3/4/06	030606845-0008	Marriott Hotel, 38th Floor (roof level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST14-3/4/06	030606845-0009	West Face - South end at corner (scaffolding level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST15-3/4/06	030606845-0010	South Face - East end at corner (scaffolding level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST16-3/4/06	030606845-0011	East Face - North end at corner (scaffolding level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST17-3/4/06	030606845-0012	North Face - West end at corner (scaffolding level)	3/4/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST1-3/5/06	030606847-0001	Southwest Area (sidewalk bridge level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST2-3/5/06	030606847-0002	Southeast Area (sidewalk bridge level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST4-3/5/06	030606847-0003	Northwest Area (street-level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST5-3/5/06	030606847-0004	Firehouse #10 (roof level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST10-3/5/06	030606847-0005	North Side Sidewalk Bridge	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST11-3/5/06	030606847-0006	90 Trinity Place (roof level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST12-3/5/06	030606847-0007	110 Greenwich Street (roof level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST13-3/5/06	030606847-0008	Marriott Hotel, 38th Floor (roof level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST14-3/5/06	030606847-0009	West Face - South end at corner (scaffolding level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST15-3/5/06	030606847-0010	South Face - East end at corner (scaffolding level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST16-3/5/06	030606847-0011	East Face - North end at corner (scaffolding level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST17-3/5/06	030606847-0012	North Face - West end at corner (scaffolding level)	3/5/06	1	2.970	Asbestos	PCME	EMSL	3/6/06	< 0.00083	No	No	
ASBESTOS-ST1-3/6/06	030606978-0001	Southwest Area (sidewalk bridge level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST2-3/6/06	030606978-0002	Southeast Area (sidewalk bridge level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST4-3/6/06	030606978-0003	Northwest Area (street-level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST5-3/6/06	030606978-0004	Firehouse #10 (roof level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST10-3/6/06	030606978-0005	North Side Sidewalk Bridge	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST11-3/6/06	030606978-0006	90 Trinity Place (roof level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST12-3/6/06	030606978-0007	110 Greenwich Street (roof level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST13-3/6/06	030606978-0008	Marriott Hotel, 38th Floor (roof level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST14-3/6/06	030606978-0009	West Face - South end at corner (scaffolding level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST15-3/6/06	030606978-0010	South Face - East end at corner (scaffolding level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST16-3/6/06	030606978-0011	East Face - North end at corner (scaffolding level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	
ASBESTOS-ST17-3/6/06	030606978-0012	North Face - West end at corner (scaffolding level)	3/6/06	1	2.970	Asbestos	PCME	EMSL	3/7/06	< 0.00083	No	No	