

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Site Specific	
										NA	Levels	Trigger Levels	
ASBESTOS-ST1-3/5/09	030906059-0001	Southwest Area (sidewalk bridge level)	3/5/09	1	3.050	Asbestos	PCME	EMSL	3/6/09	< 0.00081	No	No	
ASBESTOS-ST2-3/5/09	030906059-0002	Southeast Area (sidewalk bridge level)	3/5/09	1	3.000	Asbestos	PCME	EMSL	3/6/09	< 0.00082	No	No	
ASBESTOS-ST4-3/5/09	030906059-0003	Northwest Area (street-level)	3/5/09	1	3.010	Asbestos	PCME	EMSL	3/6/09	< 0.00082	No	No	
ASBESTOS-ST5-3/5/09	030906059-0004	Firehouse #10 (roof level)	3/5/09	1	3.130	Asbestos	PCME	EMSL	3/6/09	< 0.00086	No	No	
ASBESTOS-ST10-3/5/09	030906059-0005	North Side Sidewalk Bridge	3/5/09	1	3.090	Asbestos	PCME	EMSL	3/6/09	< 0.00087	No	No	
ASBESTOS-ST100-3/5/09	030906059-0013	Station 10 Field Duplicate	3/5/09	1	3.040	Asbestos	PCME	EMSL	3/6/09	< 0.00081	No	No	
ASBESTOS-ST11-3/5/09	030906059-0006	90 Trinity Place (roof level)	3/5/09	1	3.090	Asbestos	PCME	EMSL	3/6/09	< 0.00087	No	No	
ASBESTOS-ST12-3/5/09	030906059-0007	110 Greenwich Street (roof level)	3/5/09	1	3.050	Asbestos	PCME	EMSL	3/6/09	< 0.00081	No	No	
ASBESTOS-ST13-3/5/09	030906059-0008	Marriott Hotel, 38th Floor (roof level)	3/5/09	1	3.020	Asbestos	PCME	EMSL	3/6/09	< 0.00082	No	No	
ASBESTOS-ST14-3/5/09	030906059-0009	West Face - South end at corner (scaffolding level)	3/5/09	1	2.980	Asbestos	PCME	EMSL	3/6/09	< 0.00083	No	No	
ASBESTOS-ST15-3/5/09	030906059-0010	South Face - East end at corner (scaffolding level)	3/5/09	1	3.060	Asbestos	PCME	EMSL	3/6/09	< 0.00081	No	No	
ASBESTOS-ST16-3/5/09	030906059-0011	East Face - North end at corner (scaffolding level)	3/5/09	1	3.020	Asbestos	PCME	EMSL	3/6/09	< 0.00082	No	No	
ASBESTOS-ST17-3/5/09	030906059-0012	North Face - West end at corner (scaffolding level)	3/5/09	1	2.950	Asbestos	PCME	EMSL	3/6/09	< 0.00084	No	No	
ASBESTOS-ST1-3/6/09	030906126-0001	Southwest Area (sidewalk bridge level)	3/6/09	1	3.030	Asbestos	PCME	EMSL	3/7/09	< 0.00081	No	No	
ASBESTOS-ST2-3/6/09	030906126-0002	Southeast Area (sidewalk bridge level)	3/6/09	1	2.940	Asbestos	PCME	EMSL	3/7/09	< 0.00084	No	No	
ASBESTOS-ST4-3/6/09	030906126-0003	Northwest Area (street-level)	3/6/09	1	2.980	Asbestos	PCME	EMSL	3/7/09	< 0.00083	No	No	
ASBESTOS-ST5-3/6/09	030906126-0004	Firehouse #10 (roof level)	3/6/09	1	2.940	Asbestos	PCME	EMSL	3/7/09	< 0.00084	No	No	
ASBESTOS-ST10-3/6/09	030906126-0005	North Side Sidewalk Bridge	3/6/09	1	3.030	Asbestos	PCME	EMSL	3/7/09	< 0.00081	No	No	
ASBESTOS-ST11-3/6/09	030906126-0006	90 Trinity Place (roof level)	3/6/09	1	2.950	Asbestos	PCME	EMSL	3/7/09	< 0.00084	No	No	
ASBESTOS-ST12-3/6/09	030906126-0007	110 Greenwich Street (roof level)	3/6/09	1	2.920	Asbestos	PCME	EMSL	3/7/09	< 0.00085	No	No	
ASBESTOS-ST13-3/6/09	030906126-0008	Marriott Hotel, 38th Floor (roof level)	3/6/09	1	3.040	Asbestos	PCME	EMSL	3/7/09	< 0.00081	No	No	
ASBESTOS-ST14-3/6/09	030906126-0009	West Face - South end at corner (scaffolding level)	3/6/09	1	2.830	Asbestos	PCME	EMSL	3/7/09	< 0.00087	No	No	
ASBESTOS-ST15-3/6/09	030906126-0010	South Face - East end at corner (scaffolding level)	3/6/09	1	2.800	Asbestos	PCME	EMSL	3/7/09	< 0.00088	No	No	
ASBESTOS-ST16-3/6/09	030906126-0011	East Face - North end at corner (scaffolding level)	3/6/09	1	2.850	Asbestos	PCME	EMSL	3/7/09	< 0.00087	No	No	
ASBESTOS-ST17-3/6/09	030906126-0012	North Face - West end at corner (scaffolding level)	3/6/09	1	2.790	Asbestos	PCME	EMSL	3/7/09	< 0.00088	No	No	
ASBESTOS-ST1-3/7/09	030906234-0001	Southwest Area (sidewalk bridge level)	3/7/09	1	2.960	Asbestos	PCME	EMSL	3/9/09	< 0.00083	No	No	
ASBESTOS-ST2-3/7/09	030906234-0002	Southeast Area (sidewalk bridge level)	3/7/09	1	2.920	Asbestos	PCME	EMSL	3/9/09	< 0.00085	No	No	
ASBESTOS-ST4-3/7/09	030906234-0003	Northwest Area (street-level)	3/7/09	1	2.960	Asbestos	PCME	EMSL	3/9/09	< 0.00083	No	No	
ASBESTOS-ST5-3/7/09	030906234-0004	Firehouse #10 (roof level)	3/7/09	1	2.850	Asbestos	PCME	EMSL	3/9/09	< 0.00087	No	No	
ASBESTOS-ST10-3/7/09	030906234-0005	North Side Sidewalk Bridge	3/7/09	1	2.970	Asbestos	PCME	EMSL	3/9/09	< 0.00083	No	No	
ASBESTOS-ST11-3/7/09	030906234-0006	90 Trinity Place (roof level)	3/7/09	1	2.840	Asbestos	PCME	EMSL	3/9/09	< 0.00087	No	No	
ASBESTOS-ST12-3/7/09	030906234-0007	110 Greenwich Street (roof level)	3/7/09	1	2.930	Asbestos	PCME	EMSL	3/9/09	< 0.00084	No	No	
ASBESTOS-ST13-3/7/09	030906234-0008	Marriott Hotel, 38th Floor (roof level)	3/7/09	1	2.930	Asbestos	PCME	EMSL	3/9/09	< 0.00084	No	No	
ASBESTOS-ST14-3/7/09	030906234-0009	West Face - South end at corner (scaffolding level)	3/7/09	1	2.950	Asbestos	PCME	EMSL	3/9/09	< 0.00084	No	No	
ASBESTOS-ST15-3/7/09	030906234-0010	South Face - East end at corner (scaffolding level)	3/7/09	1	2.900	Asbestos	PCME	EMSL	3/9/09	< 0.00085	No	No	
ASBESTOS-ST16-3/7/09	030906234-0011	East Face - North end at corner (scaffolding level)	3/7/09	1	2.890	Asbestos	PCME	EMSL	3/9/09	< 0.00085	No	No	
ASBESTOS-ST17-3/7/09	030906234-0012	North Face - West end at corner (scaffolding level)	3/7/09	1	2.910	Asbestos	PCME	EMSL	3/9/09	< 0.00085	No	No	
ASBESTOS-ST1-3/8/09	030906227-0001	Southwest Area (sidewalk bridge level)	3/8/09	1	3.080	Asbestos	PCME	EMSL	3/9/09	< 0.00080	No	No	
ASBESTOS-ST2-3/8/09	030906227-0002	Southeast Area (sidewalk bridge level)	3/8/09	1	3.150	Asbestos	PCME	EMSL	3/9/09	< 0.00078	No	No	
ASBESTOS-ST4-3/8/09	030906227-0003	Northwest Area (street-level)	3/8/09	1	3.130	Asbestos	PCME	EMSL	3/9/09	< 0.00079	No	No	
ASBESTOS-ST5-3/8/09	030906227-0004	Firehouse #10 (roof level)	3/8/09	1	3.090	Asbestos	PCME	EMSL	3/9/09	< 0.00080	No	No	
ASBESTOS-ST10-3/8/09	030906227-0005	North Side Sidewalk Bridge	3/8/09	1	3.070	Asbestos	PCME	EMSL	3/9/09	< 0.00080	No	No	
ASBESTOS-ST11-3/8/09	030906227-0006	90 Trinity Place (roof level)	3/8/09	1	3.110	Asbestos	PCME	EMSL	3/9/09	< 0.00079	No	No	
ASBESTOS-ST12-3/8/09	030906227-0007	110 Greenwich Street (roof level)	3/8/09	1	3.060	Asbestos	PCME	EMSL	3/9/09	< 0.00081	No	No	
ASBESTOS-ST13-3/8/09	030906227-0008	Marriott Hotel, 38th Floor (roof level)	3/8/09	1	3.040	Asbestos	PCME	EMSL	3/9/09	< 0.00081	No	No	
ASBESTOS-ST14-3/8/09	030906227-0009	West Face - South end at corner (scaffolding level)	3/8/09	1	3.270	Asbestos	PCME	EMSL	3/9/09	< 0.00075	No	No	
ASBESTOS-ST15-3/8/09	030906227-0010	South Face - East end at corner (scaffolding level)	3/8/09	1	3.270	Asbestos	PCME	EMSL	3/9/09	< 0.00075	No	No	
ASBESTOS-ST16-3/8/09	030906227-0011	East Face - North end at corner (scaffolding level)	3/8/09	1	3.180	Asbestos	PCME	EMSL	3/9/09	< 0.00078	No	No	
ASBESTOS-ST17-3/8/09	030906227-0012	North Face - West end at corner (scaffolding level)	3/8/09	1	3.140	Asbestos	PCME	EMSL	3/9/09	< 0.00079	No	No	