

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Exceeds EPA	
										NA	Levels	Site Specific	
											Trigger Levels	Trigger Levels	
ASBESTOS-ST1-3/10/06	030607639-0001	Southwest Area (sidewalk bridge level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST2-3/10/06	030607639-0002	Southeast Area (sidewalk bridge level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST4-3/10/06	030607639-0003	Northwest Area (street-level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST5-3/10/06	030607639-0004	Firehouse #10 (roof level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST10-3/10/06	030607639-0005	North Side Sidewalk Bridge	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST11-3/10/06	030607639-0006	90 Trinity Place (roof level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST12-3/10/06	030607639-0007	110 Greenwich Street (roof level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST13-3/10/06	030607639-0008	Marriott Hotel, 38th Floor (roof level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST14-3/10/06	030607639-0009	West Face - South end at corner (scaffolding level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST15-3/10/06	030607639-0010	South Face - East end at corner (scaffolding level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST16-3/10/06	030607639-0011	East Face - North end at corner (scaffolding level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST17-3/10/06	030607639-0012	North Face - West end at corner (scaffolding level)	3/10/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST1-3/11/06	030607634-0001	Southwest Area (sidewalk bridge level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST2-3/11/06	030607634-0002	Southeast Area (sidewalk bridge level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST4-3/11/06	030607634-0003	Northwest Area (street-level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST5-3/11/06	030607634-0004	Firehouse #10 (roof level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST10-3/11/06	030607634-0005	North Side Sidewalk Bridge	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST11-3/11/06	030607634-0006	90 Trinity Place (roof level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST12-3/11/06	030607634-0007	110 Greenwich Street (roof level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST13-3/11/06	030607634-0008	Marriott Hotel, 38th Floor (roof level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST14-3/11/06	030607634-0009	West Face - South end at corner (scaffolding level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST15-3/11/06	030607634-0010	South Face - East end at corner (scaffolding level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST16-3/11/06	030607634-0011	East Face - North end at corner (scaffolding level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST17-3/11/06	030607634-0012	North Face - West end at corner (scaffolding level)	3/11/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST1-3/12/06	030607641-0001	Southwest Area (sidewalk bridge level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST2-3/12/06	030607641-0002	Southeast Area (sidewalk bridge level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST4-3/12/06	030607641-0003	Northwest Area (street-level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST5-3/12/06	030607641-0004	Firehouse #10 (roof level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST10-3/12/06	030607641-0005	North Side Sidewalk Bridge	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST11-3/12/06	030607641-0006	90 Trinity Place (roof level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST12-3/12/06	030607641-0007	110 Greenwich Street (roof level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST13-3/12/06	030607641-0008	Marriott Hotel, 38th Floor (roof level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST14-3/12/06	030607641-0009	West Face - South end at corner (scaffolding level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST15-3/12/06	030607641-0010	South Face - East end at corner (scaffolding level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST16-3/12/06	030607641-0011	East Face - North end at corner (scaffolding level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST17-3/12/06	030607641-0012	North Face - West end at corner (scaffolding level)	3/12/06	1	3.000	Asbestos	PCME	EMSL	3/13/06	< 0.00082	No	No	
ASBESTOS-ST1-3/13/06	030607755-0001	Southwest Area (sidewalk bridge level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST2-3/13/06	030607755-0002	Southeast Area (sidewalk bridge level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST4-3/13/06	030607755-0003	Northwest Area (street-level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST5-3/13/06	030607755-0004	Firehouse #10 (roof level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST10-3/13/06	030607755-0005	North Side Sidewalk Bridge	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST11-3/13/06	030607755-0006	90 Trinity Place (roof level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST12-3/13/06	030607755-0007	110 Greenwich Street (roof level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST13-3/13/06	030607755-0008	Marriott Hotel, 38th Floor (roof level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST14-3/13/06	030607755-0009	West Face - South end at corner (scaffolding level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST15-3/13/06	030607755-0010	South Face - East end at corner (scaffolding level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	
ASBESTOS-ST17-3/13/06	030607755-0012	North Face - West end at corner (scaffolding level)	3/13/06	1	3.000	Asbestos	PCME	EMSL	3/14/06	< 0.00082	No	No	

Note:

1. The asbestos sample at Station 16 (East Face - North end at corner [scaffolding level]) on March 13, 2006 was not available for analysis on account of filter damage.