

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-3/10/09	030906489-0001	Southwest Area (sidewalk bridge level)	3/10/09	1	3.130	Asbestos	PCME	EMSL	3/11/09	< 0.00086	No	No	
ASBESTOS-ST2-3/10/09	030906489-0002	Southeast Area (sidewalk bridge level)	3/10/09	1	3.140	Asbestos	PCME	EMSL	3/11/09	< 0.00079	No	No	
ASBESTOS-ST4-3/10/09	030906489-0003	Northwest Area (street-level)	3/10/09	1	3.020	Asbestos	PCME	EMSL	3/11/09	< 0.00082	No	No	
ASBESTOS-ST5-3/10/09	030906489-0004	Firehouse #10 (roof level)	3/10/09	1	3.030	Asbestos	PCME	EMSL	3/11/09	< 0.00081	No	No	
ASBESTOS-ST10-3/10/09	030906489-0005	North Side Sidewalk Bridge	3/10/09	1	3.090	Asbestos	PCME	EMSL	3/11/09	< 0.00080	No	No	
ASBESTOS-ST11-3/10/09	030906489-0006	90 Trinity Place (roof level)	3/10/09	1	3.060	Asbestos	PCME	EMSL	3/11/09	< 0.00081	No	No	
ASBESTOS-ST12-3/10/09	030906489-0007	110 Greenwich Street (roof level)	3/10/09	1	3.100	Asbestos	PCME	EMSL	3/11/09	< 0.00087	No	No	
ASBESTOS-ST13-3/10/09	030906489-0008	Marriott Hotel, 38th Floor (roof level)	3/10/09	1	3.050	Asbestos	PCME	EMSL	3/11/09	< 0.00081	No	No	
ASBESTOS-ST14-3/10/09	030906489-0009	West Face - South end at corner (scaffolding level)	3/10/09	1	3.050	Asbestos	PCME	EMSL	3/11/09	< 0.00081	No	No	
ASBESTOS-ST15-3/10/09	030906489-0010	South Face - East end at corner (scaffolding level)	3/10/09	1	2.930	Asbestos	PCME	EMSL	3/11/09	< 0.00084	No	No	
ASBESTOS-ST16-3/10/09	030906489-0011	East Face - North end at corner (scaffolding level)	3/10/09	1	2.970	Asbestos	PCME	EMSL	3/11/09	< 0.00083	No	No	
ASBESTOS-ST17-3/10/09	030906489-0012	North Face - West end at corner (scaffolding level)	3/10/09	1	3.020	Asbestos	PCME	EMSL	3/11/09	< 0.00082	No	No	
ASBESTOS-ST1-03/11/09	030906576-0001	Southwest Area (sidewalk bridge level)	3/11/09	1	3.140	Asbestos	PCME	EMSL	3/12/09	< 0.00079	No	No	
ASBESTOS-ST2-03/11/09	030906576-0002	Southeast Area (sidewalk bridge level)	3/11/09	1	3.110	Asbestos	PCME	EMSL	3/12/09	< 0.00079	No	No	
ASBESTOS-ST4-03/11/09	030906576-0003	Northwest Area (street-level)	3/11/09	1	3.050	Asbestos	PCME	EMSL	3/12/09	< 0.00081	No	No	
ASBESTOS-ST5-03/11/09	030906576-0004	Firehouse #10 (roof level)	3/11/09	1	3.040	Asbestos	PCME	EMSL	3/12/09	< 0.00081	No	No	
ASBESTOS-ST10-03/11/09	030906576-0005	North Side Sidewalk Bridge	3/11/09	1	3.080	Asbestos	PCME	EMSL	3/12/09	< 0.00080	No	No	
ASBESTOS-ST11-03/11/09	030906576-0006	90 Trinity Place (roof level)	3/11/09	1	2.990	Asbestos	PCME	EMSL	3/12/09	< 0.00083	No	No	
ASBESTOS-ST12-03/11/09	030906576-0007	110 Greenwich Street (roof level)	3/11/09	1	2.940	Asbestos	PCME	EMSL	3/12/09	< 0.00084	No	No	
ASBESTOS-ST13-03/11/09	030906576-0008	Marriott Hotel, 38th Floor (roof level)	3/11/09	1	3.040	Asbestos	PCME	EMSL	3/12/09	< 0.00081	No	No	
ASBESTOS-ST14-03/11/09	030906576-0009	West Face - South end at corner (scaffolding level)	3/11/09	1	2.980	Asbestos	PCME	EMSL	3/12/09	< 0.00083	No	No	
ASBESTOS-ST15-03/11/09	030906576-0010	South Face - East end at corner (scaffolding level)	3/11/09	1	2.950	Asbestos	PCME	EMSL	3/12/09	< 0.00084	No	No	
ASBESTOS-ST16-03/11/09	030906576-0011	East Face - North end at corner (scaffolding level)	3/11/09	1	2.920	Asbestos	PCME	EMSL	3/12/09	< 0.00085	No	No	
ASBESTOS-ST17-03/11/09	030906576-0012	North Face - West end at corner (scaffolding level)	3/11/09	1	2.930	Asbestos	PCME	EMSL	3/12/09	< 0.00084	No	No	
ASBESTOS-ST1-03/12/09	030906692-0001	Southwest Area (sidewalk bridge level)	3/12/09	1	3.120	Asbestos	PCME	EMSL	3/13/09	< 0.00086	No	No	
ASBESTOS-ST2-03/12/09	030906692-0002	Southeast Area (sidewalk bridge level)	3/12/09	1	3.080	Asbestos	PCME	EMSL	3/13/09	< 0.00087	No	No	
ASBESTOS-ST4-03/12/09	030906692-0003	Northwest Area (street-level)	3/12/09	1	2.890	Asbestos	PCME	EMSL	3/13/09	< 0.00085	No	No	
ASBESTOS-ST5-03/12/09	030906692-0004	Firehouse #10 (roof level)	3/12/09	1	3.040	Asbestos	PCME	EMSL	3/13/09	< 0.00081	No	No	
ASBESTOS-ST10-03/12/09	030906692-0005	North Side Sidewalk Bridge	3/12/09	1	2.880	Asbestos	PCME	EMSL	3/13/09	< 0.00086	No	No	
ASBESTOS-ST100-03/12/09	030906692-0013	Station 10 Field Duplicate	3/12/09	1	2.860	Asbestos	PCME	EMSL	3/13/09	< 0.00086	No	No	
ASBESTOS-ST11-03/12/09	030906692-0006	90 Trinity Place (roof level)	3/12/09	1	3.000	Asbestos	PCME	EMSL	3/13/09	< 0.00082	No	No	
ASBESTOS-ST12-03/12/09	030906692-0007	110 Greenwich Street (roof level)	3/12/09	1	3.020	Asbestos	PCME	EMSL	3/13/09	< 0.00082	No	No	
ASBESTOS-ST13-03/12/09	030906692-0008	Marriott Hotel, 38th Floor (roof level)	3/12/09	1	2.980	Asbestos	PCME	EMSL	3/13/09	< 0.00083	No	No	
ASBESTOS-ST14-03/12/09	030906692-0009	West Face - South end at corner (scaffolding level)	3/12/09	1	3.050	Asbestos	PCME	EMSL	3/13/09	< 0.00081	No	No	
ASBESTOS-ST15-03/12/09	030906692-0010	South Face - East end at corner (scaffolding level)	3/12/09	1	2.940	Asbestos	PCME	EMSL	3/13/09	< 0.00084	No	No	
ASBESTOS-ST16-03/12/09	030906692-0011	East Face - North end at corner (scaffolding level)	3/12/09	1	2.960	Asbestos	PCME	EMSL	3/13/09	< 0.00083	No	No	
ASBESTOS-ST17-03/12/09	030906692-0012	North Face - West end at corner (scaffolding level)	3/12/09	1	2.970	Asbestos	PCME	EMSL	3/13/09	< 0.00083	No	No	
ASBESTOS-ST1-3/13/09	030906744-0001	Southwest Area (sidewalk bridge level)	3/13/09	1	2.930	Asbestos	PCME	EMSL	3/14/09	< 0.00084	No	No	
ASBESTOS-ST2-3/13/09	030906744-0002	Southeast Area (sidewalk bridge level)	3/13/09	1	2.830	Asbestos	PCME	EMSL	3/14/09	< 0.00087	No	No	
ASBESTOS-ST4-3/13/09	030906744-0003	Northwest Area (street-level)	3/13/09	1	2.920	Asbestos	PCME	EMSL	3/14/09	< 0.00085	No	No	
ASBESTOS-ST5-3/13/09	030906744-0004	Firehouse #10 (roof level)	3/13/09	1	3.040	Asbestos	PCME	EMSL	3/14/09	< 0.00081	No	No	
ASBESTOS-ST10-3/13/09	030906744-0005	North Side Sidewalk Bridge	3/13/09	1	2.880	Asbestos	PCME	EMSL	3/14/09	< 0.00086	No	No	
ASBESTOS-ST11-3/13/09	030906744-0006	90 Trinity Place (roof level)	3/13/09	1	2.940	Asbestos	PCME	EMSL	3/14/09	< 0.00084	No	No	
ASBESTOS-ST12-3/13/09	030906744-0007	110 Greenwich Street (roof level)	3/13/09	1	2.840	Asbestos	PCME	EMSL	3/14/09	< 0.00087	No	No	
ASBESTOS-ST13-3/13/09	030906744-0008	Marriott Hotel, 38th Floor (roof level)	3/13/09	1	2.990	Asbestos	PCME	EMSL	3/14/09	< 0.00083	No	No	
ASBESTOS-ST14-3/13/09	030906744-0009	West Face - South end at corner (scaffolding level)	3/13/09	1	2.720	Asbestos	PCME	EMSL	3/14/09	< 0.00084	No	No	
ASBESTOS-ST15-3/13/09	030906744-0010	South Face - East end at corner (scaffolding level)	3/13/09	1	2.690	Asbestos	PCME	EMSL	3/14/09	< 0.00085	No	No	
ASBESTOS-ST16-3/13/09	030906744-0011	East Face - North end at corner (scaffolding level)	3/13/09	1	2.650	Asbestos	PCME	EMSL	3/14/09	< 0.00086	No	No	
ASBESTOS-ST17-3/13/09	030906744-0012	North Face - West end at corner (scaffolding level)	3/13/09	1	2.630	Asbestos	PCME	EMSL	3/14/09	< 0.00087	No	No	