

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-3/17/09	030907049-0001	Southwest Area (sidewalk bridge level)	3/17/09	1	3.160	Asbestos	PCME	EMSL	3/18/09	< 0.00078	No	No	
ASBESTOS-ST2-3/17/09	030907049-0002	Southeast Area (sidewalk bridge level)	3/17/09	1	3.120	Asbestos	PCME	EMSL	3/18/09	< 0.00079	No	No	
ASBESTOS-ST4-3/17/09	030907049-0003	Northwest Area (street-level)	3/17/09	1	3.100	Asbestos	PCME	EMSL	3/18/09	0.00080	No	No	
ASBESTOS-ST5-3/17/09	030907049-0004	Firehouse #10 (roof level)	3/17/09	1	3.010	Asbestos	PCME	EMSL	3/18/09	< 0.00082	No	No	
ASBESTOS-ST10-3/17/09	030907049-0005	North Side Sidewalk Bridge	3/17/09	1	3.060	Asbestos	PCME	EMSL	3/18/09	< 0.00081	No	No	
ASBESTOS-ST11-3/17/09	030907049-0006	90 Trinity Place (roof level)	3/17/09	1	3.060	Asbestos	PCME	EMSL	3/18/09	< 0.00081	No	No	
ASBESTOS-ST12-3/17/09	030907049-0007	110 Greenwich Street (roof level)	3/17/09	1	3.030	Asbestos	PCME	EMSL	3/18/09	< 0.00081	No	No	
ASBESTOS-ST13-3/17/09	030907049-0008	Marriott Hotel, 38th Floor (roof level)	3/17/09	1	3.050	Asbestos	PCME	EMSL	3/18/09	< 0.00081	No	No	
ASBESTOS-ST14-3/17/09	030907049-0009	West Face - South end at corner (scaffolding level)	3/17/09	1	3.140	Asbestos	PCME	EMSL	3/18/09	< 0.00079	No	No	
ASBESTOS-ST15-3/17/09	030907049-0010	South Face - East end at corner (scaffolding level)	3/17/09	1	3.000	Asbestos	PCME	EMSL	3/18/09	< 0.00082	No	No	
ASBESTOS-ST16-3/17/09	030907049-0011	East Face - North end at corner (scaffolding level)	3/17/09	1	3.070	Asbestos	PCME	EMSL	3/18/09	< 0.00080	No	No	
ASBESTOS-ST17-3/17/09	030907049-0012	North Face - West end at corner (scaffolding level)	3/17/09	1	3.160	Asbestos	PCME	EMSL	3/18/09	< 0.00078	No	No	
ASBESTOS-ST1-3/18/09	030907146-0001	Southwest Area (sidewalk bridge level)	3/18/09	1	3.110	Asbestos	PCME	EMSL	3/19/09	< 0.00079	No	No	
ASBESTOS-ST2-3/18/09	030907146-0002	Southeast Area (sidewalk bridge level)	3/18/09	1	3.100	Asbestos	PCME	EMSL	3/19/09	< 0.00080	No	No	
ASBESTOS-ST4-3/18/09	030907146-0003	Northwest Area (street-level)	3/18/09	1	2.980	Asbestos	PCME	EMSL	3/19/09	< 0.00083	No	No	
ASBESTOS-ST5-3/18/09	030907146-0004	Firehouse #10 (roof level)	3/18/09	1	3.050	Asbestos	PCME	EMSL	3/19/09	< 0.00081	No	No	
ASBESTOS-ST10-3/18/09	030907146-0005	North Side Sidewalk Bridge	3/18/09	1	3.060	Asbestos	PCME	EMSL	3/19/09	< 0.00081	No	No	
ASBESTOS-ST11-3/18/09	030907146-0006	90 Trinity Place (roof level)	3/18/09	1	3.030	Asbestos	PCME	EMSL	3/19/09	< 0.00081	No	No	
ASBESTOS-ST12-3/18/09	030907146-0007	110 Greenwich Street (roof level)	3/18/09	1	2.950	Asbestos	PCME	EMSL	3/19/09	< 0.00084	No	No	
ASBESTOS-ST13-3/18/09	030907146-0008	Marriott Hotel, 38th Floor (roof level)	3/18/09	1	3.030	Asbestos	PCME	EMSL	3/19/09	< 0.00081	No	No	
ASBESTOS-ST14-3/18/09	030907146-0009	West Face - South end at corner (scaffolding level)	3/18/09	1	3.080	Asbestos	PCME	EMSL	3/19/09	< 0.00080	No	No	
ASBESTOS-ST15-3/18/09	030907146-0010	South Face - East end at corner (scaffolding level)	3/18/09	1	3.180	Asbestos	PCME	EMSL	3/19/09	< 0.00078	No	No	
ASBESTOS-ST16-3/18/09	030907146-0011	East Face - North end at corner (scaffolding level)	3/18/09	1	3.050	Asbestos	PCME	EMSL	3/19/09	< 0.00081	No	No	
ASBESTOS-ST17-3/18/09	030907146-0012	North Face - West end at corner (scaffolding level)	3/18/09	1	3.050	Asbestos	PCME	EMSL	3/19/09	< 0.00081	No	No	
ASBESTOS-ST1-3/19/09	030907235-0001	Southwest Area (sidewalk bridge level)	3/19/09	1	3.030	Asbestos	PCME	EMSL	3/20/09	0.00081	No	No	
ASBESTOS-ST2-3/19/09	030907235-0002	Southeast Area (sidewalk bridge level)	3/19/09	1	3.120	Asbestos	PCME	EMSL	3/20/09	< 0.00079	No	No	
ASBESTOS-ST4-3/19/09	030907235-0003	Northwest Area (street-level)	3/19/09	1	3.040	Asbestos	PCME	EMSL	3/20/09	< 0.00081	No	No	
ASBESTOS-ST5-3/19/09	030907235-0004	Firehouse #10 (roof level)	3/19/09	1	2.980	Asbestos	PCME	EMSL	3/20/09	< 0.00083	No	No	
ASBESTOS-ST10-3/19/09	030907235-0005	North Side Sidewalk Bridge	3/19/09	1	2.990	Asbestos	PCME	EMSL	3/20/09	< 0.00083	No	No	
ASBESTOS-ST11-3/19/09	030907235-0006	90 Trinity Place (roof level)	3/19/09	1	3.010	Asbestos	PCME	EMSL	3/20/09	< 0.00082	No	No	
ASBESTOS-ST12-3/19/09	030907235-0007	110 Greenwich Street (roof level)	3/19/09	1	2.960	Asbestos	PCME	EMSL	3/20/09	< 0.00083	No	No	
ASBESTOS-ST13-3/19/09	030907235-0008	Marriott Hotel, 38th Floor (roof level)	3/19/09	1	3.010	Asbestos	PCME	EMSL	3/20/09	< 0.00082	No	No	
ASBESTOS-ST15-3/19/09	030907235-0009	South Face - East end at corner (scaffolding level)	3/19/09	1	2.960	Asbestos	PCME	EMSL	3/20/09	< 0.00083	No	No	
ASBESTOS-ST16-3/19/09	030907235-0010	East Face - North end at corner (scaffolding level)	3/19/09	1	3.000	Asbestos	PCME	EMSL	3/20/09	< 0.00082	No	No	
ASBESTOS-ST17-3/19/09	030907235-0011	North Face - West end at corner (scaffolding level)	3/19/09	1	3.040	Asbestos	PCME	EMSL	3/20/09	< 0.00081	No	No	
ASBESTOS-ST1-3/20/09	030907311-0001	Southwest Area (sidewalk bridge level)	3/20/09	1	3.020	Asbestos	PCME	EMSL	3/21/09	< 0.00082	No	No	
ASBESTOS-ST2-3/20/09	030907311-0002	Southeast Area (sidewalk bridge level)	3/20/09	1	3.070	Asbestos	PCME	EMSL	3/21/09	< 0.00088	No	No	
ASBESTOS-ST4-3/20/09	030907311-0003	Northwest Area (street-level)	3/20/09	1	3.040	Asbestos	PCME	EMSL	3/21/09	< 0.00081	No	No	
ASBESTOS-ST5-3/20/09	030907311-0004	Firehouse #10 (roof level)	3/20/09	1	2.970	Asbestos	PCME	EMSL	3/21/09	< 0.00083	No	No	
ASBESTOS-ST10-3/20/09	030907311-0005	North Side Sidewalk Bridge	3/20/09	1	3.080	Asbestos	PCME	EMSL	3/21/09	< 0.00087	No	No	
ASBESTOS-ST11-3/20/09	030907311-0006	90 Trinity Place (roof level)	3/20/09	1	2.990	Asbestos	PCME	EMSL	3/21/09	< 0.00083	No	No	
ASBESTOS-ST12-3/20/09	030907311-0007	110 Greenwich Street (roof level)	3/20/09	1	3.020	Asbestos	PCME	EMSL	3/21/09	< 0.00082	No	No	
ASBESTOS-ST13-3/20/09	030907311-0008	Marriott Hotel, 38th Floor (roof level)	3/20/09	1	3.030	Asbestos	PCME	EMSL	3/21/09	< 0.00081	No	No	
ASBESTOS-ST14-3/20/09	030907311-0009	West Face - South end at corner (scaffolding level)	3/20/09	1	2.590	Asbestos	PCME	EMSL	3/21/09	< 0.00088	No	No	
ASBESTOS-ST15-3/20/09	030907311-0010	South Face - East end at corner (scaffolding level)	3/20/09	1	2.900	Asbestos	PCME	EMSL	3/21/09	< 0.00085	No	No	
ASBESTOS-ST16-3/20/09	030907311-0011	East Face - North end at corner (scaffolding level)	3/20/09	1	2.990	Asbestos	PCME	EMSL	3/21/09	< 0.00083	No	No	
ASBESTOS-ST17-3/20/09	030907311-0012	North Face - West end at corner (scaffolding level)	3/20/09	1	2.920	Asbestos	PCME	EMSL	3/21/09	< 0.00085	No	No	

Note:

1. The asbestos sample from Staion 14 (West Face - South end at corner [scaffolding level]) on March 19, 2009 was not available for analysis on account of power failure.