

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Site Specific	
										NA	Levels	Trigger Levels	
										< 0.00082	No	No	
ASBESTOS-ST1-3/23/07	030709202-0001	Southwest Area (sidewalk bridge level)	3/23/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST2-3/23/07	030709202-0002	Southeast Area (sidewalk bridge level)	3/23/07	1	3.280	Asbestos	PCME	EMSL	3/26/07	< 0.00075	No	No	
ASBESTOS-ST4-3/23/07	030709202-0003	Northwest Area (street-level)	3/23/07	1	3.340	Asbestos	PCME	EMSL	3/26/07	< 0.00074	No	No	
ASBESTOS-ST5-3/23/07	030709202-0004	Firehouse #10 (roof level)	3/23/07	1	2.990	Asbestos	PCME	EMSL	3/26/07	< 0.00083	No	No	
ASBESTOS-ST10-3/23/07	030709202-0005	North Side Sidewalk Bridge	3/23/07	1	3.040	Asbestos	PCME	EMSL	3/26/07	< 0.00081	No	No	
ASBESTOS-ST11-3/23/07	030709202-0006	90 Trinity Place (roof level)	3/23/07	1	3.040	Asbestos	PCME	EMSL	3/26/07	< 0.00081	No	No	
ASBESTOS-ST12-3/23/07	030709202-0007	110 Greenwich Street (roof level)	3/23/07	1	2.990	Asbestos	PCME	EMSL	3/26/07	< 0.00083	No	No	
ASBESTOS-ST13-3/23/07	030709202-0008	Marriott Hotel, 38th Floor (roof level)	3/23/07	1	2.990	Asbestos	PCME	EMSL	3/26/07	< 0.00083	No	No	
ASBESTOS-ST14-3/23/07	030709202-0009	West Face - South end at corner (scaffolding level)	3/23/07	1	3.030	Asbestos	PCME	EMSL	3/26/07	< 0.00081	No	No	
ASBESTOS-ST15-3/23/07	030709202-0010	South Face - East end at corner (scaffolding level)	3/23/07	1	3.010	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST16-3/23/07	030709202-0011	East Face - North end at corner (scaffolding level)	3/23/07	1	3.030	Asbestos	PCME	EMSL	3/26/07	< 0.00081	No	No	
ASBESTOS-ST17-3/23/07	030709202-0012	North Face - West end at corner (scaffolding level)	3/23/07	1	3.030	Asbestos	PCME	EMSL	3/26/07	< 0.00081	No	No	
ASBESTOS-ST1-3/24/07	030709203-0001	Southwest Area (sidewalk bridge level)	3/24/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST2-3/24/07	030709203-0002	Southeast Area (sidewalk bridge level)	3/24/07	1	2.980	Asbestos	PCME	EMSL	3/26/07	< 0.00083	No	No	
ASBESTOS-ST4-3/24/07	030709203-0003	Northwest Area (street-level)	3/24/07	1	2.900	Asbestos	PCME	EMSL	3/26/07	< 0.00085	No	No	
ASBESTOS-ST5-3/24/07	030709203-0004	Firehouse #10 (roof level)	3/24/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST10-3/24/07	030709203-0005	North Side Sidewalk Bridge	3/24/07	1	3.000	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST11-3/24/07	030709203-0006	90 Trinity Place (roof level)	3/24/07	1	3.040	Asbestos	PCME	EMSL	3/26/07	< 0.00081	No	No	
ASBESTOS-ST12-3/24/07	030709203-0007	110 Greenwich Street (roof level)	3/24/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST13-3/24/07	030709203-0008	Marriott Hotel, 38th Floor (roof level)	3/24/07	1	3.030	Asbestos	PCME	EMSL	3/26/07	< 0.00081	No	No	
ASBESTOS-ST14-3/24/07	030709203-0009	West Face - South end at corner (scaffolding level)	3/24/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST15-3/24/07	030709203-0010	South Face - East end at corner (scaffolding level)	3/24/07	1	3.040	Asbestos	PCME	EMSL	3/26/07	< 0.00081	No	No	
ASBESTOS-ST16-3/24/07	030709203-0011	East Face - North end at corner (scaffolding level)	3/24/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST17-3/24/07	030709203-0012	North Face - West end at corner (scaffolding level)	3/24/07	1	3.040	Asbestos	PCME	EMSL	3/26/07	< 0.00081	No	No	
ASBESTOS-ST1-3/25/07	030709204-0001	Southwest Area (sidewalk bridge level)	3/25/07	1	3.120	Asbestos	PCME	EMSL	3/26/07	< 0.00079	No	No	
ASBESTOS-ST2-3/25/07	030709204-0002	Southeast Area (sidewalk bridge level)	3/25/07	1	2.960	Asbestos	PCME	EMSL	3/26/07	< 0.00083	No	No	
ASBESTOS-ST5-3/25/07	030709204-0003	Firehouse #10 (roof level)	3/25/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST10-3/25/07	030709204-0004	North Side Sidewalk Bridge	3/25/07	1	2.970	Asbestos	PCME	EMSL	3/26/07	< 0.00083	No	No	
ASBESTOS-ST11-3/25/07	030709204-0005	90 Trinity Place (roof level)	3/25/07	1	2.900	Asbestos	PCME	EMSL	3/26/07	< 0.00085	No	No	
ASBESTOS-ST12-3/25/07	030709204-0006	110 Greenwich Street (roof level)	3/25/07	1	2.970	Asbestos	PCME	EMSL	3/26/07	< 0.00083	No	No	
ASBESTOS-ST13-3/25/07	030709204-0007	Marriott Hotel, 38th Floor (roof level)	3/25/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST14-3/25/07	030709204-0008	West Face - South end at corner (scaffolding level)	3/25/07	1	2.990	Asbestos	PCME	EMSL	3/26/07	< 0.00083	No	No	
ASBESTOS-ST15-3/25/07	030709204-0009	South Face - East end at corner (scaffolding level)	3/25/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST16-3/25/07	030709204-0010	East Face - North end at corner (scaffolding level)	3/25/07	1	3.020	Asbestos	PCME	EMSL	3/26/07	< 0.00082	No	No	
ASBESTOS-ST17-3/25/07	030709204-0011	North Face - West end at corner (scaffolding level)	3/25/07	1	2.970	Asbestos	PCME	EMSL	3/26/07	< 0.00083	No	No	

Note:

1. The asbestos sample at Station 4 (Northwest Area [street-level]) on March 25, 2007 was not available for analysis on account of power failure.