

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-3/24/06	030606264-0001	Southwest Area (sidewalk bridge level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST2-3/24/06	030606264-0002	Southeast Area (sidewalk bridge level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST4-3/24/06	030606264-0003	Northwest Area (street-level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST5-3/24/06	030606264-0004	Firehouse #10 (roof level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST10-3/24/06	030606264-0005	North Side Sidewalk Bridge	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST11-3/24/06	030606264-0006	90 Trinity Place (roof level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST12-3/24/06	030606264-0007	110 Greenwich Street (roof level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST13-3/24/06	030606264-0008	Marriott Hotel, 38th Floor (roof level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST14-3/24/06	030606264-0009	West Face - South end at corner (scaffolding level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST15-3/24/06	030606264-0010	South Face - East end at corner (scaffolding level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST16-3/24/06	030606264-0011	East Face - North end at corner (scaffolding level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST17-3/24/06	030606264-0012	North Face - West end at corner (scaffolding level)	3/24/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST1-3/25/06	030609265-0001	Southwest Area (sidewalk bridge level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST2-3/25/06	030609265-0002	Southeast Area (sidewalk bridge level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST4-3/25/06	030609265-0003	Northwest Area (street-level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST5-3/25/06	030609265-0004	Firehouse #10 (roof level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST10-3/25/06	030609265-0005	North Side Sidewalk Bridge	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST11-3/25/06	030609265-0006	90 Trinity Place (roof level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST12-3/25/06	030609265-0007	110 Greenwich Street (roof level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST13-3/25/06	030609265-0008	Marriott Hotel, 38th Floor (roof level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST14-3/25/06	030609265-0009	West Face - South end at corner (scaffolding level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST15-3/25/06	030609265-0010	South Face - East end at corner (scaffolding level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST16-3/25/06	030609265-0011	East Face - North end at corner (scaffolding level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST17-3/25/06	030609265-0012	North Face - West end at corner (scaffolding level)	3/25/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST1-3/26/06	030609266-0001	Southwest Area (sidewalk bridge level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST2-3/26/06	030609266-0002	Southeast Area (sidewalk bridge level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST4-3/26/06	030609266-0003	Northwest Area (street-level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST5-3/26/06	030609266-0004	Firehouse #10 (roof level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST10-3/26/06	030609266-0005	North Side Sidewalk Bridge	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST11-3/26/06	030609266-0006	90 Trinity Place (roof level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST12-3/26/06	030609266-0007	110 Greenwich Street (roof level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST13-3/26/06	030609266-0008	Marriott Hotel, 38th Floor (roof level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST14-3/26/06	030609266-0009	West Face - South end at corner (scaffolding level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST15-3/26/06	030609266-0010	South Face - East end at corner (scaffolding level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST16-3/26/06	030609266-0011	East Face - North end at corner (scaffolding level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	
ASBESTOS-ST17-3/26/06	030609266-0012	North Face - West end at corner (scaffolding level)	3/26/06	1	3.000	Asbestos	PCME	EMSL	3/27/06	< 0.00082	No	No	