

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-3/27/08	030808715-0001	Southwest Area (sidewalk bridge level)	3/27/08	1	3.040	Asbestos	PCME	EMSL	3/28/08	< 0.00081	No	No	
ASBESTOS-ST2-3/27/08	030808715-0002	Southeast Area (sidewalk bridge level)	3/27/08	1	3.060	Asbestos	PCME	EMSL	3/28/08	< 0.00081	No	No	
ASBESTOS-ST4-3/27/08	030808715-0003	Northwest Area (street-level)	3/27/08	1	3.080	Asbestos	PCME	EMSL	3/28/08	< 0.00080	No	No	
ASBESTOS-ST5-3/27/08	030808715-0004	Firehouse #10 (roof level)	3/27/08	1	3.110	Asbestos	PCME	EMSL	3/28/08	< 0.00079	No	No	
ASBESTOS-ST10-3/27/08	030808715-0005	North Side Sidewalk Bridge	3/27/08	1	2.950	Asbestos	PCME	EMSL	3/28/08	< 0.00084	No	No	
ASBESTOS-ST11-3/27/08	030808715-0006	90 Trinity Place (roof level)	3/27/08	1	3.060	Asbestos	PCME	EMSL	3/28/08	< 0.00081	No	No	
ASBESTOS-ST12-3/27/08	030808715-0007	110 Greenwich Street (roof level)	3/27/08	1	3.000	Asbestos	PCME	EMSL	3/28/08	< 0.00082	No	No	
ASBESTOS-ST13-3/27/08	030808715-0008	Marriott Hotel, 38th Floor (roof level)	3/27/08	1	3.040	Asbestos	PCME	EMSL	3/28/08	< 0.00081	No	No	
ASBESTOS-ST14-3/27/08	030808715-0009	West Face - South end at corner (scaffolding level)	3/27/08	1	3.080	Asbestos	PCME	EMSL	3/28/08	< 0.00080	No	No	
ASBESTOS-ST15-3/27/08	030808715-0010	South Face - East end at corner (scaffolding level)	3/27/08	1	3.020	Asbestos	PCME	EMSL	3/28/08	< 0.00082	No	No	
ASBESTOS-ST16-3/27/08	030808715-0011	East Face - North end at corner (scaffolding level)	3/27/08	1	3.040	Asbestos	PCME	EMSL	3/28/08	< 0.00081	No	No	
ASBESTOS-ST17-3/27/08	030808715-0012	North Face - West end at corner (scaffolding level)	3/27/08	1	3.000	Asbestos	PCME	EMSL	3/28/08	< 0.00082	No	No	
ASBESTOS-ST1-3/28/08	030808831-0001	Southwest Area (sidewalk bridge level)	3/28/08	1	3.060	Asbestos	PCME	EMSL	3/29/08	< 0.00081	No	No	
ASBESTOS-ST2-3/28/08	030808831-0002	Southeast Area (sidewalk bridge level)	3/28/08	1	3.010	Asbestos	PCME	EMSL	3/29/08	< 0.00082	No	No	
ASBESTOS-ST4-3/28/08	030808831-0003	Northwest Area (street-level)	3/28/08	1	2.970	Asbestos	PCME	EMSL	3/29/08	< 0.00083	No	No	
ASBESTOS-ST5-3/28/08	030808831-0004	Firehouse #10 (roof level)	3/28/08	1	3.090	Asbestos	PCME	EMSL	3/29/08	< 0.00080	No	No	
ASBESTOS-ST10-3/28/08	030808831-0005	North Side Sidewalk Bridge	3/28/08	1	3.060	Asbestos	PCME	EMSL	3/29/08	< 0.00081	No	No	
ASBESTOS-ST100-3/28/08	030808831-0013	Station 10 Field Duplicate	3/28/08	1	3.010	Asbestos	PCME	EMSL	3/29/08	< 0.00082	No	No	
ASBESTOS-ST11-3/28/08	030808831-0006	90 Trinity Place (roof level)	3/28/08	1	3.030	Asbestos	PCME	EMSL	3/29/08	< 0.00081	No	No	
ASBESTOS-ST12-3/28/08	030808831-0007	110 Greenwich Street (roof level)	3/28/08	1	3.050	Asbestos	PCME	EMSL	3/29/08	< 0.00081	No	No	
ASBESTOS-ST13-3/28/08	030808831-0008	Marriott Hotel, 38th Floor (roof level)	3/28/08	1	3.000	Asbestos	PCME	EMSL	3/29/08	< 0.00082	No	No	
ASBESTOS-ST14-3/28/08	030808831-0009	West Face - South end at corner (scaffolding level)	3/28/08	1	2.980	Asbestos	PCME	EMSL	3/29/08	< 0.00083	No	No	
ASBESTOS-ST15-3/28/08	030808831-0010	South Face - East end at corner (scaffolding level)	3/28/08	1	3.020	Asbestos	PCME	EMSL	3/29/08	< 0.00082	No	No	
ASBESTOS-ST16-3/28/08	030808831-0011	East Face - North end at corner (scaffolding level)	3/28/08	1	3.080	Asbestos	PCME	EMSL	3/29/08	< 0.00080	No	No	
ASBESTOS-ST17-3/28/08	030808831-0012	North Face - West end at corner (scaffolding level)	3/28/08	1	2.940	Asbestos	PCME	EMSL	3/29/08	< 0.00084	No	No	
ASBESTOS-ST1-3/29/08	030809050-0001	Southwest Area (sidewalk bridge level)	3/29/08	1	3.020	Asbestos	PCME	EMSL	3/31/08	< 0.00082	No	No	
ASBESTOS-ST2-3/29/08	030809050-0002	Southeast Area (sidewalk bridge level)	3/29/08	1	3.070	Asbestos	PCME	EMSL	3/31/08	< 0.00080	No	No	
ASBESTOS-ST4-3/29/08	030809050-0003	Northwest Area (street-level)	3/29/08	1	2.970	Asbestos	PCME	EMSL	3/31/08	< 0.00083	No	No	
ASBESTOS-ST5-3/29/08	030809050-0004	Firehouse #10 (roof level)	3/29/08	1	3.060	Asbestos	PCME	EMSL	3/31/08	< 0.00081	No	No	
ASBESTOS-ST10-3/29/08	030809050-0005	North Side Sidewalk Bridge	3/29/08	1	3.110	Asbestos	PCME	EMSL	3/31/08	< 0.00087	No	No	
ASBESTOS-ST11-3/29/08	030809050-0006	90 Trinity Place (roof level)	3/29/08	1	3.020	Asbestos	PCME	EMSL	3/31/08	< 0.00082	No	No	
ASBESTOS-ST12-3/29/08	030809050-0007	110 Greenwich Street (roof level)	3/29/08	1	3.020	Asbestos	PCME	EMSL	3/31/08	< 0.00082	No	No	
ASBESTOS-ST13-3/29/08	030809050-0008	Marriott Hotel, 38th Floor (roof level)	3/29/08	1	3.000	Asbestos	PCME	EMSL	3/31/08	< 0.00082	No	No	
ASBESTOS-ST14-3/29/08	030809050-0009	West Face - South end at corner (scaffolding level)	3/29/08	1	3.040	Asbestos	PCME	EMSL	3/31/08	< 0.00081	No	No	
ASBESTOS-ST15-3/29/08	030809050-0010	South Face - East end at corner (scaffolding level)	3/29/08	1	3.000	Asbestos	PCME	EMSL	3/31/08	< 0.00082	No	No	
ASBESTOS-ST16-3/29/08	030809050-0011	East Face - North end at corner (scaffolding level)	3/29/08	1	3.150	Asbestos	PCME	EMSL	3/31/08	< 0.00085	No	No	
ASBESTOS-ST17-3/29/08	030809050-0012	North Face - West end at corner (scaffolding level)	3/29/08	1	3.040	Asbestos	PCME	EMSL	3/31/08	< 0.00081	No	No	
ASBESTOS-ST1-3/30/08	030809052-0001	Southwest Area (sidewalk bridge level)	3/30/08	1	2.970	Asbestos	PCME	EMSL	3/31/08	< 0.00083	No	No	
ASBESTOS-ST2-3/30/08	030809052-0002	Southeast Area (sidewalk bridge level)	3/30/08	1	2.990	Asbestos	PCME	EMSL	3/31/08	< 0.00083	No	No	
ASBESTOS-ST4-3/30/08	030809052-0003	Northwest Area (street-level)	3/30/08	1	3.020	Asbestos	PCME	EMSL	3/31/08	< 0.00082	No	No	
ASBESTOS-ST5-3/30/08	030809052-0004	Firehouse #10 (roof level)	3/30/08	1	3.090	Asbestos	PCME	EMSL	3/31/08	< 0.00080	No	No	
ASBESTOS-ST10-3/30/08	030809052-0005	North Side Sidewalk Bridge	3/30/08	1	3.060	Asbestos	PCME	EMSL	3/31/08	< 0.00088	No	No	
ASBESTOS-ST11-3/30/08	030809052-0006	90 Trinity Place (roof level)	3/30/08	1	2.980	Asbestos	PCME	EMSL	3/31/08	< 0.00083	No	No	
ASBESTOS-ST12-3/30/08	030809052-0007	110 Greenwich Street (roof level)	3/30/08	1	3.060	Asbestos	PCME	EMSL	3/31/08	< 0.00081	No	No	
ASBESTOS-ST13-3/30/08	030809052-0008	Marriott Hotel, 38th Floor (roof level)	3/30/08	1	3.060	Asbestos	PCME	EMSL	3/31/08	< 0.00081	No	No	
ASBESTOS-ST14-3/30/08	030809052-0009	West Face - South end at corner (scaffolding level)	3/30/08	1	2.980	Asbestos	PCME	EMSL	3/31/08	< 0.00082	No	No	
ASBESTOS-ST15-3/30/08	030809052-0010	South Face - East end at corner (scaffolding level)	3/30/08	1	3.000	Asbestos	PCME	EMSL	3/31/08	< 0.00082	No	No	
ASBESTOS-ST16-3/30/08	030809052-0011	East Face - North end at corner (scaffolding level)	3/30/08	1	3.060	Asbestos	PCME	EMSL	3/31/08	< 0.00088	No	No	
ASBESTOS-ST17-3/30/08	030809052-0012	North Face - West end at corner (scaffolding level)	3/30/08	1	3.110	Asbestos	PCME	EMSL	3/31/08	< 0.00079	No	No	