

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-4/7/09	030908984-0001	Southwest Area (sidewalk bridge level)	4/7/09	1	3.080	Asbestos	PCME	EMSL	4/8/09	< 0.00080	No	No	
ASBESTOS-ST2-4/7/09	030908984-0002	Southeast Area (sidewalk bridge level)	4/7/09	1	3.050	Asbestos	PCME	EMSL	4/8/09	< 0.00081	No	No	
ASBESTOS-ST4-4/7/09	030908984-0003	Northwest Area (street-level)	4/7/09	1	3.000	Asbestos	PCME	EMSL	4/8/09	< 0.00082	No	No	
ASBESTOS-ST5-4/7/09	030908984-0004	Firehouse #10 (roof level)	4/7/09	1	3.020	Asbestos	PCME	EMSL	4/8/09	< 0.00082	No	No	
ASBESTOS-ST10-4/7/09	030908984-0005	North Side Sidewalk Bridge	4/7/09	1	3.040	Asbestos	PCME	EMSL	4/8/09	< 0.00081	No	No	
ASBESTOS-ST11-4/7/09	030908984-0006	90 Trinity Place (roof level)	4/7/09	1	3.210	Asbestos	PCME	EMSL	4/8/09	< 0.00084	No	No	
ASBESTOS-ST12-4/7/09	030908984-0007	110 Greenwich Street (roof level)	4/7/09	1	3.160	Asbestos	PCME	EMSL	4/8/09	< 0.00078	No	No	
ASBESTOS-ST13-4/7/09	030908984-0008	Marriott Hotel, 38th Floor (roof level)	4/7/09	1	2.990	Asbestos	PCME	EMSL	4/8/09	< 0.00083	No	No	
ASBESTOS-ST14-4/7/09	030908984-0009	West Face - South end at corner (scaffolding level)	4/7/09	1	2.920	Asbestos	PCME	EMSL	4/8/09	< 0.00085	No	No	
ASBESTOS-ST15-4/7/09	030908984-0010	South Face - East end at corner (scaffolding level)	4/7/09	1	3.170	Asbestos	PCME	EMSL	4/8/09	< 0.00078	No	No	
ASBESTOS-ST16-4/7/09	030908984-0011	East Face - North end at corner (scaffolding level)	4/7/09	1	3.160	Asbestos	PCME	EMSL	4/8/09	< 0.00078	No	No	
ASBESTOS-ST17-4/7/09	030908984-0012	North Face - West end at corner (scaffolding level)	4/7/09	1	2.950	Asbestos	PCME	EMSL	4/8/09	< 0.00084	No	No	
ASBESTOS-ST1-4/8/09	030909078-0001	Southwest Area (sidewalk bridge level)	4/8/09	1	3.010	Asbestos	PCME	EMSL	4/9/09	< 0.00082	No	No	
ASBESTOS-ST2-4/8/09	030909078-0002	Southeast Area (sidewalk bridge level)	4/8/09	1	3.030	Asbestos	PCME	EMSL	4/9/09	< 0.00081	No	No	
ASBESTOS-ST4-4/8/09	030909078-0003	Northwest Area (street-level)	4/8/09	1	3.060	Asbestos	PCME	EMSL	4/9/09	< 0.00081	No	No	
ASBESTOS-ST5-4/8/09	030909078-0004	Firehouse #10 (roof level)	4/8/09	1	3.070	Asbestos	PCME	EMSL	4/9/09	< 0.00080	No	No	
ASBESTOS-ST10-4/8/09	030909078-0005	North Side Sidewalk Bridge	4/8/09	1	3.110	Asbestos	PCME	EMSL	4/9/09	< 0.00079	No	No	
ASBESTOS-ST100-4/8/09	030909078-0013	Station 10 Field Duplicate	4/8/09	1	3.080	Asbestos	PCME	EMSL	4/9/09	< 0.00080	No	No	
ASBESTOS-ST11-4/8/09	030909078-0006	90 Trinity Place (roof level)	4/8/09	1	3.080	Asbestos	PCME	EMSL	4/9/09	< 0.00080	No	No	
ASBESTOS-ST12-4/8/09	030909078-0007	110 Greenwich Street (roof level)	4/8/09	1	3.070	Asbestos	PCME	EMSL	4/9/09	< 0.00080	No	No	
ASBESTOS-ST13-4/8/09	030909078-0008	Marriott Hotel, 38th Floor (roof level)	4/8/09	1	3.210	Asbestos	PCME	EMSL	4/9/09	< 0.00077	No	No	
ASBESTOS-ST14-4/8/09	030909078-0009	West Face - South end at corner (scaffolding level)	4/8/09	1	3.140	Asbestos	PCME	EMSL	4/9/09	< 0.00079	No	No	
ASBESTOS-ST15-4/8/09	030909078-0010	South Face - East end at corner (scaffolding level)	4/8/09	1	3.160	Asbestos	PCME	EMSL	4/9/09	< 0.00078	No	No	
ASBESTOS-ST16-4/8/09	030909078-0011	East Face - North end at corner (scaffolding level)	4/8/09	1	3.020	Asbestos	PCME	EMSL	4/9/09	< 0.00082	No	No	
ASBESTOS-ST17-4/8/09	030909078-0012	North Face - West end at corner (scaffolding level)	4/8/09	1	3.130	Asbestos	PCME	EMSL	4/9/09	< 0.00079	No	No	
ASBESTOS-ST1-4/9/09	030909173-0001	Southwest Area (sidewalk bridge level)	4/9/09	1	2.860	Asbestos	PCME	EMSL	4/10/09	< 0.00086	No	No	
ASBESTOS-ST2-4/9/09	030909173-0002	Southeast Area (sidewalk bridge level)	4/9/09	1	2.950	Asbestos	PCME	EMSL	4/10/09	< 0.00084	No	No	
ASBESTOS-ST4-4/9/09	030909173-0003	Northwest Area (street-level)	4/9/09	1	2.950	Asbestos	PCME	EMSL	4/10/09	< 0.00084	No	No	
ASBESTOS-ST5-4/9/09	030909173-0004	Firehouse #10 (roof level)	4/9/09	1	3.120	Asbestos	PCME	EMSL	4/10/09	< 0.00079	No	No	
ASBESTOS-ST10-4/9/09	030909173-0005	North Side Sidewalk Bridge	4/9/09	1	2.990	Asbestos	PCME	EMSL	4/10/09	< 0.00083	No	No	
ASBESTOS-ST11-4/9/09	030909173-0006	90 Trinity Place (roof level)	4/9/09	1	3.150	Asbestos	PCME	EMSL	4/10/09	< 0.00078	No	No	
ASBESTOS-ST12-4/9/09	030909173-0007	110 Greenwich Street (roof level)	4/9/09	1	3.120	Asbestos	PCME	EMSL	4/10/09	< 0.00079	No	No	
ASBESTOS-ST13-4/9/09	030909173-0008	Marriott Hotel, 38th Floor (roof level)	4/9/09	1	3.160	Asbestos	PCME	EMSL	4/10/09	< 0.00078	No	No	
ASBESTOS-ST14-4/9/09	030909173-0009	West Face - South end at corner (scaffolding level)	4/9/09	1	2.990	Asbestos	PCME	EMSL	4/10/09	< 0.00083	No	No	
ASBESTOS-ST15-4/9/09	030909173-0010	South Face - East end at corner (scaffolding level)	4/9/09	1	2.930	Asbestos	PCME	EMSL	4/10/09	< 0.00084	No	No	
ASBESTOS-ST16-4/9/09	030909173-0011	East Face - North end at corner (scaffolding level)	4/9/09	1	3.060	Asbestos	PCME	EMSL	4/10/09	< 0.00081	No	No	
ASBESTOS-ST17-4/9/09	030909173-0012	North Face - West end at corner (scaffolding level)	4/9/09	1	2.960	Asbestos	PCME	EMSL	4/10/09	< 0.00083	No	No	