

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-4/12/06	030611200-0001	Southwest Area (sidewalk bridge level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST2-4/12/06	030611200-0002	Southeast Area (sidewalk bridge level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST4-4/12/06	030611200-0003	Northwest Area (street-level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST5-4/12/06	030611200-0004	Firehouse #10 (roof level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST10-4/12/06	030611200-0005	North Side Sidewalk Bridge	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST100-4/12/16	030611200-0013	Station 10 Field Duplicate	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST11-4/12/06	030611200-0006	90 Trinity Place (roof level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST12-4/12/06	030611200-0007	110 Greenwich Street (roof level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST13-4/12/06	030611200-0008	Marriott Hotel, 38th Floor (roof level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST14-4/12/06	030611200-0009	West Face - South end at corner (scaffolding level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST15-4/12/06	030611200-0010	South Face - East end at corner (scaffolding level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST16-4/12/06	030611200-0011	East Face - North end at corner (scaffolding level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST17-4/12/06	030611200-0012	North Face - West end at corner (scaffolding level)	4/12/06	1	3.000	Asbestos	PCME	EMSL	4/13/06	< 0.00082	No	No	
ASBESTOS-ST1-4/13/06	030611361-0001	Southwest Area (sidewalk bridge level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST2-4/13/06	030611361-0002	Southeast Area (sidewalk bridge level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST4-4/13/06	030611361-0003	Northwest Area (street-level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST5-4/13/06	030611361-0004	Firehouse #10 (roof level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST10-4/13/06	030611361-0005	North Side Sidewalk Bridge	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST11-4/13/06	030611361-0006	90 Trinity Place (roof level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST12-4/13/06	030611361-0007	110 Greenwich Street (roof level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST13-4/13/06	030611361-0008	Marriott Hotel, 38th Floor (roof level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST14-4/13/06	030611361-0009	West Face - South end at corner (scaffolding level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST15-4/13/06	030611361-0010	South Face - East end at corner (scaffolding level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST16-4/13/06	030611361-0011	East Face - North end at corner (scaffolding level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	
ASBESTOS-ST17-4/13/06	030611361-0012	North Face - West end at corner (scaffolding level)	4/13/06	1	3.000	Asbestos	PCME	EMSL	4/14/06	< 0.00082	No	No	