

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments | |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|-----------------------------------|--|----------|--|
| | | | | | | | | | | 0.0009 | | | | |
| | | | | | | | | | | NA | | | | |
| Target Air Quality Levels | | | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | | | |
| ASBESTOS-ST1-4/14/06 | 030611580-0001 | Southwest Area (sidewalk bridge level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST2-4/14/06 | 030611580-0002 | Southeast Area (sidewalk bridge level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST4-4/14/06 | 030611580-0003 | Northwest Area (street-level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST5-4/14/06 | 030611580-0004 | Firehouse #10 (roof level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST10-4/14/06 | 030611580-0005 | North Side Sidewalk Bridge | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST11-4/14/06 | 030611580-0006 | 90 Trinity Place (roof level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST12-4/14/06 | 030611580-0007 | 110 Greenwich Street (roof level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST13-4/14/06 | 030611580-0008 | Marriott Hotel, 38th Floor (roof level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST14-4/14/06 | 030611580-0009 | West Face - South end at corner (scaffolding level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST15-4/14/06 | 030611580-0010 | South Face - East end at corner (scaffolding level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST17-4/14/06 | 030611580-0012 | North Face - West end at corner (scaffolding level) | 4/14/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST1-4/15/06 | 030611514-0001 | Southwest Area (sidewalk bridge level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST2-4/15/06 | 030611514-0002 | Southeast Area (sidewalk bridge level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST4-4/15/06 | 030611514-0003 | Northwest Area (street-level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST5-4/15/06 | 030611514-0004 | Firehouse #10 (roof level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST10-4/15/06 | 030611514-0005 | North Side Sidewalk Bridge | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST11-4/15/06 | 030611514-0006 | 90 Trinity Place (roof level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST12-4/15/06 | 030611514-0007 | 110 Greenwich Street (roof level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST13-4/15/06 | 030611514-0008 | Marriott Hotel, 38th Floor (roof level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST14-4/15/06 | 030611514-0009 | West Face - South end at corner (scaffolding level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST15-4/15/06 | 030611514-0010 | South Face - East end at corner (scaffolding level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST16-4/15/06 | 030611514-0011 | East Face - North end at corner (scaffolding level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST17-4/15/06 | 030611514-0012 | North Face - West end at corner (scaffolding level) | 4/15/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST1-4/16/06 | 030611515-0001 | Southwest Area (sidewalk bridge level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST2-4/16/06 | 030611515-0002 | Southeast Area (sidewalk bridge level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST4-4/16/06 | 030611515-0003 | Northwest Area (street-level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST5-4/16/06 | 030611515-0004 | Firehouse #10 (roof level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST10-4/16/06 | 030611515-0005 | North Side Sidewalk Bridge | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST11-4/16/06 | 030611515-0006 | 90 Trinity Place (roof level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST12-4/16/06 | 030611515-0007 | 110 Greenwich Street (roof level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST13-4/16/06 | 030611515-0008 | Marriott Hotel, 38th Floor (roof level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST14-4/16/06 | 030611515-0009 | West Face - South end at corner (scaffolding level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST15-4/16/06 | 030611515-0010 | South Face - East end at corner (scaffolding level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST17-4/16/06 | 030611515-0012 | North Face - West end at corner (scaffolding level) | 4/16/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/17/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST1-4/17/06 | 030611658-0001 | Southwest Area (sidewalk bridge level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST2-4/17/06 | 030611658-0002 | Southeast Area (sidewalk bridge level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST4-4/17/06 | 030611658-0003 | Northwest Area (street-level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST5-4/17/06 | 030611658-0004 | Firehouse #10 (roof level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST10-4/17/06 | 030611658-0005 | North Side Sidewalk Bridge | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST11-4/17/06 | 030611658-0006 | 90 Trinity Place (roof level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST12-4/17/06 | 030611658-0007 | 110 Greenwich Street (roof level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST13-4/17/06 | 030611658-0008 | Marriott Hotel, 38th Floor (roof level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST14-4/17/06 | 030611658-0009 | West Face - South end at corner (scaffolding level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST15-4/17/06 | 030611658-0010 | South Face - East end at corner (scaffolding level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST16-4/17/06 | 030611658-0011 | East Face - North end at corner (scaffolding level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |
| ASBESTOS-ST17-4/17/06 | 030611658-0012 | North Face - West end at corner (scaffolding level) | 4/17/06 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/18/06 | < 0.00082 | No | No | | |

Note:

1. Asbestos samples at Station 16 (East Face - North end at corner [scaffolding level]) on April 14 and 16, 2006 were not available for analysis on account of filter damage.