

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-4/15/09	030909664-0001	Southwest Area (sidewalk bridge level)	4/15/09	1	3.020	Asbestos	PCME	EMSL	4/16/09	< 0.00082	No	No	
ASBESTOS-ST2-4/15/09	030909664-0002	Southeast Area (sidewalk bridge level)	4/15/09	1	3.070	Asbestos	PCME	EMSL	4/16/09	< 0.00080	No	No	
ASBESTOS-ST4-4/15/09	030909664-0003	Northwest Area (street-level)	4/15/09	1	3.050	Asbestos	PCME	EMSL	4/16/09	< 0.00081	No	No	
ASBESTOS-ST5-4/15/09	030909664-0004	Firehouse #10 (roof level)	4/15/09	1	3.180	Asbestos	PCME	EMSL	4/16/09	< 0.00078	No	No	
ASBESTOS-ST10-4/15/09	030909664-0005	North Side Sidewalk Bridge	4/15/09	1	3.080	Asbestos	PCME	EMSL	4/16/09	< 0.00080	No	No	
ASBESTOS-ST11-4/15/09	030909664-0006	90 Trinity Place (roof level)	4/15/09	1	3.260	Asbestos	PCME	EMSL	4/16/09	< 0.00076	No	No	
ASBESTOS-ST12-4/15/09	030909664-0007	110 Greenwich Street (roof level)	4/15/09	1	3.250	Asbestos	PCME	EMSL	4/16/09	< 0.00076	No	No	
ASBESTOS-ST13-4/15/09	030909664-0008	Marriott Hotel, 38th Floor (roof level)	4/15/09	1	3.130	Asbestos	PCME	EMSL	4/16/09	< 0.00079	No	No	
ASBESTOS-ST1-4/16/09	030909842-0001	Southwest Area (sidewalk bridge level)	4/16/09	1	3.260	Asbestos	PCME	EMSL	4/17/09	< 0.00083	No	No	
ASBESTOS-ST2-4/16/09	030909842-0002	Southeast Area (sidewalk bridge level)	4/16/09	1	3.180	Asbestos	PCME	EMSL	4/17/09	< 0.00085	No	No	
ASBESTOS-ST4-4/16/09	030909842-0003	Northwest Area (street-level)	4/16/09	1	3.090	Asbestos	PCME	EMSL	4/17/09	< 0.00087	No	No	
ASBESTOS-ST5-4/16/09	030909842-0004	Firehouse #10 (roof level)	4/16/09	1	3.140	Asbestos	PCME	EMSL	4/17/09	< 0.00086	No	No	
ASBESTOS-ST10-4/16/09	030909842-0005	North Side Sidewalk Bridge	4/16/09	1	3.080	Asbestos	PCME	EMSL	4/17/09	< 0.00087	No	No	
ASBESTOS-ST100-4/16/09	030909842-0013	Station 10 Field Duplicate	4/16/09	1	3.140	Asbestos	PCME	EMSL	4/17/09	< 0.00086	No	No	
ASBESTOS-ST11-4/16/09	030909842-0006	90 Trinity Place (roof level)	4/16/09	1	3.050	Asbestos	PCME	EMSL	4/17/09	< 0.00081	No	No	
ASBESTOS-ST12-4/16/09	030909842-0007	110 Greenwich Street (roof level)	4/16/09	1	2.950	Asbestos	PCME	EMSL	4/17/09	< 0.00084	No	No	
ASBESTOS-ST13-4/16/09	030909842-0008	Marriott Hotel, 38th Floor (roof level)	4/16/09	1	3.070	Asbestos	PCME	EMSL	4/17/09	< 0.00088	No	No	
ASBESTOS-ST14-4/16/09	030909842-0009	West Face - South end at corner (scaffolding level)	4/16/09	1	3.040	Asbestos	PCME	EMSL	4/17/09	< 0.00081	No	No	
ASBESTOS-ST15-4/16/09	030909842-0010	South Face - East end at corner (scaffolding level)	4/16/09	1	3.010	Asbestos	PCME	EMSL	4/17/09	< 0.00082	No	No	
ASBESTOS-ST16-4/16/09	030909842-0011	East Face - North end at corner (scaffolding level)	4/16/09	1	3.060	Asbestos	PCME	EMSL	4/17/09	< 0.00081	No	No	
ASBESTOS-ST17-4/16/09	030909842-0012	North Face - West end at corner (scaffolding level)	4/16/09	1	2.980	Asbestos	PCME	EMSL	4/17/09	< 0.00083	No	No	
ASBESTOS-ST1-4/17/09	030909916-0001	Southwest Area (sidewalk bridge level)	4/17/09	1	3.020	Asbestos	PCME	EMSL	4/18/09	< 0.00082	No	No	
ASBESTOS-ST2-4/17/09	030909916-0002	Southeast Area (sidewalk bridge level)	4/17/09	1	2.950	Asbestos	PCME	EMSL	4/18/09	< 0.00084	No	No	
ASBESTOS-ST4-4/17/09	030909916-0003	Northwest Area (street-level)	4/17/09	1	3.000	Asbestos	PCME	EMSL	4/18/09	< 0.00082	No	No	
ASBESTOS-ST5-4/17/09	030909916-0004	Firehouse #10 (roof level)	4/17/09	1	3.080	Asbestos	PCME	EMSL	4/18/09	< 0.00087	No	No	
ASBESTOS-ST10-4/17/09	030909916-0005	North Side Sidewalk Bridge	4/17/09	1	3.060	Asbestos	PCME	EMSL	4/18/09	< 0.00081	No	No	
ASBESTOS-ST11-4/17/09	030909916-0006	90 Trinity Place (roof level)	4/17/09	1	2.940	Asbestos	PCME	EMSL	4/18/09	< 0.00084	No	No	
ASBESTOS-ST12-4/17/09	030909916-0007	110 Greenwich Street (roof level)	4/17/09	1	3.010	Asbestos	PCME	EMSL	4/18/09	< 0.00082	No	No	
ASBESTOS-ST13-4/17/09	030909916-0008	Marriott Hotel, 38th Floor (roof level)	4/17/09	1	3.030	Asbestos	PCME	EMSL	4/18/09	< 0.00081	No	No	
ASBESTOS-ST14-4/17/09	030909916-0009	West Face - South end at corner (scaffolding level)	4/17/09	1	2.980	Asbestos	PCME	EMSL	4/18/09	< 0.00083	No	No	
ASBESTOS-ST15-4/17/09	030909916-0010	South Face - East end at corner (scaffolding level)	4/17/09	1	2.940	Asbestos	PCME	EMSL	4/18/09	< 0.00084	No	No	
ASBESTOS-ST16-4/17/09	030909916-0011	East Face - North end at corner (scaffolding level)	4/17/09	1	2.920	Asbestos	PCME	EMSL	4/18/09	< 0.00085	No	No	
ASBESTOS-ST17-4/17/09	030909916-0012	North Face - West end at corner (scaffolding level)	4/17/09	1	2.880	Asbestos	PCME	EMSL	4/18/09	< 0.00086	No	No	

Note:

- The asbestos samples from Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]) on April 15, 2009 were composited with samples from April 14, 2009. See sample results from April 14, 2009.