

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-4/21/06	030612302-0001	Southwest Area (sidewalk bridge level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST2-4/21/06	030612302-0002	Southeast Area (sidewalk bridge level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST4-4/21/06	030612302-0003	Northwest Area (street-level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST5-4/21/06	030612302-0004	Firehouse #10 (roof level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST10-4/21/06	030612302-0005	North Side Sidewalk Bridge	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST11-4/21/06	030612302-0006	90 Trinity Place (roof level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST12-4/21/06	030612302-0007	110 Greenwich Street (roof level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST13-4/21/06	030612302-0008	Marriott Hotel, 38th Floor (roof level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST14-4/21/06	030612302-0009	West Face - South end at corner (scaffolding level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST15-4/21/06	030612302-0010	South Face - East end at corner (scaffolding level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST16-4/21/06	030612302-0011	East Face - North end at corner (scaffolding level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST17-4/21/06	030612302-0012	North Face - West end at corner (scaffolding level)	4/21/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST1-4/22/06	030612303-0001	Southwest Area (sidewalk bridge level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST2-4/22/06	030612303-0002	Southeast Area (sidewalk bridge level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST4-4/22/06	030612303-0003	Northwest Area (street-level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST5-4/22/06	030612303-0004	Firehouse #10 (roof level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST10-4/22/06	030612303-0005	North Side Sidewalk Bridge	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST11-4/22/06	030612303-0006	90 Trinity Place (roof level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST12-4/22/06	030612303-0007	110 Greenwich Street (roof level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST13-4/22/06	030612303-0008	Marriott Hotel, 38th Floor (roof level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST14-4/22/06	030612303-0009	West Face - South end at corner (scaffolding level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST15-4/22/06	030612303-0010	South Face - East end at corner (scaffolding level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST17-4/22/06	030612303-0012	North Face - West end at corner (scaffolding level)	4/22/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST2-4/23/06	030612304-0002	Southeast Area (sidewalk bridge level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST4-4/23/06	030612304-0003	Northwest Area (street-level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST5-4/23/06	030612304-0004	Firehouse #10 (roof level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST10-4/23/06	030612304-0005	North Side Sidewalk Bridge	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST11-4/23/06	030612304-0006	90 Trinity Place (roof level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST12-4/23/06	030612304-0007	110 Greenwich Street (roof level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST13-4/23/06	030612304-0008	Marriott Hotel, 38th Floor (roof level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST14-4/23/06	030612304-0009	West Face - South end at corner (scaffolding level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST15-4/23/06	030612304-0010	South Face - East end at corner (scaffolding level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST16-4/23/06	030612304-0011	East Face - North end at corner (scaffolding level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST17-4/23/06	030612304-0012	North Face - West end at corner (scaffolding level)	4/23/06	1	3.000	Asbestos	PCME	EMSL	4/24/06	< 0.00082	No	No	
ASBESTOS-ST1-4/24/06	030612430-0001	Southwest Area (sidewalk bridge level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST2-4/24/06	030612430-0002	Southeast Area (sidewalk bridge level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST4-4/24/06	030612430-0003	Northwest Area (street-level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST5-4/24/06	030612430-0004	Firehouse #10 (roof level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST10-4/24/06	030612430-0005	North Side Sidewalk Bridge	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST11-4/24/06	030612430-0006	90 Trinity Place (roof level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST12-4/24/06	030612430-0007	110 Greenwich Street (roof level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST13-4/24/06	030612430-0008	Marriott Hotel, 38th Floor (roof level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST14-4/24/06	030612430-0009	West Face - South end at corner (scaffolding level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST15-4/24/06	030612430-0010	South Face - East end at corner (scaffolding level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	
ASBESTOS-ST17-4/24/06	030612430-0012	North Face - West end at corner (scaffolding level)	4/24/06	1	3.000	Asbestos	PCME	EMSL	4/25/06	< 0.00082	No	No	

Note:

1. Asbestos samples at Station 16 (East Face - North end at corner [scaffolding level]) on April 22 and 24, 2006 were not available for analysis on account of a damaged filter.
2. Asbestos sample at Station 1 (Southwest Area [sidewalk bridge level]) on April 23, 2006 was not available for analysis on account of a damaged filter.