

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-4/21/09	030910224-0001	Southwest Area (sidewalk bridge level)	4/21/09	1	3.080	Asbestos	PCME	EMSL	4/22/09	< 0.00080	No	No	
ASBESTOS-ST2-4/21/09	030910224-0002	Southeast Area (sidewalk bridge level)	4/21/09	1	2.990	Asbestos	PCME	EMSL	4/22/09	< 0.00083	No	No	
ASBESTOS-ST4-4/21/09	030910224-0003	Northwest Area (street-level)	4/21/09	1	3.080	Asbestos	PCME	EMSL	4/22/09	< 0.00080	No	No	
ASBESTOS-ST5-4/21/09	030910224-0004	Firehouse #10 (roof level)	4/21/09	1	3.060	Asbestos	PCME	EMSL	4/22/09	< 0.00081	No	No	
ASBESTOS-ST10-4/21/09	030910224-0005	North Side Sidewalk Bridge	4/21/09	1	3.110	Asbestos	PCME	EMSL	4/22/09	< 0.00087	No	No	
ASBESTOS-ST11-4/21/09	030910224-0006	90 Trinity Place (roof level)	4/21/09	1	3.120	Asbestos	PCME	EMSL	4/22/09	< 0.00086	No	No	
ASBESTOS-ST12-4/21/09	030910224-0007	110 Greenwich Street (roof level)	4/21/09	1	3.010	Asbestos	PCME	EMSL	4/22/09	< 0.00082	No	No	
ASBESTOS-ST13-4/21/09	030910224-0008	Marriott Hotel, 38th Floor (roof level)	4/21/09	1	3.100	Asbestos	PCME	EMSL	4/22/09	< 0.00087	No	No	
ASBESTOS-ST14-4/21/09	030910224-0009	West Face - South end at corner (scaffolding level)	4/21/09	1	3.120	Asbestos	PCME	EMSL	4/22/09	< 0.00086	No	No	
ASBESTOS-ST15-4/21/09	030910224-0010	South Face - East end at corner (scaffolding level)	4/21/09	1	3.040	Asbestos	PCME	EMSL	4/22/09	< 0.00081	No	No	
ASBESTOS-ST16-4/21/09	030910224-0011	East Face - North end at corner (scaffolding level)	4/21/09	1	3.010	Asbestos	PCME	EMSL	4/22/09	< 0.00082	No	No	
ASBESTOS-ST17-4/21/09	030910224-0012	North Face - West end at corner (scaffolding level)	4/21/09	1	3.040	Asbestos	PCME	EMSL	4/22/09	< 0.00081	No	No	
ASBESTOS-ST1-4/22/09	030910324-0001	Southwest Area (sidewalk bridge level)	4/22/09	1	3.160	Asbestos	PCME	EMSL	4/23/09	< 0.00078	No	No	
ASBESTOS-ST2-4/22/09	030910324-0002	Southeast Area (sidewalk bridge level)	4/22/09	1	3.110	Asbestos	PCME	EMSL	4/23/09	< 0.00079	No	No	
ASBESTOS-ST4-4/22/09	030910324-0003	Northwest Area (street-level)	4/22/09	1	3.060	Asbestos	PCME	EMSL	4/23/09	< 0.00081	No	No	
ASBESTOS-ST5-4/22/09	030910324-0004	Firehouse #10 (roof level)	4/22/09	1	3.090	Asbestos	PCME	EMSL	4/23/09	< 0.00080	No	No	
ASBESTOS-ST10-4/22/09	030910324-0005	North Side Sidewalk Bridge	4/22/09	1	2.970	Asbestos	PCME	EMSL	4/23/09	< 0.00083	No	No	
ASBESTOS-ST11-4/22/09	030910324-0006	90 Trinity Place (roof level)	4/22/09	1	3.040	Asbestos	PCME	EMSL	4/23/09	< 0.00081	No	No	
ASBESTOS-ST12-4/22/09	030910324-0007	110 Greenwich Street (roof level)	4/22/09	1	2.990	Asbestos	PCME	EMSL	4/23/09	< 0.00083	No	No	
ASBESTOS-ST13-4/22/09	030910324-0008	Marriott Hotel, 38th Floor (roof level)	4/22/09	1	3.070	Asbestos	PCME	EMSL	4/23/09	< 0.00080	No	No	
ASBESTOS-ST14-4/22/09	030910324-0009	West Face - South end at corner (scaffolding level)	4/22/09	1	3.140	Asbestos	PCME	EMSL	4/23/09	< 0.00079	No	No	
ASBESTOS-ST15-4/22/09	030910324-0010	South Face - East end at corner (scaffolding level)	4/22/09	1	3.060	Asbestos	PCME	EMSL	4/23/09	< 0.00081	No	No	
ASBESTOS-ST16-4/22/09	030910324-0011	East Face - North end at corner (scaffolding level)	4/22/09	1	3.040	Asbestos	PCME	EMSL	4/23/09	< 0.00081	No	No	
ASBESTOS-ST17-4/22/09	030910324-0012	North Face - West end at corner (scaffolding level)	4/22/09	1	2.960	Asbestos	PCME	EMSL	4/23/09	< 0.00083	No	No	
ASBESTOS-ST1-4/23/09	030910408-0001	Southwest Area (sidewalk bridge level)	4/23/09	1	3.150	Asbestos	PCME	EMSL	4/24/09	< 0.00078	No	No	
ASBESTOS-ST2-4/23/09	030910408-0002	Southeast Area (sidewalk bridge level)	4/23/09	1	3.120	Asbestos	PCME	EMSL	4/24/09	< 0.00079	No	No	
ASBESTOS-ST4-4/23/09	030910408-0003	Northwest Area (street-level)	4/23/09	1	3.100	Asbestos	PCME	EMSL	4/24/09	< 0.00080	No	No	
ASBESTOS-ST5-4/23/09	030910408-0004	Firehouse #10 (roof level)	4/23/09	1	3.090	Asbestos	PCME	EMSL	4/24/09	< 0.00080	No	No	
ASBESTOS-ST10-4/23/09	030910408-0005	North Side Sidewalk Bridge	4/23/09	1	3.030	Asbestos	PCME	EMSL	4/24/09	< 0.00081	No	No	
ASBESTOS-ST11-4/23/09	030910408-0006	90 Trinity Place (roof level)	4/23/09	1	3.050	Asbestos	PCME	EMSL	4/24/09	< 0.00081	No	No	
ASBESTOS-ST12-4/23/09	030910408-0007	110 Greenwich Street (roof level)	4/23/09	1	3.090	Asbestos	PCME	EMSL	4/24/09	< 0.00080	No	No	
ASBESTOS-ST13-4/23/09	030910408-0008	Marriott Hotel, 38th Floor (roof level)	4/23/09	1	3.090	Asbestos	PCME	EMSL	4/24/09	< 0.00080	No	No	
ASBESTOS-ST14-4/23/09	030910408-0009	West Face - South end at corner (scaffolding level)	4/23/09	1	3.160	Asbestos	PCME	EMSL	4/24/09	< 0.00078	No	No	
ASBESTOS-ST15-4/23/09	030910408-0010	South Face - East end at corner (scaffolding level)	4/23/09	1	3.110	Asbestos	PCME	EMSL	4/24/09	< 0.00079	No	No	
ASBESTOS-ST16-4/23/09	030910408-0011	East Face - North end at corner (scaffolding level)	4/23/09	1	3.190	Asbestos	PCME	EMSL	4/24/09	< 0.00077	No	No	
ASBESTOS-ST17-4/23/09	030910408-0012	North Face - West end at corner (scaffolding level)	4/23/09	1	3.030	Asbestos	PCME	EMSL	4/24/09	< 0.00081	No	No	
ASBESTOS-ST1-4/24/09	030910490-0001	Southwest Area (sidewalk bridge level)	4/24/09	1	2.890	Asbestos	PCME	EMSL	4/25/09	< 0.00085	No	No	
ASBESTOS-ST2-4/24/09	030910490-0002	Southeast Area (sidewalk bridge level)	4/24/09	1	2.940	Asbestos	PCME	EMSL	4/25/09	< 0.00084	No	No	
ASBESTOS-ST4-4/24/09	030910490-0003	Northwest Area (street-level)	4/24/09	1	2.940	Asbestos	PCME	EMSL	4/25/09	< 0.00084	No	No	
ASBESTOS-ST5-4/24/09	030910490-0004	Firehouse #10 (roof level)	4/24/09	1	3.050	Asbestos	PCME	EMSL	4/25/09	< 0.00081	No	No	
ASBESTOS-ST10-4/24/09	030910490-0005	North Side Sidewalk Bridge	4/24/09	1	2.960	Asbestos	PCME	EMSL	4/25/09	< 0.00083	No	No	
ASBESTOS-ST100-4/24/09	030910490-0013	Station 10 Field Duplicate	4/24/09	1	2.940	Asbestos	PCME	EMSL	4/25/09	< 0.00084	No	No	
ASBESTOS-ST11-4/24/09	030910490-0006	90 Trinity Place (roof level)	4/24/09	1	3.030	Asbestos	PCME	EMSL	4/25/09	< 0.00081	No	No	
ASBESTOS-ST12-4/24/09	030910490-0007	110 Greenwich Street (roof level)	4/24/09	1	2.920	Asbestos	PCME	EMSL	4/25/09	< 0.00085	No	No	
ASBESTOS-ST13-4/24/09	030910490-0008	Marriott Hotel, 38th Floor (roof level)	4/24/09	1	3.070	Asbestos	PCME	EMSL	4/25/09	< 0.00080	No	No	
ASBESTOS-ST14-4/24/09	030910490-0009	West Face - South end at corner (scaffolding level)	4/24/09	1	2.890	Asbestos	PCME	EMSL	4/25/09	< 0.00085	No	No	
ASBESTOS-ST15-4/24/09	030910490-0010	South Face - East end at corner (scaffolding level)	4/24/09	1	2.920	Asbestos	PCME	EMSL	4/25/09	< 0.00085	No	No	
ASBESTOS-ST16-4/24/09	030910490-0011	East Face - North end at corner (scaffolding level)	4/24/09	1	2.770	Asbestos	PCME	EMSL	4/25/09	< 0.00089	No	No	
ASBESTOS-ST17-4/24/09	030910490-0012	North Face - West end at corner (scaffolding level)	4/24/09	1	2.870	Asbestos	PCME	EMSL	4/25/09	< 0.00086	No	No	