

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-5/6/08	030813970-0001	Southwest Area (sidewalk bridge level)	5/6/08	1	3.280	Asbestos	PCME	EMSL	5/8/08	< 0.00075	No	No	
ASBESTOS-ST2-5/6/08	030813970-0002	Southeast Area (sidewalk bridge level)	5/6/08	1	3.020	Asbestos	PCME	EMSL	5/8/08	< 0.00082	No	No	
ASBESTOS-ST4-5/6/08	030813970-0003	Northwest Area (street-level)	5/6/08	1	3.170	Asbestos	PCME	EMSL	5/8/08	< 0.00078	No	No	
ASBESTOS-ST5-5/6/08	030813970-0004	Firehouse #10 (roof level)	5/6/08	1	3.090	Asbestos	PCME	EMSL	5/8/08	< 0.00080	No	No	
ASBESTOS-ST10-5/6/08	030813970-0005	North Side Sidewalk Bridge	5/6/08	1	3.040	Asbestos	PCME	EMSL	5/8/08	< 0.00081	No	No	
ASBESTOS-ST11-5/6/08	030813970-0006	90 Trinity Place (roof level)	5/6/08	1	3.060	Asbestos	PCME	EMSL	5/8/08	< 0.00081	No	No	
ASBESTOS-ST12-5/6/08	030813970-0007	110 Greenwich Street (roof level)	5/6/08	1	3.000	Asbestos	PCME	EMSL	5/8/08	< 0.00082	No	No	
ASBESTOS-ST13-5/6/08	030813970-0008	Marriott Hotel, 38th Floor (roof level)	5/6/08	1	3.010	Asbestos	PCME	EMSL	5/8/08	< 0.00082	No	No	
ASBESTOS-ST14-5/6/08	030813970-0009	West Face - South end at corner (scaffolding level)	5/6/08	1	3.080	Asbestos	PCME	EMSL	5/8/08	< 0.00080	No	No	
ASBESTOS-ST15-5/6/08	030813970-0010	South Face - East end at corner (scaffolding level)	5/6/08	1	3.040	Asbestos	PCME	EMSL	5/8/08	< 0.00081	No	No	
ASBESTOS-ST16-5/6/08	030813970-0011	East Face - North end at corner (scaffolding level)	5/6/08	1	3.110	Asbestos	PCME	EMSL	5/8/08	< 0.00087	No	No	
ASBESTOS-ST17-5/6/08	030813970-0012	North Face - West end at corner (scaffolding level)	5/6/08	1	3.070	Asbestos	PCME	EMSL	5/8/08	< 0.00080	No	No	
ASBESTOS-ST1-5/7/08	030814106-0001	Southwest Area (sidewalk bridge level)	5/7/08	1	3.220	Asbestos	PCME	EMSL	5/8/08	< 0.00077	No	No	
ASBESTOS-ST2-5/7/08	030814106-0002	Southeast Area (sidewalk bridge level)	5/7/08	1	3.120	Asbestos	PCME	EMSL	5/8/08	< 0.00079	No	No	
ASBESTOS-ST5-5/7/08	030814106-0003	Firehouse #10 (roof level)	5/7/08	1	3.110	Asbestos	PCME	EMSL	5/8/08	< 0.00079	No	No	
ASBESTOS-ST10-5/7/08	030814106-0004	North Side Sidewalk Bridge	5/7/08	1	2.990	Asbestos	PCME	EMSL	5/8/08	< 0.00083	No	No	
ASBESTOS-ST11-5/7/08	030814106-0005	90 Trinity Place (roof level)	5/7/08	1	3.010	Asbestos	PCME	EMSL	5/8/08	< 0.00082	No	No	
ASBESTOS-ST12-5/7/08	030814106-0006	110 Greenwich Street (roof level)	5/7/08	1	3.000	Asbestos	PCME	EMSL	5/8/08	< 0.00082	No	No	
ASBESTOS-ST13-5/7/08	030814106-0007	Marriott Hotel, 38th Floor (roof level)	5/7/08	1	3.040	Asbestos	PCME	EMSL	5/8/08	< 0.00081	No	No	
ASBESTOS-ST14-5/7/08	030814106-0008	West Face - South end at corner (scaffolding level)	5/7/08	1	3.010	Asbestos	PCME	EMSL	5/8/08	< 0.00082	No	No	
ASBESTOS-ST15-5/7/08	030814106-0009	South Face - East end at corner (scaffolding level)	5/7/08	1	3.110	Asbestos	PCME	EMSL	5/8/08	< 0.00079	No	No	
ASBESTOS-ST16-5/7/08	030814106-0010	East Face - North end at corner (scaffolding level)	5/7/08	1	3.120	Asbestos	PCME	EMSL	5/8/08	< 0.00079	No	No	
ASBESTOS-ST17-5/7/08	030814106-0011	North Face - West end at corner (scaffolding level)	5/7/08	1	3.060	Asbestos	PCME	EMSL	5/8/08	< 0.00081	No	No	
ASBESTOS-ST1-5/8/08	030814214-0001	Southwest Area (sidewalk bridge level)	5/8/08	1	3.020	Asbestos	PCME	EMSL	5/9/08	< 0.00082	No	No	
ASBESTOS-ST2-5/8/08	030814214-0002	Southeast Area (sidewalk bridge level)	5/8/08	1	2.940	Asbestos	PCME	EMSL	5/9/08	< 0.00084	No	No	
ASBESTOS-ST4-5/8/08	030814214-0003	Northwest Area (street-level)	5/8/08	1	2.780	Asbestos	PCME	EMSL	5/9/08	< 0.00089	No	No	
ASBESTOS-ST5-5/8/08	030814214-0004	Firehouse #10 (roof level)	5/8/08	1	3.070	Asbestos	PCME	EMSL	5/9/08	< 0.00080	No	No	
ASBESTOS-ST10-5/8/08	030814214-0005	North Side Sidewalk Bridge	5/8/08	1	2.970	Asbestos	PCME	EMSL	5/9/08	< 0.00088	No	No	
ASBESTOS-ST11-5/8/08	030814214-0006	90 Trinity Place (roof level)	5/8/08	1	3.010	Asbestos	PCME	EMSL	5/9/08	< 0.00082	No	No	
ASBESTOS-ST12-5/8/08	030814214-0007	110 Greenwich Street (roof level)	5/8/08	1	3.090	Asbestos	PCME	EMSL	5/9/08	< 0.00080	No	No	
ASBESTOS-ST13-5/8/08	030814214-0008	Marriott Hotel, 38th Floor (roof level)	5/8/08	1	3.000	Asbestos	PCME	EMSL	5/9/08	< 0.00082	No	No	
ASBESTOS-ST14-5/8/08	030814214-0009	West Face - South end at corner (scaffolding level)	5/8/08	1	3.110	Asbestos	PCME	EMSL	5/9/08	< 0.00079	No	No	
ASBESTOS-ST15-5/8/08	030814214-0010	South Face - East end at corner (scaffolding level)	5/8/08	1	2.980	Asbestos	PCME	EMSL	5/9/08	< 0.00083	No	No	
ASBESTOS-ST16-5/8/08	030814214-0011	East Face - North end at corner (scaffolding level)	5/8/08	1	3.050	Asbestos	PCME	EMSL	5/9/08	< 0.00081	No	No	
ASBESTOS-ST17-5/8/08	030814214-0012	North Face - West end at corner (scaffolding level)	5/8/08	1	3.040	Asbestos	PCME	EMSL	5/9/08	< 0.00081	No	No	
ASBESTOS-ST1-5/9/08	030814339-0001	Southwest Area (sidewalk bridge level)	5/9/08	1	2.900	Asbestos	PCME	EMSL	5/10/08	< 0.00085	No	No	
ASBESTOS-ST2-5/9/08	030814339-0002	Southeast Area (sidewalk bridge level)	5/9/08	1	3.240	Asbestos	PCME	EMSL	5/10/08	< 0.00076	No	No	
ASBESTOS-ST4-5/9/08	030814339-0003	Northwest Area (street-level)	5/9/08	1	2.940	Asbestos	PCME	EMSL	5/10/08	< 0.00084	No	No	
ASBESTOS-ST5-5/9/08	030814339-0004	Firehouse #10 (roof level)	5/9/08	1	3.140	Asbestos	PCME	EMSL	5/10/08	< 0.00079	No	No	
ASBESTOS-ST10-5/9/08	030814339-0005	North Side Sidewalk Bridge	5/9/08	1	2.970	Asbestos	PCME	EMSL	5/10/08	< 0.00083	No	No	
ASBESTOS-ST11-5/9/08	030814339-0006	90 Trinity Place (roof level)	5/9/08	1	3.010	Asbestos	PCME	EMSL	5/10/08	< 0.00082	No	No	
ASBESTOS-ST12-5/9/08	030814339-0007	110 Greenwich Street (roof level)	5/9/08	1	2.990	Asbestos	PCME	EMSL	5/10/08	< 0.00083	No	No	
ASBESTOS-ST13-5/9/08	030814339-0008	Marriott Hotel, 38th Floor (roof level)	5/9/08	1	3.030	Asbestos	PCME	EMSL	5/10/08	< 0.00081	No	No	
ASBESTOS-ST14-5/9/08	030814339-0009	West Face - South end at corner (scaffolding level)	5/9/08	1	3.030	Asbestos	PCME	EMSL	5/10/08	< 0.00081	No	No	
ASBESTOS-ST15-5/9/08	030814339-0010	South Face - East end at corner (scaffolding level)	5/9/08	1	3.050	Asbestos	PCME	EMSL	5/10/08	< 0.00081	No	No	
ASBESTOS-ST16-5/9/08	030814339-0011	East Face - North end at corner (scaffolding level)	5/9/08	1	2.990	Asbestos	PCME	EMSL	5/10/08	< 0.00083	No	No	
ASBESTOS-ST17-5/9/08	030814339-0012	North Face - West end at corner (scaffolding level)	5/9/08	1	2.970	Asbestos	PCME	EMSL	5/10/08	< 0.00083	No	No	

Note:

1. Asbestos sample at Station 4 (Northwest Area [street-level]) on May 7, 2008 was not available for analysis on account of power failure.