

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										NA			
ASBETSOS-ST1-5/12/06	030614773-0001	Southwest Area (sidewalk bridge level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST2-5/12/06	030614773-0002	Southeast Area (sidewalk bridge level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST4-5/12/06	030614773-0003	Northwest Area (street-level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST5-5/12/06	030614773-0004	Firehouse #10 (roof level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST10-5/12/06	030614773-0005	North Side Sidewalk Bridge	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST11-5/12/06	030614773-0006	90 Trinity Place (roof level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST12-5/12/06	030614773-0007	110 Greenwich Street (roof level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST13-5/12/06	030614773-0008	Marriott Hotel, 38th Floor (roof level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST14-5/12/06	030614773-0009	West Face - South end at corner (scaffolding level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST15-5/12/06	030614773-0010	South Face - East end at corner (scaffolding level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST16-5/12/06	030614773-0011	East Face - North end at corner (scaffolding level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBETSOS-ST17-5/12/06	030614773-0012	North Face - West end at corner (scaffolding level)	5/12/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST1-5/13/06	030614774-0001	Southwest Area (sidewalk bridge level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST2-5/13/06	030614774-0002	Southeast Area (sidewalk bridge level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST4-5/13/06	030614774-0003	Northwest Area (street-level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST5-5/13/06	030614774-0004	Firehouse #10 (roof level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST10-5/13/06	030614774-0005	North Side Sidewalk Bridge	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST11-5/13/06	030614774-0006	90 Trinity Place (roof level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST12-5/13/06	030614774-0007	110 Greenwich Street (roof level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST13-5/13/06	030614774-0008	Marriott Hotel, 38th Floor (roof level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST14-5/13/06	030614774-0009	West Face - South end at corner (scaffolding level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST15-5/13/06	030614774-0010	South Face - East end at corner (scaffolding level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST16-5/13/06	030614774-0011	East Face - North end at corner (scaffolding level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST17-5/13/06	030614774-0012	North Face - West end at corner (scaffolding level)	5/13/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST1-5/14/06	030614775-0001	Southwest Area (sidewalk bridge level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST2-5/14/06	030614775-0002	Southeast Area (sidewalk bridge level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST4-5/14/06	030614775-0003	Northwest Area (street-level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST5-5/14/06	030614775-0004	Firehouse #10 (roof level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST10-5/14/06	030614775-0005	North Side Sidewalk Bridge	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST11-5/14/06	030614775-0006	90 Trinity Place (roof level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST12-5/14/06	030614775-0007	110 Greenwich Street (roof level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST13-5/14/06	030614775-0008	Marriott Hotel, 38th Floor (roof level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST14-5/14/06	030614775-0009	West Face - South end at corner (scaffolding level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST15-5/14/06	030614775-0010	South Face - East end at corner (scaffolding level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST16-5/14/06	030614775-0011	East Face - North end at corner (scaffolding level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST17-5/14/06	030614775-0012	North Face - West end at corner (scaffolding level)	5/14/06	1	3.000	Asbestos	PCME	EMSL	5/15/06	< 0.00082	No	No	
ASBESTOS-ST1-5/15/06	030614932-0001	Southwest Area (sidewalk bridge level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST2-5/15/06	030614932-0002	Southeast Area (sidewalk bridge level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST4-5/15/06	030614932-0003	Northwest Area (street-level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST5-5/15/06	030614932-0004	Firehouse #10 (roof level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST10-5/15/06	030614932-0005	North Side Sidewalk Bridge	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST11-5/15/06	030614932-0006	90 Trinity Place (roof level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST12-5/15/06	030614932-0007	110 Greenwich Street (roof level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST14-5/15/06	030614932-0008	West Face - South end at corner (scaffolding level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST15-5/15/06	030614932-0009	South Face - East end at corner (scaffolding level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST16-5/15/06	030614932-0010	East Face - North end at corner (scaffolding level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	
ASBESTOS-ST17-5/15/06	030614932-0011	North Face - West end at corner (scaffolding level)	5/15/06	1	3.000	Asbestos	PCME	EMSL	5/16/06	< 0.00082	No	No	

Note:

- Asbestos sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on May 15, 2006 was not available for analysis on account of damaged filter.