

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments	
										0.0009	Air Quality Levels	Site Specific Trigger Levels		
										NA				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-5/14/07	030715461-0001	Southwest Area (sidewalk bridge level)	5/14/07	1	3.010	Asbestos	PCME	EMSL	5/15/07	< 0.00082	No	No		
ASBESTOS-ST2-5/14/07	030715461-0002	Southeast Area (sidewalk bridge level)	5/14/07	1	3.050	Asbestos	PCME	EMSL	5/15/07	< 0.00081	No	No		
ASBESTOS-ST4-5/14/07	030715461-0003	Northwest Area (street-level)	5/14/07	1	3.060	Asbestos	PCME	EMSL	5/15/07	< 0.00081	No	No		
ASBESTOS-ST5-5/14/07	030715461-0004	Firehouse #10 (roof level)	5/14/07	1	3.020	Asbestos	PCME	EMSL	5/15/07	< 0.00082	No	No		
ASBESTOS-ST10-5/14/07	030715461-0005	North Side Sidewalk Bridge	5/14/07	1	3.070	Asbestos	PCME	EMSL	5/15/07	< 0.00080	No	No		
ASBESTOS-ST11-5/14/07	030715461-0006	90 Trinity Place (roof level)	5/14/07	1	2.860	Asbestos	PCME	EMSL	5/15/07	< 0.00080	No	No		
ASBESTOS-ST12-5/14/07	030715461-0007	110 Greenwich Street (roof level)	5/14/07	1	3.050	Asbestos	PCME	EMSL	5/15/07	< 0.00081	No	No		
ASBESTOS-ST13-5/14/07	030715461-0008	Marriott Hotel, 38th Floor (roof level)	5/14/07	1	3.020	Asbestos	PCME	EMSL	5/15/07	< 0.00082	No	No		
ASBESTOS-ST14-5/14/07	030715461-0009	West Face - South end at corner (scaffolding level)	5/14/07	1	3.070	Asbestos	PCME	EMSL	5/15/07	< 0.00080	No	No		
ASBESTOS-ST15-5/14/07	030715461-0010	South Face - East end at corner (scaffolding level)	5/14/07	1	3.040	Asbestos	PCME	EMSL	5/15/07	< 0.00081	No	No		
ASBESTOS-ST16-5/14/07	030715461-0011	East Face - North end at corner (scaffolding level)	5/14/07	1	3.030	Asbestos	PCME	EMSL	5/15/07	< 0.00081	No	No		
ASBESTOS-ST17-5/14/07	030715461-0012	North Face - West end at corner (scaffolding level)	5/14/07	1	3.090	Asbestos	PCME	EMSL	5/15/07	< 0.00080	No	No		
ASBESTOS-ST1-5/15/07	030715630-0001	Southwest Area (sidewalk bridge level)	5/15/07	1	3.040	Asbestos	PCME	EMSL	5/16/07	< 0.00081	No	No		
ASBESTOS-ST2-5/15/07	030715630-0002	Southeast Area (sidewalk bridge level)	5/15/07	1	3.070	Asbestos	PCME	EMSL	5/16/07	< 0.00080	No	No		
ASBESTOS-ST4-5/15/07	030715630-0003	Northwest Area (street-level)	5/15/07	1	3.050	Asbestos	PCME	EMSL	5/16/07	< 0.00081	No	No		
ASBESTOS-ST5-5/15/07	030715630-0004	Firehouse #10 (roof level)	5/15/07	1	3.010	Asbestos	PCME	EMSL	5/16/07	< 0.00082	No	No		
ASBESTOS-ST10-5/15/07	030715630-0005	North Side Sidewalk Bridge	5/15/07	1	3.010	Asbestos	PCME	EMSL	5/16/07	< 0.00082	No	No		
ASBESTOS-ST100-5/15/07	030715630-0013	Station 10 Field Duplicate	5/15/07	1	3.040	Asbestos	PCME	EMSL	5/16/07	< 0.00081	No	No		
ASBESTOS-ST11-5/15/07	030715630-0006	90 Trinity Place (roof level)	5/15/07	1	3.160	Asbestos	PCME	EMSL	5/16/07	< 0.00078	No	No		
ASBESTOS-ST12-5/15/07	030715630-0007	110 Greenwich Street (roof level)	5/15/07	1	3.000	Asbestos	PCME	EMSL	5/16/07	< 0.00082	No	No		
ASBESTOS-ST13-5/15/07	030715630-0008	Marriott Hotel, 38th Floor (roof level)	5/15/07	1	3.030	Asbestos	PCME	EMSL	5/16/07	< 0.00081	No	No		
ASBESTOS-ST14-5/15/07	030715630-0009	West Face - South end at corner (scaffolding level)	5/15/07	1	3.070	Asbestos	PCME	EMSL	5/16/07	< 0.00080	No	No		
ASBESTOS-ST15-5/15/07	030715630-0010	South Face - East end at corner (scaffolding level)	5/15/07	1	3.020	Asbestos	PCME	EMSL	5/16/07	< 0.00082	No	No		
ASBESTOS-ST16-5/15/07	030715630-0011	East Face - North end at corner (scaffolding level)	5/15/07	1	3.050	Asbestos	PCME	EMSL	5/16/07	< 0.00081	No	No		
ASBESTOS-ST17-5/15/07	030715630-0012	North Face - West end at corner (scaffolding level)	5/15/07	1	3.040	Asbestos	PCME	EMSL	5/16/07	< 0.00081	No	No		