

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm <sup>3</sup> )	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>										<b>0.0009</b>			
<b>EPA Site Specific Trigger Levels</b>										<b>NA</b>			
ASBESTOS-ST1-5/15/10	031012768-0001	Southwest Area (sidewalk bridge level)	5/15/10	1	3.070	Asbestos	PCME	EMSL	5/17/10	< 0.00088	No	No	
ASBESTOS-ST2-5/15/10	031012768-0002	Southeast Area (sidewalk bridge level)	5/15/10	1	3.100	Asbestos	PCME	EMSL	5/17/10	< 0.00087	No	No	
ASBESTOS-ST4-5/15/10	031012768-0003	Northwest Area (street-level)	5/15/10	1	3.070	Asbestos	PCME	EMSL	5/17/10	< 0.00088	No	No	
ASBESTOS-ST5-5/15/10	031012768-0004	Firehouse #10 (roof level)	5/15/10	1	3.120	Asbestos	PCME	EMSL	5/17/10	< 0.00086	No	No	
ASBESTOS-ST11-5/15/10	031012768-0006	90 Trinity Place (roof level)	5/15/10	1	2.970	Asbestos	PCME	EMSL	5/17/10	< 0.00083	No	No	
ASBESTOS-ST12-5/15/10	031012768-0007	110 Greenwich Street (roof level)	5/15/10	1	3.010	Asbestos	PCME	EMSL	5/17/10	< 0.00082	No	No	
ASBESTOS-ST20-5/15/10	031012768-0005	Northeast Area, Sidewalk Bridge	5/15/10	1	3.010	Asbestos	PCME	EMSL	5/17/10	< 0.00082	No	No	
ASBESTOS-ST21-5/15/10	031012768-0008	Marriott Hotel, 4th Floor	5/15/10	1	3.050	Asbestos	PCME	EMSL	5/17/10	< 0.00081	No	No	
ASBESTOS-ST1-5/16/10	031012769-0001	Southwest Area (sidewalk bridge level)	5/16/10	1	3.080	Asbestos	PCME	EMSL	5/17/10	< 0.00080	No	No	
ASBESTOS-ST2-5/16/10	031012769-0002	Southeast Area (sidewalk bridge level)	5/16/10	1	3.000	Asbestos	PCME	EMSL	5/17/10	< 0.00082	No	No	
ASBESTOS-ST4-5/16/10	031012769-0003	Northwest Area (street-level)	5/16/10	1	3.050	Asbestos	PCME	EMSL	5/17/10	< 0.00081	No	No	
ASBESTOS-ST5-5/16/10	031012769-0004	Firehouse #10 (roof level)	5/16/10	1	3.080	Asbestos	PCME	EMSL	5/17/10	< 0.00080	No	No	
ASBESTOS-ST11-5/16/10	031012769-0006	90 Trinity Place (roof level)	5/16/10	1	3.120	Asbestos	PCME	EMSL	5/17/10	< 0.00079	No	No	
ASBESTOS-ST12-5/16/10	031012769-0007	110 Greenwich Street (roof level)	5/16/10	1	3.030	Asbestos	PCME	EMSL	5/17/10	< 0.00081	No	No	
ASBESTOS-ST20-5/16/10	031012769-0005	Northeast Area, Sidewalk Bridge	5/16/10	1	2.970	Asbestos	PCME	EMSL	5/17/10	< 0.00083	No	No	
ASBESTOS-ST21-5/16/10	031012769-0008	Marriott Hotel, 4th Floor	5/16/10	1	3.140	Asbestos	PCME	EMSL	5/17/10	< 0.00079	No	No	
ASBESTOS-ST1-5/17/10	031012873-0001	Southwest Area (sidewalk bridge level)	5/17/10	1	3.020	Asbestos	PCME	EMSL	5/18/10	< 0.00082	No	No	
ASBESTOS-ST2-5/17/10	031012873-0002	Southeast Area (sidewalk bridge level)	5/17/10	1	3.050	Asbestos	PCME	EMSL	5/18/10	< 0.00081	No	No	
ASBESTOS-ST4-5/17/10	031012873-0003	Northwest Area (street-level)	5/17/10	1	3.060	Asbestos	PCME	EMSL	5/18/10	< 0.00081	No	No	
ASBESTOS-ST5-5/17/10	031012873-0004	Firehouse #10 (roof level)	5/17/10	1	3.070	Asbestos	PCME	EMSL	5/18/10	< 0.00080	No	No	
ASBESTOS-ST11-5/17/10	031012873-0006	90 Trinity Place (roof level)	5/17/10	1	3.070	Asbestos	PCME	EMSL	5/18/10	< 0.00080	No	No	
ASBESTOS-ST12-5/17/10	031012873-0007	110 Greenwich Street (roof level)	5/17/10	1	3.010	Asbestos	PCME	EMSL	5/18/10	< 0.00082	No	No	
ASBESTOS-ST20-5/17/10	031012873-0005	Northeast Area, Sidewalk Bridge	5/17/10	1	3.120	Asbestos	PCME	EMSL	5/18/10	< 0.00079	No	No	
ASBESTOS-ST21-5/17/10	031012873-0008	Marriott Hotel, 4th Floor	5/17/10	1	3.010	Asbestos	PCME	EMSL	5/18/10	< 0.00082	No	No	