

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-5/18/07	030716177-0001	Southwest Area (sidewalk bridge level)	5/18/07	1	3.010	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST2-5/18/07	030716177-0002	Southeast Area (sidewalk bridge level)	5/18/07	1	3.060	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST4-5/18/07	030716177-0003	Northwest Area (street-level)	5/18/07	1	3.060	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST5-5/18/07	030716177-0004	Firehouse #10 (roof level)	5/18/07	1	3.020	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST10-5/18/07	030716177-0005	North Side Sidewalk Bridge	5/18/07	1	3.050	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST11-5/18/07	030716177-0006	90 Trinity Place (roof level)	5/18/07	1	3.030	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST12-5/18/07	030716177-0007	110 Greenwich Street (roof level)	5/18/07	1	3.060	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST13-5/18/07	030716177-0008	Marriott Hotel, 38th Floor (roof level)	5/18/07	1	3.060	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST14-5/18/07	030716177-0009	West Face - South end at corner (scaffolding level)	5/18/07	1	3.040	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST15-5/18/07	030716177-0010	South Face - East end at corner (scaffolding level)	5/18/07	1	3.020	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST16-5/18/07	030716177-0011	East Face - North end at corner (scaffolding level)	5/18/07	1	3.040	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST17-5/18/07	030716177-0012	North Face - West end at corner (scaffolding level)	5/18/07	1	3.040	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST1-5/19/07	030716178-0001	Southwest Area (sidewalk bridge level)	5/19/07	1	3.040	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST2-5/19/07	030716178-0002	Southeast Area (sidewalk bridge level)	5/19/07	1	3.020	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST4-5/19/07	030716178-0003	Northwest Area (street-level)	5/19/07	1	3.040	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST5-5/19/07	030716178-0004	Firehouse #10 (roof level)	5/19/07	1	3.010	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST10-5/19/07	030716178-0005	North Side Sidewalk Bridge	5/19/07	1	3.060	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST11-5/19/07	030716178-0006	90 Trinity Place (roof level)	5/19/07	1	3.020	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST12-5/19/07	030716178-0007	110 Greenwich Street (roof level)	5/19/07	1	3.020	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST13-5/19/07	030716178-0008	Marriott Hotel, 38th Floor (roof level)	5/19/07	1	3.020	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST14-5/19/07	030716178-0009	West Face - South end at corner (scaffolding level)	5/19/07	1	3.020	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST15-5/19/07	030716178-0010	South Face - East end at corner (scaffolding level)	5/19/07	1	3.020	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST16-5/19/07	030716178-0011	East Face - North end at corner (scaffolding level)	5/19/07	1	3.060	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST17-5/19/07	030716178-0012	North Face - West end at corner (scaffolding level)	5/19/07	1	3.010	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST1-5/20/07	030716179-0001	Southwest Area (sidewalk bridge level)	5/20/07	1	3.010	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST2-5/20/07	030716179-0002	Southeast Area (sidewalk bridge level)	5/20/07	1	3.060	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST4-5/20/07	030716179-0003	Northwest Area (street-level)	5/20/07	1	3.010	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST5-5/20/07	030716179-0004	Firehouse #10 (roof level)	5/20/07	1	3.020	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST10-5/20/07	030716179-0005	North Side Sidewalk Bridge	5/20/07	1	3.010	Asbestos	PCME	EMSL	5/21/07	< 0.00082	No	No	
ASBESTOS-ST11-5/20/07	030716179-0006	90 Trinity Place (roof level)	5/20/07	1	3.160	Asbestos	PCME	EMSL	5/21/07	< 0.00078	No	No	
ASBESTOS-ST12-5/20/07	030716179-0007	110 Greenwich Street (roof level)	5/20/07	1	3.190	Asbestos	PCME	EMSL	5/21/07	< 0.00077	No	No	
ASBESTOS-ST13-5/20/07	030716179-0008	Marriott Hotel, 38th Floor (roof level)	5/20/07	1	3.030	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST14-5/20/07	030716179-0009	West Face - South end at corner (scaffolding level)	5/20/07	1	3.060	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST15-5/20/07	030716179-0010	South Face - East end at corner (scaffolding level)	5/20/07	1	2.990	Asbestos	PCME	EMSL	5/21/07	< 0.00083	No	No	
ASBESTOS-ST16-5/20/07	030716179-0011	East Face - North end at corner (scaffolding level)	5/20/07	1	3.030	Asbestos	PCME	EMSL	5/21/07	< 0.00081	No	No	
ASBESTOS-ST17-5/20/07	030716179-0012	North Face - West end at corner (scaffolding level)	5/20/07	1	2.990	Asbestos	PCME	EMSL	5/21/07	< 0.00083	No	No	