

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-5/19/09	030912700-0001	Southwest Area (sidewalk bridge level)	5/19/09	1	3.010	Asbestos	PCME	EMSL	5/20/09	< 0.00082	No	No	
ASBESTOS-ST2-5/19/09	030912700-0002	Southeast Area (sidewalk bridge level)	5/19/09	1	2.990	Asbestos	PCME	EMSL	5/20/09	< 0.00083	No	No	
ASBESTOS-ST4-5/19/09	030912700-0003	Northwest Area (street-level)	5/19/09	1	3.010	Asbestos	PCME	EMSL	5/20/09	< 0.00082	No	No	
ASBESTOS-ST5-5/19/09	030912700-0004	Firehouse #10 (roof level)	5/19/09	1	3.000	Asbestos	PCME	EMSL	5/20/09	< 0.00082	No	No	
ASBESTOS-ST10-5/19/09	030912700-0005	North Side Sidewalk Bridge	5/19/09	1	3.040	Asbestos	PCME	EMSL	5/20/09	< 0.00081	No	No	
ASBESTOS-ST11-5/19/09	030912700-0006	90 Trinity Place (roof level)	5/19/09	1	3.000	Asbestos	PCME	EMSL	5/20/09	< 0.00082	No	No	
ASBESTOS-ST12-5/19/09	030912700-0007	110 Greenwich Street (roof level)	5/19/09	1	3.060	Asbestos	PCME	EMSL	5/20/09	< 0.00081	No	No	
ASBESTOS-ST13-5/19/09	030912700-0008	Marriott Hotel, 38th Floor (roof level)	5/19/09	1	3.030	Asbestos	PCME	EMSL	5/20/09	< 0.00081	No	No	
ASBESTOS-ST14-5/19/09	030912700-0009	West Face - South end at corner (scaffolding level)	5/19/09	1	3.040	Asbestos	PCME	EMSL	5/20/09	< 0.00081	No	No	
ASBESTOS-ST15-5/19/09	030912700-0010	South Face - East end at corner (scaffolding level)	5/19/09	1	3.000	Asbestos	PCME	EMSL	5/20/09	< 0.00082	No	No	
ASBESTOS-ST16-5/19/09	030912700-0011	East Face - North end at corner (scaffolding level)	5/19/09	1	3.050	Asbestos	PCME	EMSL	5/20/09	< 0.00081	No	No	
ASBESTOS-ST17-5/19/09	030912700-0012	North Face - West end at corner (scaffolding level)	5/19/09	1	2.990	Asbestos	PCME	EMSL	5/20/09	< 0.00083	No	No	
ASBESTOS-ST1-5/20/09	030912782-0001	Southwest Area (sidewalk bridge level)	5/20/09	1	3.040	Asbestos	PCME	EMSL	5/21/09	< 0.00081	No	No	
ASBESTOS-ST2-5/20/09	030912782-0002	Southeast Area (sidewalk bridge level)	5/20/09	1	3.110	Asbestos	PCME	EMSL	5/21/09	< 0.00079	No	No	
ASBESTOS-ST4-5/20/09	030912782-0003	Northwest Area (street-level)	5/20/09	1	3.000	Asbestos	PCME	EMSL	5/21/09	< 0.00082	No	No	
ASBESTOS-ST5-5/20/09	030912782-0004	Firehouse #10 (roof level)	5/20/09	1	3.050	Asbestos	PCME	EMSL	5/21/09	< 0.00081	No	No	
ASBESTOS-ST10-5/20/09	030912782-0005	North Side Sidewalk Bridge	5/20/09	1	3.260	Asbestos	PCME	EMSL	5/21/09	< 0.00076	No	No	
ASBESTOS-ST100-5/20/09	030912782-0013	Station 10 Field Duplicate	5/20/09	1	3.170	Asbestos	PCME	EMSL	5/21/09	< 0.00078	No	No	
ASBESTOS-ST11-5/20/09	030912782-0006	90 Trinity Place (roof level)	5/20/09	1	3.160	Asbestos	PCME	EMSL	5/21/09	< 0.00078	No	No	
ASBESTOS-ST12-5/20/09	030912782-0007	110 Greenwich Street (roof level)	5/20/09	1	3.120	Asbestos	PCME	EMSL	5/21/09	< 0.00079	No	No	
ASBESTOS-ST13-5/20/09	030912782-0008	Marriott Hotel, 38th Floor (roof level)	5/20/09	1	3.160	Asbestos	PCME	EMSL	5/21/09	< 0.00078	No	No	
ASBESTOS-ST14-5/20/09	030912782-0009	West Face - South end at corner (scaffolding level)	5/20/09	1	3.120	Asbestos	PCME	EMSL	5/21/09	< 0.00079	No	No	
ASBESTOS-ST15-5/20/09	030912782-0010	South Face - East end at corner (scaffolding level)	5/20/09	1	3.010	Asbestos	PCME	EMSL	5/21/09	< 0.00082	No	No	
ASBESTOS-ST16-5/20/09	030912782-0011	East Face - North end at corner (scaffolding level)	5/20/09	1	3.060	Asbestos	PCME	EMSL	5/21/09	< 0.00081	No	No	
ASBESTOS-ST17-5/20/09	030912782-0012	North Face - West end at corner (scaffolding level)	5/20/09	1	2.980	Asbestos	PCME	EMSL	5/21/09	< 0.00083	No	No	
ASBESTOS-ST1-5/21/09	030912889-0001	Southwest Area (sidewalk bridge level)	5/21/09	1	3.030	Asbestos	PCME	EMSL	5/22/09	< 0.00081	No	No	
ASBESTOS-ST2-5/21/09	030912889-0002	Southeast Area (sidewalk bridge level)	5/21/09	1	3.060	Asbestos	PCME	EMSL	5/22/09	< 0.00081	No	No	
ASBESTOS-ST4-5/21/09	030912889-0003	Northwest Area (street-level)	5/21/09	1	3.110	Asbestos	PCME	EMSL	5/22/09	< 0.00087	No	No	
ASBESTOS-ST5-5/21/09	030912889-0004	Firehouse #10 (roof level)	5/21/09	1	0.470	Asbestos	PCME	EMSL	5/22/09	< 0.00088	No	No	Note 1
ASBESTOS-ST10-5/21/09	030912889-0005	North Side Sidewalk Bridge	5/21/09	1	3.040	Asbestos	PCME	EMSL	5/22/09	< 0.00081	No	No	
ASBESTOS-ST11-5/21/09	030912889-0006	90 Trinity Place (roof level)	5/21/09	1	3.090	Asbestos	PCME	EMSL	5/22/09	< 0.00087	No	No	
ASBESTOS-ST12-5/21/09	030912889-0007	110 Greenwich Street (roof level)	5/21/09	1	3.170	Asbestos	PCME	EMSL	5/22/09	< 0.00085	No	No	
ASBESTOS-ST13-5/21/09	030912889-0008	Marriott Hotel, 38th Floor (roof level)	5/21/09	1	2.990	Asbestos	PCME	EMSL	5/22/09	< 0.00083	No	No	
ASBESTOS-ST14-5/21/09	030912889-0009	West Face - South end at corner (scaffolding level)	5/21/09	1	3.060	Asbestos	PCME	EMSL	5/22/09	< 0.00081	No	No	
ASBESTOS-ST15-5/21/09	030912889-0010	South Face - East end at corner (scaffolding level)	5/21/09	1	3.040	Asbestos	PCME	EMSL	5/22/09	< 0.00081	No	No	
ASBESTOS-ST16-5/21/09	030912889-0011	East Face - North end at corner (scaffolding level)	5/21/09	1	2.990	Asbestos	PCME	EMSL	5/22/09	< 0.00083	No	No	
ASBESTOS-ST17-5/21/09	030912889-0012	North Face - West end at corner (scaffolding level)	5/21/09	1	3.040	Asbestos	PCME	EMSL	5/22/09	< 0.00081	No	No	
ASBESTOS-ST1-5/22/09	030912978-0001	Southwest Area (sidewalk bridge level)	5/22/09	1	3.060	Asbestos	PCME	EMSL	5/23/09	< 0.00081	No	No	
ASBESTOS-ST2-5/22/09	030912978-0002	Southeast Area (sidewalk bridge level)	5/22/09	1	3.030	Asbestos	PCME	EMSL	5/23/09	< 0.00081	No	No	
ASBESTOS-ST4-5/22/09	030912978-0003	Northwest Area (street-level)	5/22/09	1	3.020	Asbestos	PCME	EMSL	5/23/09	< 0.00082	No	No	
ASBESTOS-ST5-5/22/09	030912978-0004	Firehouse #10 (roof level)	5/22/09	1	2.510	Asbestos	PCME	EMSL	5/23/09	< 0.00084	No	No	Note 2
ASBESTOS-ST10-5/22/09	030912978-0005	North Side Sidewalk Bridge	5/22/09	1	2.980	Asbestos	PCME	EMSL	5/23/09	< 0.00083	No	No	
ASBESTOS-ST11-5/22/09	030912978-0006	90 Trinity Place (roof level)	5/22/09	1	2.980	Asbestos	PCME	EMSL	5/23/09	< 0.00083	No	No	
ASBESTOS-ST12-5/22/09	030912978-0007	110 Greenwich Street (roof level)	5/22/09	1	3.040	Asbestos	PCME	EMSL	5/23/09	< 0.00081	No	No	
ASBESTOS-ST13-5/22/09	030912978-0008	Marriott Hotel, 38th Floor (roof level)	5/22/09	1	3.030	Asbestos	PCME	EMSL	5/23/09	< 0.00081	No	No	
ASBESTOS-ST14-5/22/09	030912978-0009	West Face - South end at corner (scaffolding level)	5/22/09	1	2.910	Asbestos	PCME	EMSL	5/23/09	< 0.00085	No	No	
ASBESTOS-ST15-5/22/09	030912978-0010	South Face - East end at corner (scaffolding level)	5/22/09	1	2.910	Asbestos	PCME	EMSL	5/23/09	< 0.00085	No	No	
ASBESTOS-ST16-5/22/09	030912978-0011	East Face - North end at corner (scaffolding level)	5/22/09	1	2.960	Asbestos	PCME	EMSL	5/23/09	< 0.00083	No	No	
ASBESTOS-ST17-5/22/09	030912978-0012	North Face - West end at corner (scaffolding level)	5/22/09	1	2.880	Asbestos	PCME	EMSL	5/23/09	< 0.00086	No	No	

Note:

1. The asbestos sample from Station 5 (Firehouse #10 [roof level]) on May 21, 2009 had a reduced volume due to a 1,211 minute power outage.
2. The asbestos sample from Station 5 (Firehouse #10 [roof level]) on May 22, 2009 had a slightly reduced volume due to a delay in starting the sample collection on account of a power outage.