

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-5/22/06	030615784-0001	Southwest Area (sidewalk bridge level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST2-5/22/06	030615784-0002	Southeast Area (sidewalk bridge level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST4-5/22/06	030615784-0003	Northwest Area (street-level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST5-5/22/06	030615784-0004	Firehouse #10 (roof level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST10-5/22/06	030615784-0005	North Side Sidewalk Bridge	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST11-5/22/06	030615784-0006	90 Trinity Place (roof level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST12-5/22/06	030615784-0007	110 Greenwich Street (roof level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST13-5/22/06	030615784-0008	Marriott Hotel, 38th Floor (roof level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	0.00083	No	No	
ASBESTOS-ST14-5/22/06	030615784-0009	West Face - South end at corner (scaffolding level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST15-5/22/06	030615784-0010	South Face - East end at corner (scaffolding level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	0.00083	No	No	
ASBESTOS-ST16-5/22/06	030615784-0011	East Face - North end at corner (scaffolding level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST17-5/22/06	030615784-0012	North Face - West end at corner (scaffolding level)	5/22/06	1	2.970	Asbestos	PCME	EMSL	5/23/06	< 0.00083	No	No	
ASBESTOS-ST1-5/23/06	030615878-0001	Southwest Area (sidewalk bridge level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST2-5/23/06	030615878-0002	Southeast Area (sidewalk bridge level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST4-5/23/06	030615878-0003	Northwest Area (street-level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST5-5/23/06	030615878-0004	Firehouse #10 (roof level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST10-5/23/06	030615878-0005	North Side Sidewalk Bridge	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST11-5/23/06	030615878-0006	90 Trinity Place (roof level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST12-5/23/06	030615878-0007	110 Greenwich Street (roof level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST13-5/23/06	030615878-0008	Marriott Hotel, 38th Floor (roof level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST14-5/23/06	030615878-0009	West Face - South end at corner (scaffolding level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST15-5/23/06	030615878-0010	South Face - East end at corner (scaffolding level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST16-5/23/06	030615878-0011	East Face - North end at corner (scaffolding level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST17-5/23/06	030615878-0012	North Face - West end at corner (scaffolding level)	5/23/06	1	2.970	Asbestos	PCME	EMSL	5/24/06	< 0.00083	No	No	
ASBESTOS-ST1-5/24/06	030616068-0001	Southwest Area (sidewalk bridge level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST2-5/24/06	030616068-0002	Southeast Area (sidewalk bridge level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST4-5/24/06	030616068-0003	Northwest Area (street-level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST5-5/24/06	030616068-0004	Firehouse #10 (roof level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST10-5/24/06	030616068-0005	North Side Sidewalk Bridge	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST100-5/24/06	030616068-0013	Station 10 Field Duplicate	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST11-5/24/06	030616068-0006	90 Trinity Place (roof level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST12-5/24/06	030616068-0007	110 Greenwich Street (roof level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST13-5/24/06	030616068-0008	Marriott Hotel, 38th Floor (roof level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST14-5/24/06	030616068-0009	West Face - South end at corner (scaffolding level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST15-5/24/06	030616068-0010	South Face - East end at corner (scaffolding level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST16-5/24/06	030616068-0011	East Face - North end at corner (scaffolding level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	
ASBESTOS-ST17-5/24/06	030616068-0012	North Face - West end at corner (scaffolding level)	5/24/06	1	2.970	Asbestos	PCME	EMSL	5/25/06	< 0.00083	No	No	