

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target | Exceeds EPA | Comments |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|--------------------|--|----------|
| | | | | | | | | | | 0.0009 | Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | |
| | | | | | | | | | | NA | | | |
| Target Air Quality Levels | | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | | |
| ASBESTOS-ST1-5/23/09 | 030913075-0001 | Southwest Area (sidewalk bridge level) | 5/23/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00081 | No | No | |
| ASBESTOS-ST2-5/23/09 | 030913075-0002 | Southeast Area (sidewalk bridge level) | 5/23/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00081 | No | No | |
| ASBESTOS-ST4-5/23/09 | 030913075-0003 | Northwest Area (street-level) | 5/23/09 | 1 | 2.980 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00083 | No | No | |
| ASBESTOS-ST5-5/23/09 | 030913075-0004 | Firehouse #10 (roof level) | 5/23/09 | 1 | 3.070 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00088 | No | No | |
| ASBESTOS-ST10-5/23/09 | 030913075-0005 | North Side Sidewalk Bridge | 5/23/09 | 1 | 3.060 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00081 | No | No | |
| ASBESTOS-ST11-5/23/09 | 030913075-0006 | 90 Trinity Place (roof level) | 5/23/09 | 1 | 3.070 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00088 | No | No | |
| ASBESTOS-ST12-5/23/09 | 030913075-0007 | 110 Greenwich Street (roof level) | 5/23/09 | 1 | 3.000 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |
| ASBESTOS-ST13-5/23/09 | 030913075-0008 | Marriott Hotel, 38th Floor (roof level) | 5/23/09 | 1 | 2.980 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00083 | No | No | |
| ASBESTOS-ST14-5/23/09 | 030913075-0009 | West Face - South end at corner (scaffolding level) | 5/23/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00081 | No | No | |
| ASBESTOS-ST15-5/23/09 | 030913075-0010 | South Face - East end at corner (scaffolding level) | 5/23/09 | 1 | 3.090 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00087 | No | No | |
| ASBESTOS-ST16-5/23/09 | 030913075-0011 | East Face - North end at corner (scaffolding level) | 5/23/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |
| ASBESTOS-ST17-5/23/09 | 030913075-0012 | North Face - West end at corner (scaffolding level) | 5/23/09 | 1 | 2.980 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00083 | No | No | |
| ASBESTOS-ST1-5/24/09 | 030913076-0001 | Southwest Area (sidewalk bridge level) | 5/24/09 | 1 | 3.030 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00081 | No | No | |
| ASBESTOS-ST2-5/24/09 | 030913076-0002 | Southeast Area (sidewalk bridge level) | 5/24/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00081 | No | No | |
| ASBESTOS-ST4-5/24/09 | 030913076-0003 | Northwest Area (street-level) | 5/24/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00081 | No | No | |
| ASBESTOS-ST5-5/24/09 | 030913076-0004 | Firehouse #10 (roof level) | 5/24/09 | 1 | 3.020 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |
| ASBESTOS-ST10-5/24/09 | 030913076-0005 | North Side Sidewalk Bridge | 5/24/09 | 1 | 3.020 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |
| ASBESTOS-ST11-5/24/09 | 030913076-0006 | 90 Trinity Place (roof level) | 5/24/09 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00083 | No | No | |
| ASBESTOS-ST12-5/24/09 | 030913076-0007 | 110 Greenwich Street (roof level) | 5/24/09 | 1 | 2.970 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00083 | No | No | |
| ASBESTOS-ST13-5/24/09 | 030913076-0008 | Marriott Hotel, 38th Floor (roof level) | 5/24/09 | 1 | 2.990 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00083 | No | No | |
| ASBESTOS-ST14-5/24/09 | 030913076-0009 | West Face - South end at corner (scaffolding level) | 5/24/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00080 | No | No | |
| ASBESTOS-ST15-5/24/09 | 030913076-0010 | South Face - East end at corner (scaffolding level) | 5/24/09 | 1 | 2.980 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00083 | No | No | |
| ASBESTOS-ST16-5/24/09 | 030913076-0011 | East Face - North end at corner (scaffolding level) | 5/24/09 | 1 | 3.070 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00080 | No | No | |
| ASBESTOS-ST17-5/24/09 | 030913076-0012 | North Face - West end at corner (scaffolding level) | 5/24/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |