

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target | Exceeds EPA | Comments |
|------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|--------------------|------------------------------|----------|
| | | | | | | | | | | 0.0009 | Air Quality Levels | Site Specific Trigger Levels | |
| | | | | | | | | | | NA | | | |
| ASBESTOS-ST1-5/25/09 | 030913077-0001 | Southwest Area (sidewalk bridge level) | 5/25/09 | 1 | 3.000 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |
| ASBESTOS-ST2-5/25/09 | 030913077-0002 | Southeast Area (sidewalk bridge level) | 5/25/09 | 1 | 3.140 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00086 | No | No | |
| ASBESTOS-ST4-5/25/09 | 030913077-0003 | Northwest Area (street-level) | 5/25/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |
| ASBESTOS-ST5-5/25/09 | 030913077-0004 | Firehouse #10 (roof level) | 5/25/09 | 1 | 3.200 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00084 | No | No | |
| ASBESTOS-ST10-5/25/09 | 030913077-0005 | North Side Sidewalk Bridge | 5/25/09 | 1 | 3.000 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |
| ASBESTOS-ST11-5/25/09 | 030913077-0006 | 90 Trinity Place (roof level) | 5/25/09 | 1 | 3.050 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00081 | No | No | |
| ASBESTOS-ST12-5/25/09 | 030913077-0007 | 110 Greenwich Street (roof level) | 5/25/09 | 1 | 3.020 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |
| ASBESTOS-ST13-5/25/09 | 030913077-0008 | Marriott Hotel, 38th Floor (roof level) | 5/25/09 | 1 | 3.020 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00082 | No | No | |
| ASBESTOS-ST14-5/25/09 | 030913077-0009 | West Face - South end at corner (scaffolding level) | 5/25/09 | 1 | 3.190 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00077 | No | No | |
| ASBESTOS-ST15-5/25/09 | 030913077-0010 | South Face - East end at corner (scaffolding level) | 5/25/09 | 1 | 3.120 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00079 | No | No | |
| ASBESTOS-ST16-5/25/09 | 030913077-0011 | East Face - North end at corner (scaffolding level) | 5/25/09 | 1 | 3.230 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00083 | No | No | |
| ASBESTOS-ST17-5/25/09 | 030913077-0012 | North Face - West end at corner (scaffolding level) | 5/25/09 | 1 | 3.130 | Asbestos | PCME | EMSL | 5/26/09 | < 0.00079 | No | No | |
| ASBESTOS-ST1-5/26/09 | 030913194-0001 | Southwest Area (sidewalk bridge level) | 5/26/09 | 1 | 3.140 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00079 | No | No | |
| ASBESTOS-ST2-5/26/09 | 030913194-0002 | Southeast Area (sidewalk bridge level) | 5/26/09 | 1 | 3.110 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00079 | No | No | |
| ASBESTOS-ST4-5/26/09 | 030913194-0003 | Northwest Area (street-level) | 5/26/09 | 1 | 2.950 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00084 | No | No | |
| ASBESTOS-ST5-5/26/09 | 030913194-0004 | Firehouse #10 (roof level) | 5/26/09 | 1 | 3.030 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00081 | No | No | |
| ASBESTOS-ST10-5/26/09 | 030913194-0005 | North Side Sidewalk Bridge | 5/26/09 | 1 | 2.980 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00083 | No | No | |
| ASBESTOS-ST11-5/26/09 | 030913194-0006 | 90 Trinity Place (roof level) | 5/26/09 | 1 | 2.990 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00083 | No | No | |
| ASBESTOS-ST12-5/26/09 | 030913194-0007 | 110 Greenwich Street (roof level) | 5/26/09 | 1 | 3.050 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00081 | No | No | |
| ASBESTOS-ST13-5/26/09 | 030913194-0008 | Marriott Hotel, 38th Floor (roof level) | 5/26/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00082 | No | No | |
| ASBESTOS-ST14-5/26/09 | 030913194-0009 | West Face - South end at corner (scaffolding level) | 5/26/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00081 | No | No | |
| ASBESTOS-ST15-5/26/09 | 030913194-0010 | South Face - East end at corner (scaffolding level) | 5/26/09 | 1 | 3.050 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00081 | No | No | |
| ASBESTOS-ST16-5/26/09 | 030913194-0011 | East Face - North end at corner (scaffolding level) | 5/26/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00080 | No | No | |
| ASBESTOS-ST17-5/26/09 | 030913194-0012 | North Face - West end at corner (scaffolding level) | 5/26/09 | 1 | 3.050 | Asbestos | PCME | EMSL | 5/27/09 | < 0.00081 | No | No | |
| ASBESTOS-ST1-5/27/09 | 030913291-0001 | Southwest Area (sidewalk bridge level) | 5/27/09 | 1 | 3.140 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00079 | No | No | |
| ASBESTOS-ST2-5/27/09 | 030913291-0002 | Southeast Area (sidewalk bridge level) | 5/27/09 | 1 | 3.140 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00079 | No | No | |
| ASBESTOS-ST4-5/27/09 | 030913291-0003 | Northwest Area (street-level) | 5/27/09 | 1 | 3.090 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00080 | No | No | |
| ASBESTOS-ST5-5/27/09 | 030913291-0004 | Firehouse #10 (roof level) | 5/27/09 | 1 | 3.020 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00082 | No | No | |
| ASBESTOS-ST10-5/27/09 | 030913291-0005 | North Side Sidewalk Bridge | 5/27/09 | 1 | 3.020 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00082 | No | No | |
| ASBESTOS-ST11-5/27/09 | 030913291-0006 | 90 Trinity Place (roof level) | 5/27/09 | 1 | 3.060 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00081 | No | No | |
| ASBESTOS-ST12-5/27/09 | 030913291-0007 | 110 Greenwich Street (roof level) | 5/27/09 | 1 | 3.120 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00079 | No | No | |
| ASBESTOS-ST13-5/27/09 | 030913291-0008 | Marriott Hotel, 38th Floor (roof level) | 5/27/09 | 1 | 3.030 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00081 | No | No | |
| ASBESTOS-ST14-5/27/09 | 030913291-0009 | West Face - South end at corner (scaffolding level) | 5/27/09 | 1 | 3.140 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00079 | No | No | |
| ASBESTOS-ST15-5/27/09 | 030913291-0010 | South Face - East end at corner (scaffolding level) | 5/27/09 | 1 | 2.990 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00083 | No | No | |
| ASBESTOS-ST16-5/27/09 | 030913291-0011 | East Face - North end at corner (scaffolding level) | 5/27/09 | 1 | 3.110 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00079 | No | No | |
| ASBESTOS-ST17-5/27/09 | 030913291-0012 | North Face - West end at corner (scaffolding level) | 5/27/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 5/28/09 | < 0.00080 | No | No | |
| ASBESTOS-ST1-5/28/09 | 030913388-0001 | Southwest Area (sidewalk bridge level) | 5/28/09 | 1 | 3.160 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00085 | No | No | |
| ASBESTOS-ST2-5/28/09 | 030913388-0002 | Southeast Area (sidewalk bridge level) | 5/28/09 | 1 | 3.150 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00085 | No | No | |
| ASBESTOS-ST4-5/28/09 | 030913388-0003 | Northwest Area (street-level) | 5/28/09 | 1 | 2.950 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00084 | No | No | |
| ASBESTOS-ST5-5/28/09 | 030913388-0004 | Firehouse #10 (roof level) | 5/28/09 | 1 | 3.050 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00081 | No | No | |
| ASBESTOS-ST10-5/28/09 | 030913388-0005 | North Side Sidewalk Bridge | 5/28/09 | 1 | 2.930 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00084 | No | No | |
| ASBESTOS-ST100-5/28/09 | 030913388-0013 | Station 10 Field Duplicate | 5/28/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00081 | No | No | |
| ASBESTOS-ST11-5/28/09 | 030913388-0006 | 90 Trinity Place (roof level) | 5/28/09 | 1 | 3.020 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00082 | No | No | |
| ASBESTOS-ST12-5/28/09 | 030913388-0007 | 110 Greenwich Street (roof level) | 5/28/09 | 1 | 3.090 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00087 | No | No | |
| ASBESTOS-ST13-5/28/09 | 030913388-0008 | Marriott Hotel, 38th Floor (roof level) | 5/28/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00082 | No | No | |
| ASBESTOS-ST14-5/28/09 | 030913388-0009 | West Face - South end at corner (scaffolding level) | 5/28/09 | 1 | 3.070 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00088 | No | No | |
| ASBESTOS-ST15-5/28/09 | 030913388-0010 | South Face - East end at corner (scaffolding level) | 5/28/09 | 1 | 2.980 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00083 | No | No | |
| ASBESTOS-ST16-5/28/09 | 030913388-0011 | East Face - North end at corner (scaffolding level) | 5/28/09 | 1 | 2.990 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00083 | No | No | |
| ASBESTOS-ST17-5/28/09 | 030913388-0012 | North Face - West end at corner (scaffolding level) | 5/28/09 | 1 | 3.120 | Asbestos | PCME | EMSL | 5/29/09 | < 0.00086 | No | No | |
| ASBESTOS-ST1-5/29/09 | 030913487-0001 | Southwest Area (sidewalk bridge level) | 5/29/09 | 1 | 3.090 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00087 | No | No | |
| ASBESTOS-ST2-5/29/09 | 030913487-0002 | Southeast Area (sidewalk bridge level) | 5/29/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00087 | No | No | |
| ASBESTOS-ST4-5/29/09 | 030913487-0003 | Northwest Area (street-level) | 5/29/09 | 1 | 3.020 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00082 | No | No | |
| ASBESTOS-ST5-5/29/09 | 030913487-0004 | Firehouse #10 (roof level) | 5/29/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00081 | No | No | |
| ASBESTOS-ST10-5/29/09 | 030913487-0005 | North Side Sidewalk Bridge | 5/29/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00082 | No | No | |
| ASBESTOS-ST11-5/29/09 | 030913487-0006 | 90 Trinity Place (roof level) | 5/29/09 | 1 | 2.980 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00083 | No | No | |
| ASBESTOS-ST12-5/29/09 | 030913487-0007 | 110 Greenwich Street (roof level) | 5/29/09 | 1 | 2.980 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00083 | No | No | |
| ASBESTOS-ST13-5/29/09 | 030913487-0008 | Marriott Hotel, 38th Floor (roof level) | 5/29/09 | 1 | 3.050 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00081 | No | No | |
| ASBESTOS-ST14-5/29/09 | 030913487-0009 | West Face - South end at corner (scaffolding level) | 5/29/09 | 1 | 2.930 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00084 | No | No | |
| ASBESTOS-ST15-5/29/09 | 030913487-0010 | South Face - East end at corner (scaffolding level) | 5/29/09 | 1 | 2.940 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00084 | No | No | |
| ASBESTOS-ST16-5/29/09 | 030913487-0011 | East Face - North end at corner (scaffolding level) | 5/29/09 | 1 | 2.890 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00085 | No | No | |
| ASBESTOS-ST17-5/29/09 | 030913487-0012 | North Face - West end at corner (scaffolding level) | 5/29/09 | 1 | 2.900 | Asbestos | PCME | EMSL | 5/30/09 | < 0.00085 | No | No | |