

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-6/2/09	030913775-0001	Southwest Area (sidewalk bridge level)	6/2/09	1	3.040	Asbestos	PCME	EMSL	6/3/09	< 0.00081	No	No	
ASBESTOS-ST2-6/2/09	030913775-0002	Southeast Area (sidewalk bridge level)	6/2/09	1	3.180	Asbestos	PCME	EMSL	6/3/09	< 0.00078	No	No	
ASBESTOS-ST4-6/2/09	030913775-0003	Northwest Area (street-level)	6/2/09	1	3.020	Asbestos	PCME	EMSL	6/3/09	< 0.00082	No	No	
ASBESTOS-ST5-6/2/09	030913775-0004	Firehouse #10 (roof level)	6/2/09	1	2.970	Asbestos	PCME	EMSL	6/3/09	< 0.00083	No	No	
ASBESTOS-ST10-6/2/09	030913775-0005	North Side Sidewalk Bridge	6/2/09	1	3.010	Asbestos	PCME	EMSL	6/3/09	< 0.00082	No	No	
ASBESTOS-ST11-6/2/09	030913775-0006	90 Trinity Place (roof level)	6/2/09	1	3.030	Asbestos	PCME	EMSL	6/3/09	< 0.00081	No	No	
ASBESTOS-ST12-6/2/09	030913775-0007	110 Greenwich Street (roof level)	6/2/09	1	3.000	Asbestos	PCME	EMSL	6/3/09	< 0.00082	No	No	
ASBESTOS-ST13-6/2/09	030913775-0008	Marriott Hotel, 38th Floor (roof level)	6/2/09	1	3.150	Asbestos	PCME	EMSL	6/3/09	< 0.00078	No	No	
ASBESTOS-ST1-6/3/09	030913872-0001	Southwest Area (sidewalk bridge level)	6/3/09	1	3.100	Asbestos	PCME	EMSL	6/4/09	< 0.00087	No	No	
ASBESTOS-ST2-6/3/09	030913872-0002	Southeast Area (sidewalk bridge level)	6/3/09	1	3.080	Asbestos	PCME	EMSL	6/4/09	< 0.00087	No	No	
ASBESTOS-ST4-6/3/09	030913872-0003	Northwest Area (street-level)	6/3/09	1	3.040	Asbestos	PCME	EMSL	6/4/09	< 0.00081	No	No	
ASBESTOS-ST5-6/3/09	030913872-0004	Firehouse #10 (roof level)	6/3/09	1	3.050	Asbestos	PCME	EMSL	6/4/09	< 0.00081	No	No	
ASBESTOS-ST10-6/3/09	030913872-0005	North Side Sidewalk Bridge	6/3/09	1	2.960	Asbestos	PCME	EMSL	6/4/09	< 0.00083	No	No	
ASBESTOS-ST11-6/3/09	030913872-0006	90 Trinity Place (roof level)	6/3/09	1	3.070	Asbestos	PCME	EMSL	6/4/09	< 0.00088	No	No	
ASBESTOS-ST12-6/3/09	030913872-0007	110 Greenwich Street (roof level)	6/3/09	1	3.080	Asbestos	PCME	EMSL	6/4/09	< 0.00087	No	No	
ASBESTOS-ST13-6/3/09	030913872-0008	Marriott Hotel, 38th Floor (roof level)	6/3/09	1	3.040	Asbestos	PCME	EMSL	6/4/09	< 0.00081	No	No	
ASBESTOS-ST1-6/4/09	030913958-0001	Southwest Area (sidewalk bridge level)	6/4/09	1	3.050	Asbestos	PCME	EMSL	6/5/09	< 0.00081	No	No	
ASBESTOS-ST2-6/4/09	030913958-0002	Southeast Area (sidewalk bridge level)	6/4/09	1	3.030	Asbestos	PCME	EMSL	6/5/09	< 0.00081	No	No	
ASBESTOS-ST4-6/4/09	030913958-0003	Northwest Area (street-level)	6/4/09	1	2.980	Asbestos	PCME	EMSL	6/5/09	< 0.00083	No	No	
ASBESTOS-ST5-6/4/09	030913958-0004	Firehouse #10 (roof level)	6/4/09	1	3.010	Asbestos	PCME	EMSL	6/5/09	< 0.00082	No	No	
ASBESTOS-ST10-6/4/09	030913958-0005	North Side Sidewalk Bridge	6/4/09	1	2.990	Asbestos	PCME	EMSL	6/5/09	< 0.00083	No	No	
ASBESTOS-ST11-6/4/09	030913958-0006	90 Trinity Place (roof level)	6/4/09	1	2.930	Asbestos	PCME	EMSL	6/5/09	< 0.00084	No	No	
ASBESTOS-ST12-6/4/09	030913958-0007	110 Greenwich Street (roof level)	6/4/09	1	3.050	Asbestos	PCME	EMSL	6/5/09	< 0.00081	No	No	
ASBESTOS-ST13-6/4/09	030913958-0008	Marriott Hotel, 38th Floor (roof level)	6/4/09	1	3.040	Asbestos	PCME	EMSL	6/5/09	< 0.00081	No	No	
ASBESTOS-ST1-6/5/09	030913993-0001	Southwest Area (sidewalk bridge level)	6/5/09	1	2.940	Asbestos	PCME	EMSL	6/6/09	< 0.00084	No	No	
ASBESTOS-ST2-6/5/09	030913993-0002	Southeast Area (sidewalk bridge level)	6/5/09	1	2.910	Asbestos	PCME	EMSL	6/6/09	< 0.00085	No	No	
ASBESTOS-ST4-6/5/09	030913993-0003	Northwest Area (street-level)	6/5/09	1	2.960	Asbestos	PCME	EMSL	6/6/09	< 0.00083	No	No	
ASBESTOS-ST5-6/5/09	030913993-0004	Firehouse #10 (roof level)	6/5/09	1	3.080	Asbestos	PCME	EMSL	6/6/09	< 0.00080	No	No	
ASBESTOS-ST10-6/5/09	030913993-0005	North Side Sidewalk Bridge	6/5/09	1	2.930	Asbestos	PCME	EMSL	6/6/09	< 0.00084	No	No	
ASBESTOS-ST100-6/5/09	030913993-0009	Station 10 Field Duplicate	6/5/09	1	3.000	Asbestos	PCME	EMSL	6/6/09	< 0.00082	No	No	
ASBESTOS-ST11-6/5/09	030913993-0006	90 Trinity Place (roof level)	6/5/09	1	2.940	Asbestos	PCME	EMSL	6/6/09	< 0.00084	No	No	
ASBESTOS-ST12-6/5/09	030913993-0007	110 Greenwich Street (roof level)	6/5/09	1	2.930	Asbestos	PCME	EMSL	6/6/09	< 0.00084	No	No	
ASBESTOS-ST13-6/5/09	030913993-0008	Marriott Hotel, 38th Floor (roof level)	6/5/09	1	3.050	Asbestos	PCME	EMSL	6/6/09	< 0.00081	No	No	