

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments	
										<b>0.0009</b>	Air Quality Levels	Site Specific Trigger Levels		
										<b>NA</b>				
<b>Target Air Quality Levels</b>														
<b>EPA Site Specific Trigger Levels</b>														
ASBESTOS-ST1-6/13/06	030618088-0001	Southwest Area (sidewalk bridge level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST2-6/13/06	030618088-0002	Southeast Area (sidewalk bridge level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST4-6/13/06	030618088-0003	Northwest Area (street-level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST5-6/13/06	030618088-0004	Firehouse #10 (roof level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST10-6/13/06	030618088-0005	North Side Sidewalk Bridge	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST11-6/13/06	030618088-0006	90 Trinity Place (roof level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST12-6/13/06	030618088-0007	110 Greenwich Street (roof level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST13-6/13/06	030618088-0008	Marriott Hotel, 38th Floor (roof level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST14-6/13/06	030618088-0009	West Face - South end at corner (scaffolding level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST15-6/13/06	030618088-0010	South Face - East end at corner (scaffolding level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST16-6/13/06	030618088-0011	East Face - North end at corner (scaffolding level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST17-6/13/06	030618088-0012	North Face - West end at corner (scaffolding level)	6/13/06	1	2.970	Asbestos	PCME	EMSL	6/14/06	< 0.00083	No	No		
ASBESTOS-ST1-6/14/06	030618231-0001	Southwest Area (sidewalk bridge level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST2-6/14/06	030618231-0002	Southeast Area (sidewalk bridge level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST4-6/14/06	030618231-0003	Northwest Area (street-level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST5-6/14/06	030618231-0004	Firehouse #10 (roof level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST10-6/14/06	030618231-0005	North Side Sidewalk Bridge	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST11-6/14/06	030618231-0006	90 Trinity Place (roof level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST12-6/14/06	030618231-0007	110 Greenwich Street (roof level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST13-6/14/06	030618231-0008	Marriott Hotel, 38th Floor (roof level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST14-6/14/06	030618231-0009	West Face - South end at corner (scaffolding level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST15-6/14/06	030618231-0010	South Face - East end at corner (scaffolding level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST16-6/14/06	030618231-0011	East Face - North end at corner (scaffolding level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		
ASBESTOS-ST17-6/14/06	030618231-0012	North Face - West end at corner (scaffolding level)	6/14/06	1	2.940	Asbestos	PCME	EMSL	6/15/06	< 0.00084	No	No		