

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>										<b>0.0009</b>			
<b>EPA Site Specific Trigger Levels</b>										<b>NA</b>			
ASBESTOS-ST1-6/17/09	030915076-0001	Southwest Area (sidewalk bridge level)	6/17/09	1	3.070	Asbestos	PCME	EMSL	6/18/09	< 0.00080	No	No	
ASBESTOS-ST2-6/17/09	030915076-0002	Southeast Area (sidewalk bridge level)	6/17/09	1	3.010	Asbestos	PCME	EMSL	6/18/09	< 0.00082	No	No	
ASBESTOS-ST4-6/17/09	030915076-0003	Northwest Area (street-level)	6/17/09	1	3.050	Asbestos	PCME	EMSL	6/18/09	< 0.00081	No	No	
ASBESTOS-ST5-6/17/09	030915076-0004	Firehouse #10 (roof level)	6/17/09	1	3.040	Asbestos	PCME	EMSL	6/18/09	< 0.00081	No	No	
ASBESTOS-ST10-6/17/09	030915076-0005	North Side Sidewalk Bridge	6/17/09	1	3.010	Asbestos	PCME	EMSL	6/18/09	< 0.00082	No	No	
ASBESTOS-ST11-6/17/09	030915076-0006	90 Trinity Place (roof level)	6/17/09	1	3.040	Asbestos	PCME	EMSL	6/18/09	< 0.00081	No	No	
ASBESTOS-ST12-6/17/09	030915076-0007	110 Greenwich Street (roof level)	6/17/09	1	3.070	Asbestos	PCME	EMSL	6/18/09	< 0.00080	No	No	
ASBESTOS-ST13-6/17/09	030915076-0008	Marriott Hotel, 38th Floor (roof level)	6/17/09	1	3.120	Asbestos	PCME	EMSL	6/18/09	< 0.00079	No	No	
ASBESTOS-ST1-6/18/09	030915182-0001	Southwest Area (sidewalk bridge level)	6/18/09	1	3.000	Asbestos	PCME	EMSL	6/19/09	< 0.00082	No	No	
ASBESTOS-ST2-6/18/09	030915182-0002	Southeast Area (sidewalk bridge level)	6/18/09	1	3.040	Asbestos	PCME	EMSL	6/19/09	< 0.00081	No	No	
ASBESTOS-ST4-6/18/09	030915182-0003	Northwest Area (street-level)	6/18/09	1	3.210	Asbestos	PCME	EMSL	6/19/09	< 0.00084	No	No	
ASBESTOS-ST5-6/18/09	030915182-0004	Firehouse #10 (roof level)	6/18/09	1	3.110	Asbestos	PCME	EMSL	6/19/09	< 0.00087	No	No	
ASBESTOS-ST10-6/18/09	030915182-0005	North Side Sidewalk Bridge	6/18/09	1	2.990	Asbestos	PCME	EMSL	6/19/09	< 0.00083	No	No	
ASBESTOS-ST11-6/18/09	030915182-0006	90 Trinity Place (roof level)	6/18/09	1	3.050	Asbestos	PCME	EMSL	6/19/09	< 0.00081	No	No	
ASBESTOS-ST12-6/18/09	030915182-0007	110 Greenwich Street (roof level)	6/18/09	1	3.180	Asbestos	PCME	EMSL	6/19/09	< 0.00085	No	No	
ASBESTOS-ST13-6/18/09	030915182-0008	Marriott Hotel, 38th Floor (roof level)	6/18/09	1	3.020	Asbestos	PCME	EMSL	6/19/09	< 0.00082	No	No	
ASBESTOS-ST1-6/19/09	030915259-0001	Southwest Area (sidewalk bridge level)	6/19/09	1	3.010	Asbestos	PCME	EMSL	6/20/09	< 0.00082	No	No	
ASBESTOS-ST2-6/19/09	030915259-0002	Southeast Area (sidewalk bridge level)	6/19/09	1	2.940	Asbestos	PCME	EMSL	6/20/09	< 0.00084	No	No	
ASBESTOS-ST4-6/19/09	030915259-0003	Northwest Area (street-level)	6/19/09	1	3.090	Asbestos	PCME	EMSL	6/20/09	< 0.00087	No	No	
ASBESTOS-ST5-6/19/09	030915259-0004	Firehouse #10 (roof level)	6/19/09	1	3.090	Asbestos	PCME	EMSL	6/20/09	< 0.00087	No	No	
ASBESTOS-ST10-6/19/09	030915259-0005	North Side Sidewalk Bridge	6/19/09	1	2.990	Asbestos	PCME	EMSL	6/20/09	< 0.00083	No	No	
ASBESTOS-ST11-6/19/09	030915259-0006	90 Trinity Place (roof level)	6/19/09	1	3.110	Asbestos	PCME	EMSL	6/20/09	< 0.00087	No	No	
ASBESTOS-ST12-6/19/09	030915259-0007	110 Greenwich Street (roof level)	6/19/09	1	3.030	Asbestos	PCME	EMSL	6/20/09	< 0.00081	No	No	
ASBESTOS-ST13-6/19/09	030915259-0008	Marriott Hotel, 38th Floor (roof level)	6/19/09	1	3.120	Asbestos	PCME	EMSL	6/20/09	< 0.00086	No	No	