

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-6/24/08	030820047-0001	Southwest Area (sidewalk bridge level)	6/24/08	1	3.210	Asbestos	PCME	EMSL	6/25/08	< 0.00084	No	No	
ASBESTOS-ST2-6/24/08	030820047-0002	Southeast Area (sidewalk bridge level)	6/24/08	1	3.050	Asbestos	PCME	EMSL	6/25/08	< 0.00081	No	No	
ASBESTOS-ST4-6/24/08	030820047-0003	Northwest Area (street-level)	6/24/08	1	3.030	Asbestos	PCME	EMSL	6/25/08	< 0.00081	No	No	
ASBESTOS-ST5-6/24/08	030820047-0004	Firehouse #10 (roof level)	6/24/08	1	3.070	Asbestos	PCME	EMSL	6/25/08	< 0.00080	No	No	
ASBESTOS-ST10-6/24/08	030820047-0005	North Side Sidewalk Bridge	6/24/08	1	2.940	Asbestos	PCME	EMSL	6/25/08	< 0.00084	No	No	
ASBESTOS-ST11-6/24/08	030820047-0006	90 Trinity Place (roof level)	6/24/08	1	3.010	Asbestos	PCME	EMSL	6/25/08	< 0.00082	No	No	
ASBESTOS-ST12-6/24/08	030820047-0007	110 Greenwich Street (roof level)	6/24/08	1	3.060	Asbestos	PCME	EMSL	6/25/08	< 0.00081	No	No	
ASBESTOS-ST13-6/24/08	030820047-0008	Marriott Hotel, 38th Floor (roof level)	6/24/08	1	3.010	Asbestos	PCME	EMSL	6/25/08	< 0.00082	No	No	
ASBESTOS-ST14-6/24/08	030820047-0009	West Face - South end at corner (scaffolding level)	6/24/08	1	3.030	Asbestos	PCME	EMSL	6/25/08	< 0.00081	No	No	
ASBESTOS-ST15-6/24/08	030820047-0010	South Face - East end at corner (scaffolding level)	6/24/08	1	2.990	Asbestos	PCME	EMSL	6/25/08	< 0.00083	No	No	
ASBESTOS-ST16-6/24/08	030820047-0011	East Face - North end at corner (scaffolding level)	6/24/08	1	3.010	Asbestos	PCME	EMSL	6/25/08	< 0.00082	No	No	
ASBESTOS-ST17-6/24/08	030820047-0012	North Face - West end at corner (scaffolding level)	6/24/08	1	3.000	Asbestos	PCME	EMSL	6/25/08	< 0.00082	No	No	
ASBESTOS-ST1-6/25/08	030820230-0001	Southwest Area (sidewalk bridge level)	6/25/08	1	3.010	Asbestos	PCME	EMSL	6/26/08	< 0.00082	No	No	
ASBESTOS-ST2-6/25/08	030820230-0002	Southeast Area (sidewalk bridge level)	6/25/08	1	3.040	Asbestos	PCME	EMSL	6/26/08	< 0.00081	No	No	
ASBESTOS-ST4-6/25/08	030820230-0003	Northwest Area (street-level)	6/25/08	1	3.110	Asbestos	PCME	EMSL	6/26/08	< 0.00079	No	No	
ASBESTOS-ST5-6/25/08	030820230-0004	Firehouse #10 (roof level)	6/25/08	1	3.010	Asbestos	PCME	EMSL	6/26/08	< 0.00082	No	No	
ASBESTOS-ST10-6/25/08	030820230-0005	North Side Sidewalk Bridge	6/25/08	1	3.030	Asbestos	PCME	EMSL	6/26/08	< 0.00081	No	No	
ASBESTOS-ST11-6/25/08	030820230-0006	90 Trinity Place (roof level)	6/25/08	1	3.100	Asbestos	PCME	EMSL	6/26/08	< 0.00080	No	No	
ASBESTOS-ST12-6/25/08	030820230-0007	110 Greenwich Street (roof level)	6/25/08	1	3.010	Asbestos	PCME	EMSL	6/26/08	< 0.00082	No	No	
ASBESTOS-ST13-6/25/08	030820230-0008	Marriott Hotel, 38th Floor (roof level)	6/25/08	1	3.120	Asbestos	PCME	EMSL	6/26/08	< 0.00079	No	No	
ASBESTOS-ST14-6/25/08	030820230-0009	West Face - South end at corner (scaffolding level)	6/25/08	1	3.070	Asbestos	PCME	EMSL	6/26/08	< 0.00080	No	No	
ASBESTOS-ST15-6/25/08	030820230-0010	South Face - East end at corner (scaffolding level)	6/25/08	1	3.010	Asbestos	PCME	EMSL	6/26/08	< 0.00082	No	No	
ASBESTOS-ST16-6/25/08	030820230-0011	East Face - North end at corner (scaffolding level)	6/25/08	1	3.160	Asbestos	PCME	EMSL	6/26/08	< 0.00078	No	No	
ASBESTOS-ST17-6/25/08	030820230-0012	North Face - West end at corner (scaffolding level)	6/25/08	1	2.990	Asbestos	PCME	EMSL	6/26/08	< 0.00083	No	No	
ASBESTOS-ST1-6/26/08	030820314-0001	Southwest Area (sidewalk bridge level)	6/26/08	1	3.060	Asbestos	PCME	EMSL	6/27/08	< 0.00081	No	No	
ASBESTOS-ST2-6/26/08	030820314-0002	Southeast Area (sidewalk bridge level)	6/26/08	1	3.090	Asbestos	PCME	EMSL	6/27/08	< 0.00080	No	No	
ASBESTOS-ST4-6/26/08	030820314-0003	Northwest Area (street-level)	6/26/08	1	3.060	Asbestos	PCME	EMSL	6/27/08	< 0.00081	No	No	
ASBESTOS-ST5-6/26/08	030820314-0004	Firehouse #10 (roof level)	6/26/08	1	2.990	Asbestos	PCME	EMSL	6/27/08	< 0.00083	No	No	
ASBESTOS-ST10-6/26/08	030820314-0005	North Side Sidewalk Bridge	6/26/08	1	2.980	Asbestos	PCME	EMSL	6/27/08	< 0.00083	No	No	
ASBESTOS-ST11-6/26/08	030820314-0006	90 Trinity Place (roof level)	6/26/08	1	3.050	Asbestos	PCME	EMSL	6/27/08	< 0.00081	No	No	
ASBESTOS-ST12-6/26/08	030820314-0007	110 Greenwich Street (roof level)	6/26/08	1	3.060	Asbestos	PCME	EMSL	6/27/08	< 0.00081	No	No	
ASBESTOS-ST13-6/26/08	030820314-0008	Marriott Hotel, 38th Floor (roof level)	6/26/08	1	2.970	Asbestos	PCME	EMSL	6/27/08	< 0.00083	No	No	
ASBESTOS-ST14-6/26/08	030820314-0009	West Face - South end at corner (scaffolding level)	6/26/08	1	2.970	Asbestos	PCME	EMSL	6/27/08	< 0.00083	No	No	
ASBESTOS-ST15-6/26/08	030820314-0010	South Face - East end at corner (scaffolding level)	6/26/08	1	3.020	Asbestos	PCME	EMSL	6/27/08	< 0.00082	No	No	
ASBESTOS-ST16-6/26/08	030820314-0011	East Face - North end at corner (scaffolding level)	6/26/08	1	3.040	Asbestos	PCME	EMSL	6/27/08	< 0.00081	No	No	
ASBESTOS-ST17-6/26/08	030820314-0012	North Face - West end at corner (scaffolding level)	6/26/08	1	3.040	Asbestos	PCME	EMSL	6/27/08	< 0.00081	No	No	
ASBESTOS-ST1-6/27/08	030820539-0001	Southwest Area (sidewalk bridge level)	6/27/08	1	3.120	Asbestos	PCME	EMSL	6/28/08	< 0.00079	No	No	
ASBESTOS-ST2-6/27/08	030820539-0002	Southeast Area (sidewalk bridge level)	6/27/08	1	3.110	Asbestos	PCME	EMSL	6/28/08	< 0.00079	No	No	
ASBESTOS-ST4-6/27/08	030820539-0003	Northwest Area (street-level)	6/27/08	1	3.050	Asbestos	PCME	EMSL	6/28/08	< 0.00081	No	No	
ASBESTOS-ST5-6/27/08	030820539-0004	Firehouse #10 (roof level)	6/27/08	1	3.020	Asbestos	PCME	EMSL	6/28/08	< 0.00082	No	No	
ASBESTOS-ST10-6/27/08	030820539-0005	North Side Sidewalk Bridge	6/27/08	1	3.020	Asbestos	PCME	EMSL	6/28/08	< 0.00082	No	No	
ASBESTOS-ST11-6/27/08	030820539-0006	90 Trinity Place (roof level)	6/27/08	1	3.040	Asbestos	PCME	EMSL	6/28/08	< 0.00081	No	No	
ASBESTOS-ST12-6/27/08	030820539-0007	110 Greenwich Street (roof level)	6/27/08	1	3.000	Asbestos	PCME	EMSL	6/28/08	< 0.00082	No	No	
ASBESTOS-ST13-6/27/08	030820539-0008	Marriott Hotel, 38th Floor (roof level)	6/27/08	1	3.000	Asbestos	PCME	EMSL	6/28/08	< 0.00082	No	No	
ASBESTOS-ST14-6/27/08	030820539-0009	West Face - South end at corner (scaffolding level)	6/27/08	1	3.010	Asbestos	PCME	EMSL	6/28/08	< 0.00082	No	No	
ASBESTOS-ST15-6/27/08	030820539-0010	South Face - East end at corner (scaffolding level)	6/27/08	1	3.050	Asbestos	PCME	EMSL	6/28/08	< 0.00081	No	No	
ASBESTOS-ST16-6/27/08	030820539-0011	East Face - North end at corner (scaffolding level)	6/27/08	1	3.010	Asbestos	PCME	EMSL	6/28/08	< 0.00082	No	No	
ASBESTOS-ST17-6/27/08	030820539-0012	North Face - West end at corner (scaffolding level)	6/27/08	1	3.020	Asbestos	PCME	EMSL	6/28/08	< 0.00082	No	No	
ASBESTOS-ST1-6/28/08	030820739-0001	Southwest Area (sidewalk bridge level)	6/28/08	1	2.980	Asbestos	PCME	EMSL	6/30/08	< 0.00083	No	No	
ASBESTOS-ST2-6/28/08	030820739-0002	Southeast Area (sidewalk bridge level)	6/28/08	1	2.910	Asbestos	PCME	EMSL	6/30/08	< 0.00085	No	No	
ASBESTOS-ST4-6/28/08	030820739-0003	Northwest Area (street-level)	6/28/08	1	3.090	Asbestos	PCME	EMSL	6/30/08	< 0.00080	No	No	
ASBESTOS-ST5-6/28/08	030820739-0004	Firehouse #10 (roof level)	6/28/08	1	3.040	Asbestos	PCME	EMSL	6/30/08	< 0.00081	No	No	
ASBESTOS-ST10-6/28/08	030820739-0005	North Side Sidewalk Bridge	6/28/08	1	3.070	Asbestos	PCME	EMSL	6/30/08	< 0.00080	No	No	
ASBESTOS-ST11-6/28/08	030820739-0006	90 Trinity Place (roof level)	6/28/08	1	3.040	Asbestos	PCME	EMSL	6/30/08	< 0.00081	No	No	
ASBESTOS-ST12-6/28/08	030820739-0007	110 Greenwich Street (roof level)	6/28/08	1	3.040	Asbestos	PCME	EMSL	6/30/08	< 0.00081	No	No	
ASBESTOS-ST13-6/28/08	030820739-0008	Marriott Hotel, 38th Floor (roof level)	6/28/08	1	3.000	Asbestos	PCME	EMSL	6/30/08	< 0.00082	No	No	
ASBESTOS-ST14-6/28/08	030820739-0009	West Face - South end at corner (scaffolding level)	6/28/08	1	3.000	Asbestos	PCME	EMSL	6/30/08	< 0.00082	No	No	
ASBESTOS-ST15-6/28/08	030820739-0010	South Face - East end at corner (scaffolding level)	6/28/08	1	3.040	Asbestos	PCME	EMSL	6/30/08	< 0.00081	No	No	
ASBESTOS-ST16-6/28/08	030820739-0011	East Face - North end at corner (scaffolding level)	6/28/08	1	3.060	Asbestos	PCME	EMSL	6/30/08	< 0.00081	No	No	
ASBESTOS-ST17-6/28/08	030820739-0012	North Face - West end at corner (scaffolding level)	6/28/08	1	3.010	Asbestos	PCME	EMSL	6/30/08	< 0.00082	No	No	
ASBESTOS-ST1-6/29/08	030820740-0001	Southwest Area (sidewalk bridge level)	6/29/08	1	3.120	Asbestos	PCME	EMSL	6/30/08	< 0.00079	No	No	
ASBESTOS-ST2-6/29/08	030820740-0002	Southeast Area (sidewalk bridge level)	6/29/08	1	3.110	Asbestos	PCME	EMSL	6/30/08	< 0.00079	No	No	
ASBESTOS-ST4-6/29/08	030820740-0003	Northwest Area (street-level)	6/29/08	1	3.150	Asbestos	PCME	EMSL	6/30/08	< 0.00078	No	No	
ASBESTOS-ST5-6/29/08	030820740-0004	Firehouse #10 (roof level)	6/29/08	1	3.110	Asbestos	PCME	EMSL	6/30/08	< 0.00079	No	No	
ASBESTOS-ST10-6/29/08	030820740-0005	North Side Sidewalk Bridge	6/29/08	1	3.010	Asbestos	PCME	EMSL	6/30/08	< 0.00082	No	No	
ASBESTOS-ST11-6/29/08	030820740-0006	90 Trinity Place (roof level)	6/29/08	1	3.000	Asbestos	PCME	EMSL	6/30/08	< 0.00082	No	No	
ASBESTOS-ST12-6/29/08	030820740-0007	110 Greenwich Street (roof level)	6/29/08	1	3.010	Asbestos	PCME	EMSL	6/30/08	< 0.00082	No	No	
ASBESTOS-ST13-6/29/08	030820740-0008	Marriott Hotel, 38th Floor (roof level)	6/29/08	1	3.060	Asbestos	PCME	EMSL	6/30/08	< 0.00081	No	No	
ASBESTOS-ST14-6/29/08	030820740-0009	West Face - South end at corner (scaffolding level)	6/29/08	1	3.110	Asbestos	PCME	EMSL	6/30/08	< 0.00079	No	No	
ASBESTOS-ST15-6/29/08	030820740-0010	South Face - East end at corner (scaffolding level)	6/29/08	1	3.110	Asbestos	PCME	EMSL	6/30/08	< 0.00079	No	No	
ASBESTOS-ST16-6/29/08	030820740-0011	East Face - North end at corner (scaffolding level)	6/29/08	1	3.050	Asbestos	PCME	EMSL	6/30/08	< 0.00081	No	No	
ASBESTOS-ST17-6/29/08	030820740-0012	North Face - West end at corner (scaffolding level)	6/29/08	1	3.060	Asbestos	PCME	EMSL	6/30/08	< 0.00081	No	No	