

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-6/26/09	030915980-0001	Southwest Area (sidewalk bridge level)	6/26/09	1	3.050	Asbestos	PCME	EMSL	6/27/09	< 0.00081	No	No	
ASBESTOS-ST2-6/26/09	030915980-0002	Southeast Area (sidewalk bridge level)	6/26/09	1	3.040	Asbestos	PCME	EMSL	6/27/09	0.00081	No	No	
ASBESTOS-ST4-6/26/09	030915980-0003	Northwest Area (street-level)	6/26/09	1	2.930	Asbestos	PCME	EMSL	6/27/09	0.00084	No	No	
ASBESTOS-ST5-6/26/09	030915980-0004	Firehouse #10 (roof level)	6/26/09	1	2.960	Asbestos	PCME	EMSL	6/27/09	< 0.00083	No	No	
ASBESTOS-ST10-6/26/09	030915980-0005	North Side Sidewalk Bridge	6/26/09	1	3.070	Asbestos	PCME	EMSL	6/27/09	< 0.00088	No	No	
ASBESTOS-ST11-6/26/09	030915980-0006	90 Trinity Place (roof level)	6/26/09	1	3.000	Asbestos	PCME	EMSL	6/27/09	< 0.00082	No	No	
ASBESTOS-ST12-6/26/09	030915980-0007	110 Greenwich Street (roof level)	6/26/09	1	3.060	Asbestos	PCME	EMSL	6/27/09	< 0.00081	No	No	
ASBESTOS-ST13-6/26/09	030915980-0008	Marriott Hotel, 38th Floor (roof level)	6/26/09	1	3.040	Asbestos	PCME	EMSL	6/27/09	< 0.00081	No	No	
ASBESTOS-ST1-6/27/09	030916150-0001	Southwest Area (sidewalk bridge level)	6/27/09	1	3.030	Asbestos	PCME	EMSL	6/29/09	< 0.00081	No	No	
ASBESTOS-ST2-6/27/09	030916150-0002	Southeast Area (sidewalk bridge level)	6/27/09	1	2.980	Asbestos	PCME	EMSL	6/29/09	< 0.00083	No	No	
ASBESTOS-ST4-6/27/09	030916150-0003	Northwest Area (street-level)	6/27/09	1	2.980	Asbestos	PCME	EMSL	6/29/09	< 0.00083	No	No	
ASBESTOS-ST5-6/27/09	030916150-0004	Firehouse #10 (roof level)	6/27/09	1	3.030	Asbestos	PCME	EMSL	6/29/09	< 0.00081	No	No	
ASBESTOS-ST10-6/27/09	030916150-0005	North Side Sidewalk Bridge	6/27/09	1	3.000	Asbestos	PCME	EMSL	6/29/09	< 0.00082	No	No	
ASBESTOS-ST11-6/27/09	030916150-0006	90 Trinity Place (roof level)	6/27/09	1	3.060	Asbestos	PCME	EMSL	6/29/09	< 0.00081	No	No	
ASBESTOS-ST12-6/27/09	030916150-0007	110 Greenwich Street (roof level)	6/27/09	1	3.050	Asbestos	PCME	EMSL	6/29/09	< 0.00081	No	No	
ASBESTOS-ST13-6/27/09	030916150-0008	Marriott Hotel, 38th Floor (roof level)	6/27/09	1	3.060	Asbestos	PCME	EMSL	6/29/09	< 0.00081	No	No	
ASBESTOS-ST1-6/28/09	030916153-0001	Southwest Area (sidewalk bridge level)	6/28/09	1	3.090	Asbestos	PCME	EMSL	6/29/09	< 0.00080	No	No	
ASBESTOS-ST2-6/28/09	030916153-0002	Southeast Area (sidewalk bridge level)	6/28/09	1	3.200	Asbestos	PCME	EMSL	6/29/09	< 0.00077	No	No	
ASBESTOS-ST4-6/28/09	030916153-0003	Northwest Area (street-level)	6/28/09	1	3.080	Asbestos	PCME	EMSL	6/29/09	< 0.00080	No	No	
ASBESTOS-ST5-6/28/09	030916153-0004	Firehouse #10 (roof level)	6/28/09	1	3.120	Asbestos	PCME	EMSL	6/29/09	< 0.00079	No	No	
ASBESTOS-ST10-6/28/09	030916153-0005	North Side Sidewalk Bridge	6/28/09	1	3.100	Asbestos	PCME	EMSL	6/29/09	< 0.00080	No	No	
ASBESTOS-ST11-6/28/09	030916153-0006	90 Trinity Place (roof level)	6/28/09	1	3.100	Asbestos	PCME	EMSL	6/29/09	< 0.00080	No	No	
ASBESTOS-ST12-6/28/09	030916153-0007	110 Greenwich Street (roof level)	6/28/09	1	3.060	Asbestos	PCME	EMSL	6/29/09	< 0.00081	No	No	
ASBESTOS-ST13-6/28/09	030916153-0008	Marriott Hotel, 38th Floor (roof level)	6/28/09	1	3.040	Asbestos	PCME	EMSL	6/29/09	< 0.00081	No	No	