

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-6/29/07	030721643-0001	Southwest Area (sidewalk bridge level)	6/29/07	1	3.040	Asbestos	PCME	EMSL	7/2/07	< 0.00081	No	No	
ASBESTOS-ST2-6/29/07	030721643-0002	Southeast Area (sidewalk bridge level)	6/29/07	1	3.010	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST4-6/29/07	030721643-0003	Northwest Area (street-level)	6/29/07	1	3.010	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST5-6/29/07	030721643-0004	Firehouse #10 (roof level)	6/29/07	1	3.040	Asbestos	PCME	EMSL	7/2/07	< 0.00081	No	No	
ASBESTOS-ST10-6/29/07	030721643-0005	North Side Sidewalk Bridge	6/29/07	1	3.010	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST11-6/29/07	030721643-0006	90 Trinity Place (roof level)	6/29/07	1	3.020	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST12-6/29/07	030721643-0007	110 Greenwich Street (roof level)	6/29/07	1	2.960	Asbestos	PCME	EMSL	7/2/07	< 0.00083	No	No	
ASBESTOS-ST13-6/29/07	030721643-0008	Marriott Hotel, 38th Floor (roof level)	6/29/07	1	3.010	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST14-6/29/07	030721643-0009	West Face - South end at corner (scaffolding level)	6/29/07	1	2.960	Asbestos	PCME	EMSL	7/2/07	< 0.00083	No	No	
ASBESTOS-ST15-6/29/07	030721643-0010	South Face - East end at corner (scaffolding level)	6/29/07	1	2.990	Asbestos	PCME	EMSL	7/2/07	< 0.00083	No	No	
ASBESTOS-ST16-6/29/07	030721643-0011	East Face - North end at corner (scaffolding level)	6/29/07	1	3.010	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST17-6/29/07	030721643-0012	North Face - West end at corner (scaffolding level)	6/29/07	1	3.090	Asbestos	PCME	EMSL	7/2/07	< 0.00080	No	No	
ASBESTOS-ST1-6/30/07	030721644-0001	Southwest Area (sidewalk bridge level)	6/30/07	1	3.010	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST2-6/30/07	030721644-0002	Southeast Area (sidewalk bridge level)	6/30/07	1	2.980	Asbestos	PCME	EMSL	7/2/07	< 0.00083	No	No	
ASBESTOS-ST4-6/30/07	030721644-0003	Northwest Area (street-level)	6/30/07	1	3.040	Asbestos	PCME	EMSL	7/2/07	< 0.00081	No	No	
ASBESTOS-ST5-6/30/07	030721644-0004	Firehouse #10 (roof level)	6/30/07	1	3.010	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST10-6/30/07	030721644-0005	North Side Sidewalk Bridge	6/30/07	1	3.050	Asbestos	PCME	EMSL	7/2/07	< 0.00081	No	No	
ASBESTOS-ST11-6/30/07	030721644-0006	90 Trinity Place (roof level)	6/30/07	1	3.090	Asbestos	PCME	EMSL	7/2/07	< 0.00080	No	No	
ASBESTOS-ST12-6/30/07	030721644-0007	110 Greenwich Street (roof level)	6/30/07	1	2.960	Asbestos	PCME	EMSL	7/2/07	< 0.00083	No	No	
ASBESTOS-ST13-6/30/07	030721644-0008	Marriott Hotel, 38th Floor (roof level)	6/30/07	1	3.010	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST14-6/30/07	030721644-0009	West Face - South end at corner (scaffolding level)	6/30/07	1	2.960	Asbestos	PCME	EMSL	7/2/07	< 0.00083	No	No	
ASBESTOS-ST15-6/30/07	030721644-0010	South Face - East end at corner (scaffolding level)	6/30/07	1	2.940	Asbestos	PCME	EMSL	7/2/07	< 0.00084	No	No	
ASBESTOS-ST16-6/30/07	030721644-0011	East Face - North end at corner (scaffolding level)	6/30/07	1	3.060	Asbestos	PCME	EMSL	7/2/07	< 0.00081	No	No	
ASBESTOS-ST17-6/30/07	030721644-0012	North Face - West end at corner (scaffolding level)	6/30/07	1	3.050	Asbestos	PCME	EMSL	7/2/07	< 0.00081	No	No	
ASBESTOS-ST1-7/1/07	030721645-0001	Southwest Area (sidewalk bridge level)	7/1/07	1	3.030	Asbestos	PCME	EMSL	7/2/07	< 0.00081	No	No	
ASBESTOS-ST2-7/1/07	030721645-0002	Southeast Area (sidewalk bridge level)	7/1/07	1	3.040	Asbestos	PCME	EMSL	7/2/07	< 0.00081	No	No	
ASBESTOS-ST4-7/1/07	030721645-0003	Northwest Area (street-level)	7/1/07	1	3.110	Asbestos	PCME	EMSL	7/2/07	< 0.00079	No	No	
ASBESTOS-ST5-7/1/07	030721645-0004	Firehouse #10 (roof level)	7/1/07	1	3.020	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST10-7/1/07	030721645-0005	North Side Sidewalk Bridge	7/1/07	1	2.950	Asbestos	PCME	EMSL	7/2/07	< 0.00084	No	No	
ASBESTOS-ST11-7/1/07	030721645-0006	90 Trinity Place (roof level)	7/1/07	1	2.960	Asbestos	PCME	EMSL	7/2/07	< 0.00083	No	No	
ASBESTOS-ST12-7/1/07	030721645-0007	110 Greenwich Street (roof level)	7/1/07	1	2.960	Asbestos	PCME	EMSL	7/2/07	< 0.00083	No	No	
ASBESTOS-ST13-7/1/07	030721645-0008	Marriott Hotel, 38th Floor (roof level)	7/1/07	1	3.010	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST14-7/1/07	030721645-0009	West Face - South end at corner (scaffolding level)	7/1/07	1	3.000	Asbestos	PCME	EMSL	7/2/07	< 0.00082	No	No	
ASBESTOS-ST15-7/1/07	030721645-0010	South Face - East end at corner (scaffolding level)	7/1/07	1	3.150	Asbestos	PCME	EMSL	7/2/07	< 0.00078	No	No	
ASBESTOS-ST16-7/1/07	030721645-0011	East Face - North end at corner (scaffolding level)	7/1/07	1	3.090	Asbestos	PCME	EMSL	7/2/07	< 0.00080	No	No	
ASBESTOS-ST17-7/1/07	030721645-0012	North Face - West end at corner (scaffolding level)	7/1/07	1	2.850	Asbestos	PCME	EMSL	7/2/07	< 0.00087	No	No	