

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-7/3/06	030620484-0001	Southwest Area (sidewalk bridge level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST2-7/3/06	030620484-0002	Southeast Area (sidewalk bridge level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST4-7/3/06	030620484-0003	Northwest Area (street-level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST5-7/3/06	030620484-0004	Firehouse #10 (roof level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST10-7/3/06	030620484-0005	North Side Sidewalk Bridge	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST11-7/3/06	030620484-0006	90 Trinity Place (roof level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST12-7/3/06	030620484-0007	110 Greenwich Street (roof level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST13-7/3/06	030620484-0008	Marriott Hotel, 38th Floor (roof level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST14-7/3/06	030620484-0009	West Face - South end at corner (scaffolding level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST15-7/3/06	030620484-0010	South Face - East end at corner (scaffolding level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST16-7/3/06	030620484-0011	East Face - North end at corner (scaffolding level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST17-7/3/06	030620484-0012	North Face - West end at corner (scaffolding level)	7/3/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST1-7/4/06	030620486-0001	Southwest Area (sidewalk bridge level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST2-7/4/06	030620486-0002	Southeast Area (sidewalk bridge level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST4-7/4/06	030620486-0003	Northwest Area (street-level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST5-7/4/06	030620486-0004	Firehouse #10 (roof level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST10-7/4/06	030620486-0005	North Side Sidewalk Bridge	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST11-7/4/06	030620486-0006	90 Trinity Place (roof level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST12-7/4/06	030620486-0007	110 Greenwich Street (roof level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST13-7/4/06	030620486-0008	Marriott Hotel, 38th Floor (roof level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST14-7/4/06	030620486-0009	West Face - South end at corner (scaffolding level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST15-7/4/06	030620486-0010	South Face - East end at corner (scaffolding level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST16-7/4/06	030620486-0011	East Face - North end at corner (scaffolding level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST17-7/4/06	030620486-0012	North Face - West end at corner (scaffolding level)	7/4/06	1	2.940	Asbestos	PCME	EMSL	7/5/06	< 0.00084	No	No	
ASBESTOS-ST1-7/5/06	030620651-0001	Southwest Area (sidewalk bridge level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST2-7/5/06	030620651-0002	Southeast Area (sidewalk bridge level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST4-7/5/06	030620651-0003	Northwest Area (street-level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST5-7/5/06	030620651-0004	Firehouse #10 (roof level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST10-7/5/06	030620651-0005	North Side Sidewalk Bridge	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST100-7/5/06	030620651-0013	Station 10 Field Duplicate	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST11-7/5/06	030620651-0006	90 Trinity Place (roof level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST12-7/5/06	030620651-0007	110 Greenwich Street (roof level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST13-7/5/06	030620651-0008	Marriott Hotel, 38th Floor (roof level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST14-7/5/06	030620651-0009	West Face - South end at corner (scaffolding level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST15-7/5/06	030620651-0010	South Face - East end at corner (scaffolding level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST16-7/5/06	030620651-0011	East Face - North end at corner (scaffolding level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	
ASBESTOS-ST17-7/5/06	030620651-0012	North Face - West end at corner (scaffolding level)	7/5/06	1	2.940	Asbestos	PCME	EMSL	7/6/06	< 0.00084	No	No	