

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality	Exceeds EPA	
EPA Site Specific Trigger Levels										NA	Levels	Site Specific	Trigger Levels
ASBESTOS-ST1-7/14/06	030622009-0001	Southwest Area (sidewalk bridge level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST2-7/14/06	030622009-0002	Southeast Area (sidewalk bridge level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST4-7/14/06	030622009-0003	Northwest Area (street-level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST5-7/14/06	030622009-0004	Firehouse #10 (roof level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST6-7/14/06	030622010-0001	Southwest Area (roof level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST7-7/14/06	030622010-0002	Southeast Area (roof level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST8-7/14/06	030622010-0003	Northeast Area (roof level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST9-7/14/06	030622010-0004	Northwest Area (roof level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST10-7/14/06	030622009-0005	North Side Sidewalk Bridge	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST11-7/14/06	030622009-0006	90 Trinity Place (roof level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST12-7/14/06	030622009-0007	110 Greenwich Street (roof level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST13-7/14/06	030622009-0008	Marriott Hotel, 38th Floor (roof level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST14-7/14/06	030622009-0009	West Face - South end at corner (scaffolding level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST15-7/14/06	030622009-0010	South Face - East end at corner (scaffolding level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST16-7/14/06	030622009-0011	East Face - North end at corner (scaffolding level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST17-7/14/06	030622009-0012	North Face - West end at corner (scaffolding level)	7/14/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST1-7/15/06	030622011-0001	Southwest Area (sidewalk bridge level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST2-7/15/06	030622011-0002	Southeast Area (sidewalk bridge level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST4-7/15/06	030622011-0003	Northwest Area (street-level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST5-7/15/06	030622011-0004	Firehouse #10 (roof level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST6-7/15/06	030622012-0001	Southwest Area (roof level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST7-7/15/06	030622012-0002	Southeast Area (roof level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST8-7/15/06	030622012-0003	Northeast Area (roof level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST9-7/15/06	030622012-0004	Northwest Area (roof level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST10-7/15/06	030622011-0005	North Side Sidewalk Bridge	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST11-7/15/06	030622011-0006	90 Trinity Place (roof level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST12-7/15/06	030622011-0007	110 Greenwich Street (roof level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST13-7/15/06	030622011-0008	Marriott Hotel, 38th Floor (roof level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST14-7/15/06	030622011-0009	West Face - South end at corner (scaffolding level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST15-7/15/06	030622011-0010	South Face - East end at corner (scaffolding level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST16-7/15/06	030622011-0011	East Face - North end at corner (scaffolding level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST17-7/15/06	030622011-0012	North Face - West end at corner (scaffolding level)	7/15/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST1-7/16/06	030622013-0001	Southwest Area (sidewalk bridge level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST2-7/16/06	030622013-0002	Southeast Area (sidewalk bridge level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST4-7/16/06	030622013-0003	Northwest Area (street-level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST5-7/16/06	030622013-0004	Firehouse #10 (roof level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST6-7/16/06	030622014-0001	Southwest Area (roof level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST7-7/16/06	030622014-0002	Southeast Area (roof level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST8-7/16/06	030622014-0003	Northeast Area (roof level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST9-7/16/06	030622014-0004	Northwest Area (roof level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST10-7/16/06	030622013-0005	North Side Sidewalk Bridge	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST11-7/16/06	030622013-0006	90 Trinity Place (roof level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST12-7/16/06	030622013-0007	110 Greenwich Street (roof level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST13-7/16/06	030622013-0008	Marriott Hotel, 38th Floor (roof level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST14-7/16/06	030622013-0009	West Face - South end at corner (scaffolding level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST15-7/16/06	030622013-0010	South Face - East end at corner (scaffolding level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST16-7/16/06	030622013-0011	East Face - North end at corner (scaffolding level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	
ASBESTOS-ST17-7/16/06	030622013-0012	North Face - West end at corner (scaffolding level)	7/16/06	1	2.940	Asbestos	PCME	EMSL	7/17/06	< 0.00084	No	No	