

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-7/17/06	030622221-0001	Southwest Area (sidewalk bridge level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST2-7/17/06	030622221-0002	Southeast Area (sidewalk bridge level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST4-7/17/06	030622221-0003	Northwest Area (street-level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST5-7/17/06	030622221-0004	Firehouse #10 (roof level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST6-7/17/06	030622220-0001	Southwest Area (roof level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST7-7/17/06	030622220-0002	Southeast Area (roof level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST8-7/17/06	030622220-0003	Northeast Area (roof level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST9-7/17/06	030622220-0004	Northwest Area (roof level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST10-7/17/06	030622221-0005	North Side Sidewalk Bridge	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST11-7/17/06	030622221-0006	90 Trinity Place (roof level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST12-7/17/06	030622221-0007	110 Greenwich Street (roof level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST13-7/17/06	030622221-0008	Marriott Hotel, 38th Floor (roof level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST14-7/17/06	030622221-0009	West Face - South end at corner (scaffolding level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST15-7/17/06	030622221-0010	South Face - East end at corner (scaffolding level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST16-7/17/06	030622221-0011	East Face - North end at corner (scaffolding level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST17-7/17/06	030622221-0012	North Face - West end at corner (scaffolding level)	7/17/06	1	2.940	Asbestos	PCME	EMSL	7/18/06	< 0.00084	No	No	
ASBESTOS-ST1-7/18/06	030622380-0001	Southwest Area (sidewalk bridge level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST4-7/18/06	030622380-0002	Northwest Area (street-level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST5-7/18/06	030622380-0003	Firehouse #10 (roof level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST6-7/18/06	030622381-0001	Southwest Area (roof level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST7-7/18/06	030622381-0002	Southeast Area (roof level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST8-7/18/06	030622381-0003	Northeast Area (roof level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST9-7/18/06	030622381-0004	Northwest Area (roof level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST10-7/18/06	030622380-0004	North Side Sidewalk Bridge	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST11-7/18/06	030622380-0005	90 Trinity Place (roof level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST12-7/18/06	030622380-0006	110 Greenwich Street (roof level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST13-7/18/06	030622380-0007	Marriott Hotel, 38th Floor (roof level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST14-7/18/06	030622380-0008	West Face - South end at corner (scaffolding level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST15-7/18/06	030622380-0009	South Face - East end at corner (scaffolding level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST16-7/18/06	030622380-0010	East Face - North end at corner (scaffolding level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	
ASBESTOS-ST17-7/18/06	030622380-0011	North Face - West end at corner (scaffolding level)	7/18/06	1	2.940	Asbestos	PCME	EMSL	7/19/06	< 0.00084	No	No	

Note:

1. Asbestos sample at Station 2 (Southeast Area [sidewalk bridge level]) on July 18, 2006 was not available for analysis on account of timer malfunction.