

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-7/19/07	030724083-0001	Southwest Area (sidewalk bridge level)	7/19/07	1	3.050	Asbestos	PCME	EMSL	7/20/07	< 0.00081	No	No	
ASBESTOS-ST2-7/19/07	030724083-0002	Southeast Area (sidewalk bridge level)	7/19/07	1	3.060	Asbestos	PCME	EMSL	7/20/07	< 0.00081	No	No	
ASBESTOS-ST4-7/19/07	030724083-0003	Northwest Area (street-level)	7/19/07	1	2.560	Asbestos	PCME	EMSL	7/20/07	< 0.00089	No	No	
ASBESTOS-ST5-7/19/07	030724083-0004	Firehouse #10 (roof level)	7/19/07	1	3.050	Asbestos	PCME	EMSL	7/20/07	< 0.00081	No	No	
ASBESTOS-ST10-7/19/07	030724083-0005	North Side Sidewalk Bridge	7/19/07	1	3.020	Asbestos	PCME	EMSL	7/20/07	< 0.00082	No	No	
ASBESTOS-ST11-7/19/07	030724083-0006	90 Trinity Place (roof level)	7/19/07	1	2.990	Asbestos	PCME	EMSL	7/20/07	< 0.00083	No	No	
ASBESTOS-ST12-7/19/07	030724083-0007	110 Greenwich Street (roof level)	7/19/07	1	3.040	Asbestos	PCME	EMSL	7/20/07	< 0.00081	No	No	
ASBESTOS-ST13-7/19/07	030724083-0008	Marriott Hotel, 38th Floor (roof level)	7/19/07	1	3.020	Asbestos	PCME	EMSL	7/20/07	< 0.00082	No	No	
ASBESTOS-ST14-7/19/07	030724083-0009	West Face - South end at corner (scaffolding level)	7/19/07	1	2.920	Asbestos	PCME	EMSL	7/20/07	< 0.00085	No	No	
ASBESTOS-ST15-7/19/07	030724083-0010	South Face - East end at corner (scaffolding level)	7/19/07	1	3.040	Asbestos	PCME	EMSL	7/20/07	< 0.00081	No	No	
ASBESTOS-ST16-7/19/07	030724083-0011	East Face - North end at corner (scaffolding level)	7/19/07	1	3.090	Asbestos	PCME	EMSL	7/20/07	< 0.00080	No	No	
ASBESTOS-ST17-7/19/07	030724083-0012	North Face - West end at corner (scaffolding level)	7/19/07	1	3.060	Asbestos	PCME	EMSL	7/20/07	< 0.00081	No	No	
ASBESTOS-ST1-7/20/07	030724332-0001	Southwest Area (sidewalk bridge level)	7/20/07	1	3.040	Asbestos	PCME	EMSL	7/22/07	< 0.00081	No	No	
ASBESTOS-ST2-7/20/07	030724332-0002	Southeast Area (sidewalk bridge level)	7/20/07	1	3.050	Asbestos	PCME	EMSL	7/22/07	< 0.00081	No	No	
ASBESTOS-ST4-7/20/07	030724332-0003	Northwest Area (street-level)	7/20/07	1	2.980	Asbestos	PCME	EMSL	7/22/07	< 0.00083	No	No	
ASBESTOS-ST5-7/20/07	030724332-0004	Firehouse #10 (roof level)	7/20/07	1	3.060	Asbestos	PCME	EMSL	7/22/07	< 0.00081	No	No	
ASBESTOS-ST10-7/20/07	030724332-0005	North Side Sidewalk Bridge	7/20/07	1	2.930	Asbestos	PCME	EMSL	7/22/07	< 0.00084	No	No	
ASBESTOS-ST11-7/20/07	030724332-0006	90 Trinity Place (roof level)	7/20/07	1	3.040	Asbestos	PCME	EMSL	7/22/07	< 0.00081	No	No	
ASBESTOS-ST12-7/20/07	030724332-0007	110 Greenwich Street (roof level)	7/20/07	1	3.010	Asbestos	PCME	EMSL	7/22/07	< 0.00082	No	No	
ASBESTOS-ST13-7/20/07	030724332-0008	Marriott Hotel, 38th Floor (roof level)	7/20/07	1	3.010	Asbestos	PCME	EMSL	7/22/07	< 0.00082	No	No	
ASBESTOS-ST14-7/20/07	030724332-0009	West Face - South end at corner (scaffolding level)	7/20/07	1	3.050	Asbestos	PCME	EMSL	7/22/07	< 0.00081	No	No	
ASBESTOS-ST15-7/20/07	030724332-0010	South Face - East end at corner (scaffolding level)	7/20/07	1	3.010	Asbestos	PCME	EMSL	7/22/07	< 0.00082	No	No	
ASBESTOS-ST16-7/20/07	030724332-0011	East Face - North end at corner (scaffolding level)	7/20/07	1	3.030	Asbestos	PCME	EMSL	7/22/07	< 0.00081	No	No	
ASBESTOS-ST17-7/20/07	030724332-0012	North Face - West end at corner (scaffolding level)	7/20/07	1	3.040	Asbestos	PCME	EMSL	7/22/07	< 0.00081	No	No	
ASBESTOS-ST1-7/21/07	030724469-0001	Southwest Area (sidewalk bridge level)	7/21/07	1	3.040	Asbestos	SEM	EMSL	7/23/07	< 0.00060	No	No	
ASBESTOS-ST2-7/21/07	030724469-0002	Southeast Area (sidewalk bridge level)	7/21/07	1	3.010	Asbestos	SEM	EMSL	7/23/07	< 0.00060	No	No	
ASBESTOS-ST4-7/21/07	030724469-0003	Northwest Area (street-level)	7/21/07	1	3.040	Asbestos	SEM	EMSL	7/23/07	< 0.00060	No	No	
ASBESTOS-ST5-7/21/07	030724469-0004	Firehouse #10 (roof level)	7/21/07	1	3.040	Asbestos	PCME	EMSL	7/23/07	< 0.00089	No	No	
ASBESTOS-ST10-7/21/07	030724469-0005	North Side Sidewalk Bridge	7/21/07	1	3.040	Asbestos	PCME	EMSL	7/23/07	< 0.00089	No	No	
ASBESTOS-ST11-7/21/07	030724469-0006	90 Trinity Place (roof level)	7/21/07	1	3.010	Asbestos	PCME	EMSL	7/23/07	< 0.00089	No	No	
ASBESTOS-ST12-7/21/07	030724469-0007	110 Greenwich Street (roof level)	7/21/07	1	3.010	Asbestos	PCME	EMSL	7/23/07	< 0.00082	No	No	
ASBESTOS-ST13-7/21/07	030724469-0008	Marriott Hotel, 38th Floor (roof level)	7/21/07	1	3.000	Asbestos	PCME	EMSL	7/23/07	< 0.00082	No	No	
ASBESTOS-ST14-7/21/07	030724469-0009	West Face - South end at corner (scaffolding level)	7/21/07	1	3.000	Asbestos	PCME	EMSL	7/23/07	< 0.00082	No	No	
ASBESTOS-ST15-7/21/07	030724469-0010	South Face - East end at corner (scaffolding level)	7/21/07	1	3.030	Asbestos	PCME	EMSL	7/23/07	< 0.00081	No	No	
ASBESTOS-ST16-7/21/07	030724469-0011	East Face - North end at corner (scaffolding level)	7/21/07	1	3.010	Asbestos	PCME	EMSL	7/23/07	< 0.00082	No	No	
ASBESTOS-ST17-7/21/07	030724469-0012	North Face - West end at corner (scaffolding level)	7/21/07	1	3.000	Asbestos	PCME	EMSL	7/23/07	< 0.00082	No	No	
ASBESTOS-ST1-7/22/07	030724460-0001	Southwest Area (sidewalk bridge level)	7/22/07	1	3.010	Asbestos	PCME	EMSL	7/23/07	< 0.00082	No	No	
ASBESTOS-ST2-7/22/07	030724460-0002	Southeast Area (sidewalk bridge level)	7/22/07	1	2.800	Asbestos	PCME	EMSL	7/23/07	< 0.00088	No	No	
ASBESTOS-ST4-7/22/07	030724460-0003	Northwest Area (street-level)	7/22/07	1	3.040	Asbestos	PCME	EMSL	7/23/07	< 0.00081	No	No	
ASBESTOS-ST5-7/22/07	030724460-0004	Firehouse #10 (roof level)	7/22/07	1	3.040	Asbestos	PCME	EMSL	7/23/07	< 0.00081	No	No	
ASBESTOS-ST10-7/22/07	030724460-0005	North Side Sidewalk Bridge	7/22/07	1	3.040	Asbestos	PCME	EMSL	7/23/07	< 0.00081	No	No	
ASBESTOS-ST11-7/22/07	030724460-0006	90 Trinity Place (roof level)	7/22/07	1	3.090	Asbestos	PCME	EMSL	7/23/07	< 0.00080	No	No	
ASBESTOS-ST12-7/22/07	030724460-0007	110 Greenwich Street (roof level)	7/22/07	1	2.960	Asbestos	PCME	EMSL	7/23/07	< 0.00083	No	No	
ASBESTOS-ST13-7/22/07	030724460-0008	Marriott Hotel, 38th Floor (roof level)	7/22/07	1	3.010	Asbestos	PCME	EMSL	7/23/07	< 0.00082	No	No	
ASBESTOS-ST14-7/22/07	030724460-0009	West Face - South end at corner (scaffolding level)	7/22/07	1	3.040	Asbestos	PCME	EMSL	7/23/07	< 0.00081	No	No	
ASBESTOS-ST15-7/22/07	030724460-0010	South Face - East end at corner (scaffolding level)	7/22/07	1	3.010	Asbestos	PCME	EMSL	7/23/07	< 0.00082	No	No	
ASBESTOS-ST16-7/22/07	030724460-0011	East Face - North end at corner (scaffolding level)	7/22/07	1	3.010	Asbestos	PCME	EMSL	7/23/07	< 0.00082	No	No	
ASBESTOS-ST17-7/22/07	030724460-0012	North Face - West end at corner (scaffolding level)	7/22/07	1	3.040	Asbestos	PCME	EMSL	7/23/07	< 0.00081	No	No	