

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-7/22/09	030918781-0001	Southwest Area (sidewalk bridge level)	7/22/09	1	2.990	Asbestos	PCME	EMSL	7/23/09	< 0.00083	No	No	
ASBESTOS-ST2-7/22/09	030918781-0002	Southeast Area (sidewalk bridge level)	7/22/09	1	2.910	Asbestos	PCME	EMSL	7/23/09	< 0.00085	No	No	
ASBESTOS-ST4-7/22/09	030918781-0003	Northwest Area (street-level)	7/22/09	1	3.070	Asbestos	PCME	EMSL	7/23/09	< 0.00080	No	No	
ASBESTOS-ST5-7/22/09	030918781-0004	Firehouse #10 (roof level)	7/22/09	1	2.990	Asbestos	PCME	EMSL	7/23/09	< 0.00083	No	No	
ASBESTOS-ST10-7/22/09	030918781-0005	North Side Sidewalk Bridge	7/22/09	1	2.930	Asbestos	PCME	EMSL	7/23/09	< 0.00084	No	No	
ASBESTOS-ST11-7/22/09	030918781-0006	90 Trinity Place (roof level)	7/22/09	1	3.030	Asbestos	PCME	EMSL	7/23/09	< 0.00081	No	No	
ASBESTOS-ST12-7/22/09	030918781-0007	110 Greenwich Street (roof level)	7/22/09	1	2.940	Asbestos	PCME	EMSL	7/23/09	< 0.00084	No	No	
ASBESTOS-ST13-7/22/09	030918781-0008	Marriott Hotel, 38th Floor (roof level)	7/22/09	1	2.950	Asbestos	PCME	EMSL	7/23/09	< 0.00084	No	No	
ASBESTOS-ST1-7/23/09	030918946-0001	Southwest Area (sidewalk bridge level)	7/23/09	1	3.020	Asbestos	PCME	EMSL	7/24/09	< 0.00082	No	No	
ASBESTOS-ST2-7/23/09	030918946-0002	Southeast Area (sidewalk bridge level)	7/23/09	1	3.030	Asbestos	PCME	EMSL	7/24/09	< 0.00081	No	No	
ASBESTOS-ST4-7/23/09	030918946-0003	Northwest Area (street-level)	7/23/09	1	3.090	Asbestos	PCME	EMSL	7/24/09	< 0.00080	No	No	
ASBESTOS-ST5-7/23/09	030918946-0004	Firehouse #10 (roof level)	7/23/09	1	3.080	Asbestos	PCME	EMSL	7/24/09	< 0.00080	No	No	
ASBESTOS-ST10-7/23/09	030918946-0005	North Side Sidewalk Bridge	7/23/09	1	3.070	Asbestos	PCME	EMSL	7/24/09	< 0.00080	No	No	
ASBESTOS-ST11-7/23/09	030918946-0006	90 Trinity Place (roof level)	7/23/09	1	3.040	Asbestos	PCME	EMSL	7/24/09	< 0.00081	No	No	
ASBESTOS-ST12-7/23/09	030918946-0007	110 Greenwich Street (roof level)	7/23/09	1	3.150	Asbestos	PCME	EMSL	7/24/09	< 0.00078	No	No	
ASBESTOS-ST13-7/23/09	030918946-0008	Marriott Hotel, 38th Floor (roof level)	7/23/09	1	3.070	Asbestos	PCME	EMSL	7/24/09	< 0.00080	No	No	
ASBESTOS-ST1-7/24/09	030919032-0001	Southwest Area (sidewalk bridge level)	7/24/09	1	3.030	Asbestos	PCME	EMSL	7/25/09	< 0.00081	No	No	
ASBESTOS-ST2-7/24/09	030919032-0002	Southeast Area (sidewalk bridge level)	7/24/09	1	3.060	Asbestos	PCME	EMSL	7/25/09	< 0.00081	No	No	
ASBESTOS-ST4-7/24/09	030919032-0003	Northwest Area (street-level)	7/24/09	1	3.010	Asbestos	PCME	EMSL	7/25/09	< 0.00082	No	No	
ASBESTOS-ST5-7/24/09	030919032-0004	Firehouse #10 (roof level)	7/24/09	1	3.030	Asbestos	PCME	EMSL	7/25/09	< 0.00081	No	No	
ASBESTOS-ST10-7/24/09	030919032-0005	North Side Sidewalk Bridge	7/24/09	1	3.050	Asbestos	PCME	EMSL	7/25/09	< 0.00081	No	No	
ASBESTOS-ST11-7/24/09	030919032-0006	90 Trinity Place (roof level)	7/24/09	1	3.050	Asbestos	PCME	EMSL	7/25/09	< 0.00081	No	No	
ASBESTOS-ST12-7/24/09	030919032-0007	110 Greenwich Street (roof level)	7/24/09	1	3.050	Asbestos	PCME	EMSL	7/25/09	< 0.00081	No	No	
ASBESTOS-ST13-7/24/09	030919032-0008	Marriott Hotel, 38th Floor (roof level)	7/24/09	1	3.030	Asbestos	PCME	EMSL	7/25/09	< 0.00081	No	No	