

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-7/30/08	030825847-0001	Southwest Area (sidewalk bridge level)	7/30/08	1	3.110	Asbestos	PCME	EMSL	7/31/08	< 0.00079	No	No	
ASBESTOS-ST2-7/30/08	030825847-0002	Southeast Area (sidewalk bridge level)	7/30/08	1	3.040	Asbestos	PCME	EMSL	7/31/08	< 0.00081	No	No	
ASBESTOS-ST4-7/30/08	030825847-0003	Northwest Area (street-level)	7/30/08	1	3.090	Asbestos	PCME	EMSL	7/31/08	< 0.00080	No	No	
ASBESTOS-ST5-7/30/08	030825847-0004	Firehouse #10 (roof level)	7/30/08	1	3.180	Asbestos	PCME	EMSL	7/31/08	< 0.00078	No	No	
ASBESTOS-ST10-7/30/08	030825847-0005	North Side Sidewalk Bridge	7/30/08	1	3.120	Asbestos	PCME	EMSL	7/31/08	< 0.00079	No	No	
ASBESTOS-ST11-7/30/08	030825847-0006	90 Trinity Place (roof level)	7/30/08	1	3.070	Asbestos	PCME	EMSL	7/31/08	< 0.00080	No	No	
ASBESTOS-ST12-7/30/08	030825847-0007	110 Greenwich Street (roof level)	7/30/08	1	3.010	Asbestos	PCME	EMSL	7/31/08	< 0.00082	No	No	
ASBESTOS-ST13-7/30/08	030825847-0008	Marriott Hotel, 38th Floor (roof level)	7/30/08	1	3.060	Asbestos	PCME	EMSL	7/31/08	< 0.00081	No	No	
ASBESTOS-ST14-7/30/08	030825847-0009	West Face - South end at corner (scaffolding level)	7/30/08	1	3.050	Asbestos	PCME	EMSL	7/31/08	< 0.00081	No	No	
ASBESTOS-ST15-7/30/08	030825847-0010	South Face - East end at corner (scaffolding level)	7/30/08	1	3.010	Asbestos	PCME	EMSL	7/31/08	< 0.00082	No	No	
ASBESTOS-ST16-7/30/08	030825847-0011	East Face - North end at corner (scaffolding level)	7/30/08	1	3.060	Asbestos	PCME	EMSL	7/31/08	< 0.00081	No	No	
ASBESTOS-ST17-7/30/08	030825847-0012	North Face - West end at corner (scaffolding level)	7/30/08	1	3.130	Asbestos	PCME	EMSL	7/31/08	< 0.00079	No	No	
ASBESTOS-ST1-7/31/08	030826013-0001	Southwest Area (sidewalk bridge level)	7/31/08	1	2.960	Asbestos	PCME	EMSL	8/1/08	< 0.00083	No	No	
ASBESTOS-ST2-7/31/08	030826013-0002	Southeast Area (sidewalk bridge level)	7/31/08	1	3.050	Asbestos	PCME	EMSL	8/1/08	< 0.00081	No	No	
ASBESTOS-ST4-7/31/08	030826013-0003	Northwest Area (street-level)	7/31/08	1	3.090	Asbestos	PCME	EMSL	8/1/08	< 0.00080	No	No	
ASBESTOS-ST5-7/31/08	030826013-0004	Firehouse #10 (roof level)	7/31/08	1	3.140	Asbestos	PCME	EMSL	8/1/08	< 0.00079	No	No	
ASBESTOS-ST10-7/31/08	030826013-0005	North Side Sidewalk Bridge	7/31/08	1	3.010	Asbestos	PCME	EMSL	8/1/08	< 0.00082	No	No	
ASBESTOS-ST11-7/31/08	030826013-0006	90 Trinity Place (roof level)	7/31/08	1	3.040	Asbestos	PCME	EMSL	8/1/08	< 0.00081	No	No	
ASBESTOS-ST12-7/31/08	030826013-0007	110 Greenwich Street (roof level)	7/31/08	1	3.060	Asbestos	PCME	EMSL	8/1/08	< 0.00081	No	No	
ASBESTOS-ST13-7/31/08	030826013-0008	Marriott Hotel, 38th Floor (roof level)	7/31/08	1	2.980	Asbestos	PCME	EMSL	8/1/08	< 0.00083	No	No	
ASBESTOS-ST14-7/31/08	030826013-0009	West Face - South end at corner (scaffolding level)	7/31/08	1	3.060	Asbestos	PCME	EMSL	8/1/08	< 0.00081	No	No	
ASBESTOS-ST15-7/31/08	030826013-0010	South Face - East end at corner (scaffolding level)	7/31/08	1	3.000	Asbestos	PCME	EMSL	8/1/08	< 0.00082	No	No	
ASBESTOS-ST16-7/31/08	030826013-0011	East Face - North end at corner (scaffolding level)	7/31/08	1	3.050	Asbestos	PCME	EMSL	8/1/08	< 0.00081	No	No	
ASBESTOS-ST17-7/31/08	030826013-0012	North Face - West end at corner (scaffolding level)	7/31/08	1	3.200	Asbestos	PCME	EMSL	8/1/08	< 0.00077	No	No	
ASBESTOS-ST1-8/1/08	030826133-0001	Southwest Area (sidewalk bridge level)	8/1/08	1	3.010	Asbestos	PCME	EMSL	8/2/08	< 0.00082	No	No	
ASBESTOS-ST2-8/1/08	030826133-0002	Southeast Area (sidewalk bridge level)	8/1/08	1	3.070	Asbestos	PCME	EMSL	8/2/08	< 0.00080	No	No	
ASBESTOS-ST4-8/1/08	030826133-0003	Northwest Area (street-level)	8/1/08	1	2.970	Asbestos	PCME	EMSL	8/2/08	< 0.00083	No	No	
ASBESTOS-ST5-8/1/08	030826133-0004	Firehouse #10 (roof level)	8/1/08	1	3.040	Asbestos	PCME	EMSL	8/2/08	< 0.00081	No	No	
ASBESTOS-ST10-8/1/08	030826133-0005	North Side Sidewalk Bridge	8/1/08	1	3.050	Asbestos	PCME	EMSL	8/2/08	< 0.00081	No	No	
ASBESTOS-ST11-8/1/08	030826133-0006	90 Trinity Place (roof level)	8/1/08	1	3.060	Asbestos	PCME	EMSL	8/2/08	< 0.00081	No	No	
ASBESTOS-ST12-8/1/08	030826133-0007	110 Greenwich Street (roof level)	8/1/08	1	3.000	Asbestos	PCME	EMSL	8/2/08	< 0.00082	No	No	
ASBESTOS-ST13-8/1/08	030826133-0008	Marriott Hotel, 38th Floor (roof level)	8/1/08	1	3.000	Asbestos	PCME	EMSL	8/2/08	< 0.00082	No	No	
ASBESTOS-ST14-8/1/08	030826133-0009	West Face - South end at corner (scaffolding level)	8/1/08	1	3.020	Asbestos	PCME	EMSL	8/2/08	< 0.00082	No	No	
ASBESTOS-ST15-8/1/08	030826133-0010	South Face - East end at corner (scaffolding level)	8/1/08	1	3.010	Asbestos	PCME	EMSL	8/2/08	< 0.00082	No	No	
ASBESTOS-ST16-8/1/08	030826133-0011	East Face - North end at corner (scaffolding level)	8/1/08	1	2.990	Asbestos	PCME	EMSL	8/2/08	< 0.00083	No	No	
ASBESTOS-ST17-8/1/08	030826133-0012	North Face - West end at corner (scaffolding level)	8/1/08	1	3.000	Asbestos	PCME	EMSL	8/2/08	< 0.00082	No	No	
ASBESTOS-ST1-8/2/08	030826360-0001	Southwest Area (sidewalk bridge level)	8/2/08	1	3.010	Asbestos	PCME	EMSL	8/4/08	< 0.00082	No	No	
ASBESTOS-ST2-8/2/08	030826360-0002	Southeast Area (sidewalk bridge level)	8/2/08	1	3.060	Asbestos	PCME	EMSL	8/4/08	< 0.00081	No	No	
ASBESTOS-ST4-8/2/08	030826360-0003	Northwest Area (street-level)	8/2/08	1	3.150	Asbestos	PCME	EMSL	8/4/08	< 0.00078	No	No	
ASBESTOS-ST5-8/2/08	030826360-0004	Firehouse #10 (roof level)	8/2/08	1	3.050	Asbestos	PCME	EMSL	8/4/08	< 0.00081	No	No	
ASBESTOS-ST10-8/2/08	030826360-0005	North Side Sidewalk Bridge	8/2/08	1	3.040	Asbestos	PCME	EMSL	8/4/08	< 0.00081	No	No	
ASBESTOS-ST11-8/2/08	030826360-0006	90 Trinity Place (roof level)	8/2/08	1	3.000	Asbestos	PCME	EMSL	8/4/08	< 0.00082	No	No	
ASBESTOS-ST12-8/2/08	030826360-0007	110 Greenwich Street (roof level)	8/2/08	1	3.070	Asbestos	PCME	EMSL	8/4/08	< 0.00080	No	No	
ASBESTOS-ST13-8/2/08	030826360-0008	Marriott Hotel, 38th Floor (roof level)	8/2/08	1	2.990	Asbestos	PCME	EMSL	8/4/08	< 0.00083	No	No	
ASBESTOS-ST14-8/2/08	030826360-0009	West Face - South end at corner (scaffolding level)	8/2/08	1	2.990	Asbestos	PCME	EMSL	8/4/08	< 0.00083	No	No	
ASBESTOS-ST15-8/2/08	030826360-0010	South Face - East end at corner (scaffolding level)	8/2/08	1	3.040	Asbestos	PCME	EMSL	8/4/08	< 0.00081	No	No	
ASBESTOS-ST16-8/2/08	030826360-0011	East Face - North end at corner (scaffolding level)	8/2/08	1	3.070	Asbestos	PCME	EMSL	8/4/08	< 0.00080	No	No	
ASBESTOS-ST17-8/2/08	030826360-0012	North Face - West end at corner (scaffolding level)	8/2/08	1	3.050	Asbestos	PCME	EMSL	8/4/08	< 0.00081	No	No	
ASBESTOS-ST1-8/3/08	030826357-0001	Southwest Area (sidewalk bridge level)	8/3/08	1	3.060	Asbestos	PCME	EMSL	8/4/08	< 0.00088	No	No	
ASBESTOS-ST2-8/3/08	030826357-0002	Southeast Area (sidewalk bridge level)	8/3/08	1	3.060	Asbestos	PCME	EMSL	8/4/08	< 0.00088	No	No	
ASBESTOS-ST4-8/3/08	030826357-0003	Northwest Area (street-level)	8/3/08	1	3.040	Asbestos	PCME	EMSL	8/4/08	< 0.00089	No	No	
ASBESTOS-ST5-8/3/08	030826357-0004	Firehouse #10 (roof level)	8/3/08	1	2.920	Asbestos	PCME	EMSL	8/4/08	< 0.00085	No	No	
ASBESTOS-ST10-8/3/08	030826357-0005	North Side Sidewalk Bridge	8/3/08	1	3.000	Asbestos	PCME	EMSL	8/4/08	< 0.00082	No	No	
ASBESTOS-ST11-8/3/08	030826357-0006	90 Trinity Place (roof level)	8/3/08	1	3.010	Asbestos	PCME	EMSL	8/4/08	< 0.00082	No	No	
ASBESTOS-ST12-8/3/08	030826357-0007	110 Greenwich Street (roof level)	8/3/08	1	3.040	Asbestos	PCME	EMSL	8/4/08	< 0.00081	No	No	
ASBESTOS-ST13-8/3/08	030826357-0008	Marriott Hotel, 38th Floor (roof level)	8/3/08	1	3.040	Asbestos	PCME	EMSL	8/4/08	< 0.00081	No	No	
ASBESTOS-ST14-8/3/08	030826357-0009	West Face - South end at corner (scaffolding level)	8/3/08	1	3.070	Asbestos	PCME	EMSL	8/4/08	< 0.00080	No	No	
ASBESTOS-ST15-8/3/08	030826357-0010	South Face - East end at corner (scaffolding level)	8/3/08	1	3.020	Asbestos	PCME	EMSL	8/4/08	< 0.00082	No	No	
ASBESTOS-ST16-8/3/08	030826357-0011	East Face - North end at corner (scaffolding level)	8/3/08	1	3.040	Asbestos	PCME	EMSL	8/4/08	< 0.00081	No	No	
ASBESTOS-ST17-8/3/08	030826357-0012	North Face - West end at corner (scaffolding level)	8/3/08	1	3.060	Asbestos	PCME	EMSL	8/4/08	< 0.00081	No	No	