

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-8/2/07	030726230-0001	Southwest Area (sidewalk bridge level)	8/2/07	1	2.970	Asbestos	PCME	EMSL	8/3/07	< 0.00083	No	No	
ASBESTOS-ST2-8/2/07	030726230-0002	Southeast Area (sidewalk bridge level)	8/2/07	1	3.090	Asbestos	PCME	EMSL	8/3/07	< 0.00080	No	No	
ASBESTOS-ST4-8/2/07	030726230-0003	Northwest Area (street-level)	8/2/07	1	2.920	Asbestos	PCME	EMSL	8/3/07	< 0.00085	No	No	
ASBESTOS-ST5-8/2/07	030726230-0004	Firehouse #10 (roof level)	8/2/07	1	3.020	Asbestos	PCME	EMSL	8/3/07	< 0.00082	No	No	
ASBESTOS-ST10-8/2/07	030726230-0005	North Side Sidewalk Bridge	8/2/07	1	3.280	Asbestos	PCME	EMSL	8/3/07	< 0.00075	No	No	
ASBESTOS-ST11-8/2/07	030726230-0006	90 Trinity Place (roof level)	8/2/07	1	2.960	Asbestos	PCME	EMSL	8/3/07	< 0.00083	No	No	
ASBESTOS-ST12-8/2/07	030726230-0007	110 Greenwich Street (roof level)	8/2/07	1	3.090	Asbestos	PCME	EMSL	8/3/07	< 0.00080	No	No	
ASBESTOS-ST13-8/2/07	030726230-0008	Marriott Hotel, 38th Floor (roof level)	8/2/07	1	3.040	Asbestos	PCME	EMSL	8/3/07	< 0.00081	No	No	
ASBESTOS-ST14-8/2/07	030726230-0009	West Face - South end at corner (scaffolding level)	8/2/07	1	3.020	Asbestos	PCME	EMSL	8/3/07	< 0.00082	No	No	
ASBESTOS-ST15-8/2/07	030726230-0010	South Face - East end at corner (scaffolding level)	8/2/07	1	3.100	Asbestos	PCME	EMSL	8/3/07	< 0.00080	No	No	
ASBESTOS-ST16-8/2/07	030726230-0011	East Face - North end at corner (scaffolding level)	8/2/07	1	2.930	Asbestos	PCME	EMSL	8/3/07	< 0.00084	No	No	
ASBESTOS-ST17-8/2/07	030726230-0012	North Face - West end at corner (scaffolding level)	8/2/07	1	3.090	Asbestos	PCME	EMSL	8/3/07	< 0.00080	No	No	
ASBESTOS-ST1-8/3/07	030726379-0001	Southwest Area (sidewalk bridge level)	8/3/07	1	3.090	Asbestos	PCME	EMSL	8/4/07	< 0.00080	No	No	
ASBESTOS-ST2-8/3/07	030726379-0002	Southeast Area (sidewalk bridge level)	8/3/07	1	3.060	Asbestos	PCME	EMSL	8/4/07	< 0.00081	No	No	
ASBESTOS-ST4-8/3/07	030726379-0003	Northwest Area (street-level)	8/3/07	1	2.970	Asbestos	PCME	EMSL	8/4/07	< 0.00083	No	No	
ASBESTOS-ST5-8/3/07	030726379-0004	Firehouse #10 (roof level)	8/3/07	1	3.110	Asbestos	PCME	EMSL	8/4/07	< 0.00079	No	No	
ASBESTOS-ST10-8/3/07	030726379-0005	North Side Sidewalk Bridge	8/3/07	1	3.090	Asbestos	PCME	EMSL	8/4/07	< 0.00080	No	No	
ASBESTOS-ST11-8/3/07	030726379-0006	90 Trinity Place (roof level)	8/3/07	1	3.150	Asbestos	PCME	EMSL	8/4/07	< 0.00078	No	No	
ASBESTOS-ST12-8/3/07	030726379-0007	110 Greenwich Street (roof level)	8/3/07	1	3.020	Asbestos	PCME	EMSL	8/4/07	< 0.00082	No	No	
ASBESTOS-ST13-8/3/07	030726379-0008	Marriott Hotel, 38th Floor (roof level)	8/3/07	1	3.070	Asbestos	PCME	EMSL	8/4/07	< 0.00080	No	No	
ASBESTOS-ST14-8/3/07	030726379-0009	West Face - South end at corner (scaffolding level)	8/3/07	1	2.960	Asbestos	PCME	EMSL	8/4/07	< 0.00083	No	No	
ASBESTOS-ST15-8/3/07	030726379-0010	South Face - East end at corner (scaffolding level)	8/3/07	1	3.070	Asbestos	PCME	EMSL	8/4/07	< 0.00080	No	No	
ASBESTOS-ST16-8/3/07	030726379-0011	East Face - North end at corner (scaffolding level)	8/3/07	1	3.150	Asbestos	PCME	EMSL	8/4/07	< 0.00078	No	No	
ASBESTOS-ST17-8/3/07	030726379-0012	North Face - West end at corner (scaffolding level)	8/3/07	1	2.920	Asbestos	PCME	EMSL	8/4/07	< 0.00085	No	No	
ASBESTOS-ST1-8/4/07	030726564-0001	Southwest Area (sidewalk bridge level)	8/4/07	1	3.090	Asbestos	PCME	EMSL	8/6/07	< 0.00080	No	No	
ASBESTOS-ST2-8/4/07	030726564-0002	Southeast Area (sidewalk bridge level)	8/4/07	1	2.950	Asbestos	PCME	EMSL	8/6/07	< 0.00084	No	No	
ASBESTOS-ST5-8/4/07	030726564-0004	Firehouse #10 (roof level)	8/4/07	1	3.060	Asbestos	PCME	EMSL	8/6/07	< 0.00081	No	No	
ASBESTOS-ST10-8/4/07	030726564-0005	North Side Sidewalk Bridge	8/4/07	1	2.900	Asbestos	PCME	EMSL	8/6/07	< 0.00085	No	No	
ASBESTOS-ST11-8/4/07	030726564-0006	90 Trinity Place (roof level)	8/4/07	1	2.970	Asbestos	PCME	EMSL	8/6/07	< 0.00083	No	No	
ASBESTOS-ST12-8/4/07	030726564-0007	110 Greenwich Street (roof level)	8/4/07	1	3.090	Asbestos	PCME	EMSL	8/6/07	< 0.00080	No	No	
ASBESTOS-ST13-8/4/07	030726564-0008	Marriott Hotel, 38th Floor (roof level)	8/4/07	1	3.010	Asbestos	PCME	EMSL	8/6/07	< 0.00082	No	No	
ASBESTOS-ST14-8/4/07	030726564-0009	West Face - South end at corner (scaffolding level)	8/4/07	1	3.090	Asbestos	PCME	EMSL	8/6/07	< 0.00080	No	No	
ASBESTOS-ST15-8/4/07	030726564-0010	South Face - East end at corner (scaffolding level)	8/4/07	1	3.010	Asbestos	PCME	EMSL	8/6/07	< 0.00082	No	No	
ASBESTOS-ST16-8/4/07	030726564-0011	East Face - North end at corner (scaffolding level)	8/4/07	1	3.020	Asbestos	PCME	EMSL	8/6/07	< 0.00082	No	No	
ASBESTOS-ST17-8/4/07	030726564-0012	North Face - West end at corner (scaffolding level)	8/4/07	1	3.090	Asbestos	PCME	EMSL	8/6/07	< 0.00080	No	No	
ASBESTOS-ST1-8/5/07	030726252-0001	Southwest Area (sidewalk bridge level)	8/5/07	1	2.960	Asbestos	PCME	EMSL	8/6/07	< 0.00083	No	No	
ASBESTOS-ST2-8/5/07	030726252-0002	Southeast Area (sidewalk bridge level)	8/5/07	1	2.960	Asbestos	PCME	EMSL	8/6/07	< 0.00083	No	No	
ASBESTOS-ST4-8/5/07	030726252-0003	Northwest Area (street-level)	8/5/07	1	3.150	Asbestos	PCME	EMSL	8/6/07	< 0.00085	No	No	
ASBESTOS-ST5-8/5/07	030726252-0004	Firehouse #10 (roof level)	8/5/07	1	3.010	Asbestos	PCME	EMSL	8/6/07	< 0.00082	No	No	
ASBESTOS-ST10-8/5/07	030726252-0005	North Side Sidewalk Bridge	8/5/07	1	2.960	Asbestos	PCME	EMSL	8/6/07	< 0.00083	No	No	
ASBESTOS-ST11-8/5/07	030726252-0006	90 Trinity Place (roof level)	8/5/07	1	3.040	Asbestos	PCME	EMSL	8/6/07	< 0.00081	No	No	
ASBESTOS-ST12-8/5/07	030726252-0007	110 Greenwich Street (roof level)	8/5/07	1	3.090	Asbestos	PCME	EMSL	8/6/07	< 0.00080	No	No	
ASBESTOS-ST13-8/5/07	030726252-0008	Marriott Hotel, 38th Floor (roof level)	8/5/07	1	3.010	Asbestos	PCME	EMSL	8/6/07	< 0.00082	No	No	
ASBESTOS-ST14-8/5/07	030726252-0009	West Face - South end at corner (scaffolding level)	8/5/07	1	3.020	Asbestos	PCME	EMSL	8/6/07	< 0.00082	No	No	
ASBESTOS-ST15-8/5/07	030726252-0010	South Face - East end at corner (scaffolding level)	8/5/07	1	3.030	Asbestos	PCME	EMSL	8/6/07	< 0.00081	No	No	
ASBESTOS-ST16-8/5/07	030726252-0011	East Face - North end at corner (scaffolding level)	8/5/07	1	3.020	Asbestos	PCME	EMSL	8/6/07	< 0.00082	No	No	
ASBESTOS-ST17-8/5/07	030726252-0012	North Face - West end at corner (scaffolding level)	8/5/07	1	3.110	Asbestos	PCME	EMSL	8/6/07	< 0.00087	No	No	
ASBESTOS-ST1-8/6/07	030726712-0001	Southwest Area (sidewalk bridge level)	8/6/07	1	3.230	Asbestos	PCME	EMSL	8/7/07	< 0.00076	No	No	
ASBESTOS-ST2-8/6/07	030726712-0002	Southeast Area (sidewalk bridge level)	8/6/07	1	3.030	Asbestos	PCME	EMSL	8/7/07	< 0.00081	No	No	
ASBESTOS-ST4-8/6/07	030726712-0003	Northwest Area (street-level)	8/6/07	1	3.020	Asbestos	PCME	EMSL	8/7/07	< 0.00082	No	No	
ASBESTOS-ST5-8/6/07	030726712-0004	Firehouse #10 (roof level)	8/6/07	1	3.090	Asbestos	PCME	EMSL	8/7/07	< 0.00080	No	No	
ASBESTOS-ST10-8/6/07	030726712-0005	North Side Sidewalk Bridge	8/6/07	1	3.020	Asbestos	PCME	EMSL	8/7/07	< 0.00082	No	No	
ASBESTOS-ST11-8/6/07	030726712-0006	90 Trinity Place (roof level)	8/6/07	1	3.040	Asbestos	PCME	EMSL	8/7/07	< 0.00081	No	No	
ASBESTOS-ST12-8/6/07	030726712-0007	110 Greenwich Street (roof level)	8/6/07	1	3.060	Asbestos	PCME	EMSL	8/7/07	< 0.00081	No	No	
ASBESTOS-ST13-8/6/07	030726712-0008	Marriott Hotel, 38th Floor (roof level)	8/6/07	1	2.960	Asbestos	PCME	EMSL	8/7/07	< 0.00083	No	No	
ASBESTOS-ST14-8/6/07	030726712-0009	West Face - South end at corner (scaffolding level)	8/6/07	1	3.010	Asbestos	PCME	EMSL	8/7/07	< 0.00082	No	No	
ASBESTOS-ST15-8/6/07	030726712-0010	South Face - East end at corner (scaffolding level)	8/6/07	1	3.020	Asbestos	PCME	EMSL	8/7/07	< 0.00082	No	No	
ASBESTOS-ST16-8/6/07	030726712-0011	East Face - North end at corner (scaffolding level)	8/6/07	1	3.050	Asbestos	PCME	EMSL	8/7/07	< 0.00081	No	No	
ASBESTOS-ST17-8/6/07	030726712-0012	North Face - West end at corner (scaffolding level)	8/6/07	1	3.010	Asbestos	PCME	EMSL	8/7/07	< 0.00082	No	No	

Note:

1. Asbestos result at Station 4 (Northwest Area [street-level]) on August 4, 2007 is temporarily unavailable on account of samples being overloaded. Samples are currently being analyzed via SEM and the results will be provided in the next posting.