

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>										<b>0.0009</b>			
<b>EPA Site Specific Trigger Levels</b>										<b>NA</b>			
ASBESTOS-ST1-8/5/09	030920294-0001	Southwest Area (sidewalk bridge level)	8/5/09	1	3.030	Asbestos	PCME	EMSL	8/6/09	< 0.00081	No	No	
ASBESTOS-ST2-8/5/09	030920294-0002	Southeast Area (sidewalk bridge level)	8/5/09	1	3.110	Asbestos	PCME	EMSL	8/6/09	< 0.00079	No	No	
ASBESTOS-ST4-8/5/09	030920294-0003	Northwest Area (street-level)	8/5/09	1	2.920	Asbestos	PCME	EMSL	8/6/09	< 0.00085	No	No	
ASBESTOS-ST5-8/5/09	030920294-0004	Firehouse #10 (roof level)	8/5/09	1	3.010	Asbestos	PCME	EMSL	8/6/09	< 0.00082	No	No	
ASBESTOS-ST10-8/5/09	030920294-0005	North Side Sidewalk Bridge	8/5/09	1	3.070	Asbestos	PCME	EMSL	8/6/09	< 0.00080	No	No	
ASBESTOS-ST11-8/5/09	030920294-0006	90 Trinity Place (roof level)	8/5/09	1	3.020	Asbestos	PCME	EMSL	8/6/09	< 0.00082	No	No	
ASBESTOS-ST12-8/5/09	030920294-0007	110 Greenwich Street (roof level)	8/5/09	1	3.050	Asbestos	PCME	EMSL	8/6/09	< 0.00081	No	No	
ASBESTOS-ST13-8/5/09	030920294-0008	Marriott Hotel, 38th Floor (roof level)	8/5/09	1	3.080	Asbestos	PCME	EMSL	8/6/09	< 0.00080	No	No	
ASBESTOS-ST1-8/6/09	030920434-0001	Southwest Area (sidewalk bridge level)	8/6/09	1	3.060	Asbestos	PCME	EMSL	8/7/09	< 0.00081	No	No	
ASBESTOS-ST2-8/6/09	030920434-0002	Southeast Area (sidewalk bridge level)	8/6/09	1	3.060	Asbestos	PCME	EMSL	8/7/09	< 0.00081	No	No	
ASBESTOS-ST4-8/6/09	030920434-0003	Northwest Area (street-level)	8/6/09	1	2.980	Asbestos	PCME	EMSL	8/7/09	< 0.00083	No	No	
ASBESTOS-ST10-8/6/09	030920434-0004	North Side Sidewalk Bridge	8/6/09	1	2.960	Asbestos	PCME	EMSL	8/7/09	< 0.00083	No	No	
ASBESTOS-ST11-8/6/09	030920434-0005	90 Trinity Place (roof level)	8/6/09	1	3.040	Asbestos	PCME	EMSL	8/7/09	< 0.00081	No	No	
ASBESTOS-ST12-8/6/09	030920434-0006	110 Greenwich Street (roof level)	8/6/09	1	3.060	Asbestos	PCME	EMSL	8/7/09	< 0.00081	No	No	
ASBESTOS-ST13-8/6/09	030920434-0007	Marriott Hotel, 38th Floor (roof level)	8/6/09	1	3.080	Asbestos	PCME	EMSL	8/7/09	< 0.00080	No	No	
ASBESTOS-ST1-8/7/09	030920503-0001	Southwest Area (sidewalk bridge level)	8/7/09	1	3.040	Asbestos	PCME	EMSL	8/8/09	< 0.00081	No	No	
ASBESTOS-ST2-8/7/09	030920503-0002	Southeast Area (sidewalk bridge level)	8/7/09	1	3.090	Asbestos	PCME	EMSL	8/8/09	< 0.00080	No	No	
ASBESTOS-ST4-8/7/09	030920503-0003	Northwest Area (street-level)	8/7/09	1	3.030	Asbestos	PCME	EMSL	8/8/09	< 0.00081	No	No	
ASBESTOS-ST5-8/7/09	030920503-0004	Firehouse #10 (roof level)	8/7/09	1	3.100	Asbestos	PCME	EMSL	8/8/09	< 0.00080	No	No	
ASBESTOS-ST10-8/7/09	030920503-0005	North Side Sidewalk Bridge	8/7/09	1	3.030	Asbestos	PCME	EMSL	8/8/09	< 0.00081	No	No	
ASBESTOS-ST11-8/7/09	030920503-0006	90 Trinity Place (roof level)	8/7/09	1	3.020	Asbestos	PCME	EMSL	8/8/09	< 0.00082	No	No	
ASBESTOS-ST12-8/7/09	030920503-0007	110 Greenwich Street (roof level)	8/7/09	1	3.010	Asbestos	PCME	EMSL	8/8/09	< 0.00082	No	No	
ASBESTOS-ST13-8/7/09	030920503-0008	Marriott Hotel, 38th Floor (roof level)	8/7/09	1	3.120	Asbestos	PCME	EMSL	8/8/09	< 0.00079	No	No	

Note:

1. The asbestos sample from Station 5 (Firehouse #10 [roof level]) on August 6, 2009 was not available for analysis on account of pump failure.