

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Site Specific	
										NA	Levels	Trigger Levels	
ASBESTOS-ST1-8/11/07	030727413-0001	Southwest Area (sidewalk bridge level)	8/11/07	1	2.860	Asbestos	SEM	EMSL	8/13/07	< 0.00080	No	No	
ASBESTOS-ST2-8/11/07	030727413-0002	Southeast Area (sidewalk bridge level)	8/11/07	1	3.020	Asbestos	SEM	EMSL	8/13/07	< 0.00080	No	No	
ASBESTOS-ST4-8/11/07	030727413-0003	Northwest Area (street-level)	8/11/07	1	2.890	Asbestos	SEM	EMSL	8/13/07	< 0.00080	No	No	
ASBESTOS-ST5-8/11/07	030727413-0004	Firehouse #10 (roof level)	8/11/07	1	3.010	Asbestos	PCME	EMSL	8/13/07	< 0.00082	No	No	
ASBESTOS-ST10-8/11/07	030727413-0005	North Side Sidewalk Bridge	8/11/07	1	3.010	Asbestos	PCME	EMSL	8/13/07	< 0.00082	No	No	
ASBESTOS-ST11-8/11/07	030727413-0006	90 Trinity Place (roof level)	8/11/07	1	2.960	Asbestos	PCME	EMSL	8/13/07	< 0.00083	No	No	
ASBESTOS-ST12-8/11/07	030727413-0007	110 Greenwich Street (roof level)	8/11/07	1	2.720	Asbestos	PCME	EMSL	8/13/07	< 0.00084	No	No	
ASBESTOS-ST13-8/11/07	030727413-0008	Marriott Hotel, 38th Floor (roof level)	8/11/07	1	3.010	Asbestos	PCME	EMSL	8/13/07	< 0.00082	No	No	
ASBESTOS-ST14-8/11/07	030727413-0009	West Face - South end at corner (scaffolding level)	8/11/07	1	3.040	Asbestos	PCME	EMSL	8/13/07	< 0.00081	No	No	
ASBESTOS-ST15-8/11/07	030727413-0010	South Face - East end at corner (scaffolding level)	8/11/07	1	3.040	Asbestos	PCME	EMSL	8/13/07	< 0.00081	No	No	
ASBESTOS-ST16-8/11/07	030727413-0011	East Face - North end at corner (scaffolding level)	8/11/07	1	3.040	Asbestos	PCME	EMSL	8/13/07	< 0.00081	No	No	
ASBESTOS-ST17-8/11/07	030724332-0012	North Face - West end at corner (scaffolding level)	8/11/07	1	2.920	Asbestos	PCME	EMSL	8/13/07	< 0.00085	No	No	
ASBESTOS-ST1-8/12/07	030727412-0001	Southwest Area (sidewalk bridge level)	8/12/07	1	3.100	Asbestos	PCME	EMSL	8/13/07	< 0.00080	No	No	
ASBESTOS-ST2-8/12/07	030727412-0002	Southeast Area (sidewalk bridge level)	8/12/07	1	3.060	Asbestos	PCME	EMSL	8/13/07	< 0.00081	No	No	
ASBESTOS-ST4-8/12/07	030727412-0003	Northwest Area (street-level)	8/12/07	1	3.170	Asbestos	PCME	EMSL	8/13/07	< 0.00078	No	No	
ASBESTOS-ST5-8/12/07	030727412-0004	Firehouse #10 (roof level)	8/12/07	1	3.010	Asbestos	PCME	EMSL	8/13/07	< 0.00082	No	No	
ASBESTOS-ST10-8/12/07	030727412-0005	North Side Sidewalk Bridge	8/12/07	1	3.190	Asbestos	PCME	EMSL	8/13/07	< 0.00077	No	No	
ASBESTOS-ST11-8/12/07	030727412-0006	90 Trinity Place (roof level)	8/12/07	1	2.960	Asbestos	PCME	EMSL	8/13/07	< 0.00083	No	No	
ASBESTOS-ST12-8/12/07	030727412-0007	110 Greenwich Street (roof level)	8/12/07	1	3.090	Asbestos	PCME	EMSL	8/13/07	< 0.00074	No	No	
ASBESTOS-ST13-8/12/07	030727412-0008	Marriott Hotel, 38th Floor (roof level)	8/12/07	1	3.020	Asbestos	PCME	EMSL	8/13/07	< 0.00082	No	No	
ASBESTOS-ST14-8/12/07	030727412-0009	West Face - South end at corner (scaffolding level)	8/12/07	1	3.010	Asbestos	PCME	EMSL	8/13/07	< 0.00082	No	No	
ASBESTOS-ST15-8/12/07	030727412-0010	South Face - East end at corner (scaffolding level)	8/12/07	1	2.980	Asbestos	PCME	EMSL	8/13/07	< 0.00083	No	No	
ASBESTOS-ST16-8/12/07	030727412-0011	East Face - North end at corner (scaffolding level)	8/12/07	1	3.000	Asbestos	PCME	EMSL	8/13/07	< 0.00082	No	No	
ASBESTOS-ST17-8/12/07	030727412-0012	North Face - West end at corner (scaffolding level)	8/12/07	1	3.000	Asbestos	PCME	EMSL	8/13/07	< 0.00082	No	No	
ASBESTOS-ST1-8/13/07	030727540-0001	Southwest Area (sidewalk bridge level)	8/13/07	1	2.990	Asbestos	PCME	EMSL	8/14/07	< 0.00083	No	No	
ASBESTOS-ST2-8/13/07	030727540-0002	Southeast Area (sidewalk bridge level)	8/13/07	1	3.110	Asbestos	PCME	EMSL	8/14/07	< 0.00079	No	No	
ASBESTOS-ST4-8/13/07	030727540-0003	Northwest Area (street-level)	8/13/07	1	2.800	Asbestos	PCME	EMSL	8/14/07	< 0.00088	No	No	
ASBESTOS-ST5-8/13/07	030727540-0004	Firehouse #10 (roof level)	8/13/07	1	3.040	Asbestos	PCME	EMSL	8/14/07	< 0.00081	No	No	
ASBESTOS-ST10-8/13/07	030727540-0005	North Side Sidewalk Bridge	8/13/07	1	2.970	Asbestos	PCME	EMSL	8/14/07	< 0.00083	No	No	
ASBESTOS-ST11-8/13/07	030727540-0006	90 Trinity Place (roof level)	8/13/07	1	2.960	Asbestos	PCME	EMSL	8/14/07	< 0.00083	No	No	
ASBESTOS-ST12-8/13/07	030727540-0007	110 Greenwich Street (roof level)	8/13/07	1	2.920	Asbestos	PCME	EMSL	8/14/07	< 0.00078	No	No	
ASBESTOS-ST13-8/13/07	030727540-0008	Marriott Hotel, 38th Floor (roof level)	8/13/07	1	3.040	Asbestos	PCME	EMSL	8/14/07	< 0.00081	No	No	
ASBESTOS-ST14-8/13/07	030727540-0009	West Face - South end at corner (scaffolding level)	8/13/07	1	2.880	Asbestos	PCME	EMSL	8/14/07	< 0.00086	No	No	
ASBESTOS-ST15-8/13/07	030727540-0010	South Face - East end at corner (scaffolding level)	8/13/07	1	3.010	Asbestos	PCME	EMSL	8/14/07	< 0.00082	No	No	
ASBESTOS-ST16-8/13/07	030727540-0011	East Face - North end at corner (scaffolding level)	8/13/07	1	3.040	Asbestos	PCME	EMSL	8/14/07	< 0.00081	No	No	
ASBESTOS-ST17-8/13/07	030727540-0012	North Face - West end at corner (scaffolding level)	8/13/07	1	2.970	Asbestos	PCME	EMSL	8/14/07	< 0.00083	No	No	