

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm ³)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-8/12/09	030920950-0001	Southwest Area (sidewalk bridge level)	8/12/09	1	2.990	Asbestos	PCME	EMSL	8/13/09	< 0.00083	No	No	
ASBESTOS-ST2-8/12/09	030920950-0002	Southeast Area (sidewalk bridge level)	8/12/09	1	2.930	Asbestos	PCME	EMSL	8/13/09	< 0.00084	No	No	
ASBESTOS-ST4-8/12/09	030920950-0003	Northwest Area (street-level)	8/12/09	1	2.980	Asbestos	PCME	EMSL	8/13/09	< 0.00083	No	No	
ASBESTOS-ST5-8/12/09	030920950-0004	Firehouse #10 (roof level)	8/12/09	1	3.090	Asbestos	PCME	EMSL	8/13/09	< 0.00080	No	No	
ASBESTOS-ST10-8/12/09	030920950-0005	North Side Sidewalk Bridge	8/12/09	1	3.070	Asbestos	PCME	EMSL	8/13/09	< 0.00080	No	No	
ASBESTOS-ST100-8/12/09	030920950-0009	Station 10 Field Duplicate	8/12/09	1	3.060	Asbestos	PCME	EMSL	8/13/09	< 0.00081	No	No	
ASBESTOS-ST11-8/12/09	030920950-0006	90 Trinity Place (roof level)	8/12/09	1	3.010	Asbestos	PCME	EMSL	8/13/09	< 0.00082	No	No	
ASBESTOS-ST12-8/12/09	030920950-0007	110 Greenwich Street (roof level)	8/12/09	1	3.070	Asbestos	PCME	EMSL	8/13/09	< 0.00080	No	No	
ASBESTOS-ST13-8/12/09	030920950-0008	Marriott Hotel, 38th Floor (roof level)	8/12/09	1	3.000	Asbestos	PCME	EMSL	8/13/09	< 0.00082	No	No	
ASBESTOS-ST1-8/13/09	030921085-0001	Southwest Area (sidewalk bridge level)	8/13/09	1	3.110	Asbestos	PCME	EMSL	8/14/09	< 0.00087	No	No	
ASBESTOS-ST2-8/13/09	030921085-0002	Southeast Area (sidewalk bridge level)	8/13/09	1	3.090	Asbestos	PCME	EMSL	8/14/09	< 0.00087	No	No	
ASBESTOS-ST4-8/13/09	030921085-0003	Northwest Area (street-level)	8/13/09	1	3.280	Asbestos	PCME	EMSL	8/14/09	< 0.00082	No	No	
ASBESTOS-ST5-8/13/09	030921085-0004	Firehouse #10 (roof level)	8/13/09	1	3.110	Asbestos	PCME	EMSL	8/14/09	< 0.00087	No	No	
ASBESTOS-ST10-8/13/09	030921085-0005	North Side Sidewalk Bridge	8/13/09	1	3.140	Asbestos	PCME	EMSL	8/14/09	< 0.00086	No	No	
ASBESTOS-ST11-8/13/09	030921085-0006	90 Trinity Place (roof level)	8/13/09	1	3.150	Asbestos	PCME	EMSL	8/14/09	< 0.00085	No	No	
ASBESTOS-ST12-8/13/09	030921085-0007	110 Greenwich Street (roof level)	8/13/09	1	3.120	Asbestos	PCME	EMSL	8/14/09	< 0.00086	No	No	
ASBESTOS-ST13-8/13/09	030921085-0008	Marriott Hotel, 38th Floor (roof level)	8/13/09	1	3.050	Asbestos	PCME	EMSL	8/14/09	< 0.00081	No	No	
ASBESTOS-ST1-8/14/09	030921133-0001	Southwest Area (sidewalk bridge level)	8/14/09	1	3.060	Asbestos	PCME	EMSL	8/15/09	< 0.00081	No	No	
ASBESTOS-ST2-8/14/09	030921133-0002	Southeast Area (sidewalk bridge level)	8/14/09	1	3.000	Asbestos	PCME	EMSL	8/15/09	< 0.00082	No	No	
ASBESTOS-ST4-8/14/09	030921133-0003	Northwest Area (street-level)	8/14/09	1	2.950	Asbestos	PCME	EMSL	8/15/09	< 0.00084	No	No	
ASBESTOS-ST5-8/14/09	030921133-0004	Firehouse #10 (roof level)	8/14/09	1	2.960	Asbestos	PCME	EMSL	8/15/09	< 0.00083	No	No	
ASBESTOS-ST10-8/14/09	030921133-0005	North Side Sidewalk Bridge	8/14/09	1	2.990	Asbestos	PCME	EMSL	8/15/09	< 0.00083	No	No	
ASBESTOS-ST11-8/14/09	030921133-0006	90 Trinity Place (roof level)	8/14/09	1	2.900	Asbestos	PCME	EMSL	8/15/09	< 0.00085	No	No	
ASBESTOS-ST12-8/14/09	030921133-0007	110 Greenwich Street (roof level)	8/14/09	1	2.940	Asbestos	PCME	EMSL	8/15/09	< 0.00084	No	No	
ASBESTOS-ST13-8/14/09	030921133-0008	Marriott Hotel, 38th Floor (roof level)	8/14/09	1	3.030	Asbestos	PCME	EMSL	8/15/09	< 0.00081	No	No	