

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-8/17/07	030728305-0001	Southwest Area (sidewalk bridge level)	8/17/07	1	3.020	Asbestos	PCME	EMSL	8/19/07	< 0.00082	No	No	
ASBESTOS-ST2-8/17/07	030728305-0002	Southeast Area (sidewalk bridge level)	8/17/07	1	3.030	Asbestos	PCME	EMSL	8/19/07	< 0.00081	No	No	
ASBESTOS-ST4-8/17/07	030728305-0003	Northwest Area (street-level)	8/17/07	1	3.020	Asbestos	PCME	EMSL	8/19/07	< 0.00082	No	No	
ASBESTOS-ST5-8/17/07	030728305-0004	Firehouse #10 (roof level)	8/17/07	1	3.020	Asbestos	PCME	EMSL	8/19/07	< 0.00082	No	No	
ASBESTOS-ST10-8/17/07	030728305-0005	North Side Sidewalk Bridge	8/17/07	1	3.000	Asbestos	PCME	EMSL	8/19/07	< 0.00082	No	No	
ASBESTOS-ST11-8/17/07	030728305-0006	90 Trinity Place (roof level)	8/17/07	1	2.970	Asbestos	PCME	EMSL	8/19/07	< 0.00083	No	No	
ASBESTOS-ST12-8/17/07	030728305-0007	110 Greenwich Street (roof level)	8/17/07	1	3.050	Asbestos	PCME	EMSL	8/19/07	< 0.00081	No	No	
ASBESTOS-ST13-8/17/07	030728305-0008	Marriott Hotel, 38th Floor (roof level)	8/17/07	1	3.010	Asbestos	PCME	EMSL	8/19/07	< 0.00082	No	No	
ASBESTOS-ST14-8/17/07	030728305-0009	West Face - South end at corner (scaffolding level)	8/17/07	1	3.010	Asbestos	PCME	EMSL	8/19/07	< 0.00082	No	No	
ASBESTOS-ST15-8/17/07	030728305-0010	South Face - East end at corner (scaffolding level)	8/17/07	1	3.020	Asbestos	PCME	EMSL	8/19/07	< 0.00082	No	No	
ASBESTOS-ST16-8/17/07	030728305-0011	East Face - North end at corner (scaffolding level)	8/17/07	1	3.030	Asbestos	PCME	EMSL	8/19/07	< 0.00081	No	No	
ASBESTOS-ST17-8/17/07	030728305-0012	North Face - West end at corner (scaffolding level)	8/17/07	1	3.020	Asbestos	PCME	EMSL	8/19/07	< 0.00082	No	No	
ASBESTOS-ST1-8/18/07	030728279-0001	Southwest Area (sidewalk bridge level)	8/18/07	1	2.750	Asbestos	PCME	EMSL	8/19/07	< 0.00083	No	No	
ASBESTOS-ST2-8/18/07	030728279-0002	Southeast Area (sidewalk bridge level)	8/18/07	1	2.770	Asbestos	PCME	EMSL	8/19/07	< 0.00082	No	No	
ASBESTOS-ST5-8/18/07	030728278-0001	Firehouse #10 (roof level)	8/18/07	1	2.430	Asbestos	PCME	EMSL	8/19/07	< 0.00087	No	No	
ASBESTOS-ST10-8/18/07	030728278-0002	North Side Sidewalk Bridge	8/18/07	1	2.590	Asbestos	PCME	EMSL	8/19/07	< 0.00088	No	No	
ASBESTOS-ST11-8/18/07	030728288-0006	90 Trinity Place (roof level)	8/18/07	1	2.990	Asbestos	PCME	EMSL	8/19/07	< 0.00083	No	No	
ASBESTOS-ST12-8/18/07	030728278-0003	110 Greenwich Street (roof level)	8/18/07	1	2.470	Asbestos	PCME	EMSL	8/19/07	< 0.00086	No	No	
ASBESTOS-ST13-8/18/07	030728278-0004	Marriott Hotel, 38th Floor (roof level)	8/18/07	1	2.440	Asbestos	PCME	EMSL	8/19/07	< 0.00087	No	No	
ASBESTOS-ST1-8/19/07	030729526-0001	Southwest Area (sidewalk bridge level)	8/19/07	1	23.750	Asbestos	PCME	EMSL	8/28/07	0.0001	No	No	Result represents conditions from 8/19/07 through 8/28/07
ASBESTOS-ST4-8/19/07	030728415-0001	Northwest Area (street-level)	8/19/07	1	2.830	Asbestos	PCME	EMSL	8/20/07	< 0.00087	No	No	
ASBESTOS-ST5-8/19/07	030728415-0002	Firehouse #10 (roof level)	8/19/07	1	3.210	Asbestos	PCME	EMSL	8/20/07	< 0.00077	No	No	
ASBESTOS-ST10-8/19/07	030728415-0003	North Side Sidewalk Bridge	8/19/07	1	3.010	Asbestos	PCME	EMSL	8/20/07	< 0.00082	No	No	
ASBESTOS-ST11-8/19/07	030728415-0004	90 Trinity Place (roof level)	8/19/07	1	3.090	Asbestos	PCME	EMSL	8/20/07	< 0.00080	No	No	
ASBESTOS-ST12-8/19/07	030728415-0005	110 Greenwich Street (roof level)	8/19/07	1	2.960	Asbestos	PCME	EMSL	8/20/07	< 0.00083	No	No	
ASBESTOS-ST13-8/19/07	030728415-0006	Marriott Hotel, 38th Floor (roof level)	8/19/07	1	3.000	Asbestos	PCME	EMSL	8/20/07	< 0.00082	No	No	
ASBESTOS-ST17-8/19/07	030729351-0006	North Face - West end at corner (scaffolding level)	8/19/07	1	23.680	Asbestos	PCME	EMSL	8/27/07	0.00008	No	No	Result represents conditions from 8/19/07 through 8/27/07

Note:

1. Asbestos results at Station 4 (Northwest Area [street-level]), Station 15 [South Face - East end at corner [scaffolding level]], Station 16 (East Face - North end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]), on August 18, 2007 were not available as these samples were overloaded with carbanaceous particulate and completely obs
2. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]) on August 18, 2007 was not available for analysis on account of power failure.
3. Asbestos sample at Station 2 (Southeast Area [sidewalk bridge level]) on August 19, 2007 is not available as this sample was overloaded with carbanaceous particulate and completely obscured and could therefore not be analyzed.
4. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]) on August 19, 2007 was not available for analysis on account of pump failure.
5. Asbestos results at Station 15 [South Face - East end at corner [scaffolding level]] and Station 16 (East Face - North end at corner [scaffolding level]) on August 19, 2007 were not available as these samples were overloaded with carbanaceous particulate and completely obscured and could therefore not be analyzed.

scured and could therefore not be analyzed.