

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-8/18/06	030627220-0001	Southwest Area (sidewalk bridge level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST2-8/18/06	030627220-0002	Southeast Area (sidewalk bridge level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST4-8/18/06	030627220-0003	Northwest Area (street-level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST5-8/18/06	030627220-0004	Firehouse #10 (roof level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST6-8/18/06	030627221-0001	Southwest Area (roof level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST7-8/18/06	030627221-0002	Southeast Area (roof level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST8-8/18/06	030627221-0003	Northeast Area (roof level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST9-8/18/06	030627221-0004	Northwest Area (roof level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST10-8/18/06	030627220-0005	North Side Sidewalk Bridge	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST11-8/18/06	030627220-0006	90 Trinity Place (roof level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST12-8/18/06	030627220-0007	110 Greenwich Street (roof level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST13-8/18/06	030627220-0008	Marriott Hotel, 38th Floor (roof level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST14-8/18/06	030627220-0009	West Face - South end at corner (scaffolding level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST15-8/18/06	030627220-0010	South Face - East end at corner (scaffolding level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST16-8/18/06	030627220-0011	East Face - North end at corner (scaffolding level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST17-8/18/06	030627220-0012	North Face - West end at corner (scaffolding level)	8/18/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST1-8/19/06	030627222-0001	Southwest Area (sidewalk bridge level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST2-8/19/06	030627222-0002	Southeast Area (sidewalk bridge level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST4-8/19/06	030627222-0003	Northwest Area (street-level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST5-8/19/06	030627222-0004	Firehouse #10 (roof level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST6-8/19/06	030627223-0001	Southwest Area (roof level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST7-8/19/06	030627223-0002	Southeast Area (roof level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST9-8/19/06	030627223-0003	Northwest Area (roof level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST10-8/19/06	030627222-0005	North Side Sidewalk Bridge	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST11-8/19/06	030627222-0006	90 Trinity Place (roof level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST12-8/19/06	030627222-0007	110 Greenwich Street (roof level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST13-8/19/06	030627222-0008	Marriott Hotel, 38th Floor (roof level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST14-8/19/06	030627222-0009	West Face - South end at corner (scaffolding level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST15-8/19/06	030627222-0010	South Face - East end at corner (scaffolding level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST16-8/19/06	030627222-0011	East Face - North end at corner (scaffolding level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST17-8/19/06	030627222-0012	North Face - West end at corner (scaffolding level)	8/19/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST1-8/20/06	030627224-0001	Southwest Area (sidewalk bridge level)	8/20/06	1	3.060	Asbestos	PCME	EMSL	8/21/06	< 0.00081	No	No	
ASBESTOS-ST2-8/20/06	030627224-0002	Southeast Area (sidewalk bridge level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST4-8/20/06	030627224-0003	Northwest Area (street-level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST5-8/20/06	030627224-0004	Firehouse #10 (roof level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST6-8/20/06	030627225-0001	Southwest Area (roof level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST7-8/20/06	030627225-0002	Southeast Area (roof level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST8-8/20/06	030627225-0003	Northeast Area (roof level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST9-8/20/06	030627225-0004	Northwest Area (roof level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST10-8/20/06	030627224-0005	North Side Sidewalk Bridge	8/20/06	1	3.060	Asbestos	PCME	EMSL	8/21/06	< 0.00081	No	No	
ASBESTOS-ST11-8/20/06	030627224-0006	90 Trinity Place (roof level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST12-8/20/06	030627224-0007	110 Greenwich Street (roof level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST13-8/20/06	030627224-0008	Marriott Hotel, 38th Floor (roof level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST14-8/20/06	030627224-0009	West Face - South end at corner (scaffolding level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST15-8/20/06	030627224-0010	South Face - East end at corner (scaffolding level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST16-8/20/06	030627224-0011	East Face - North end at corner (scaffolding level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	
ASBESTOS-ST17-8/20/06	030627224-0012	North Face - West end at corner (scaffolding level)	8/20/06	1	2.970	Asbestos	PCME	EMSL	8/21/06	< 0.00083	No	No	

Note:

- Asbestos sample at Station 8 (Northeast Area [roof level]) on August 19, 2006 was not available for analysis on account of temporary power failure.