

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009				
										NA				
Target Air Quality Levels										0.0009		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels										NA				
ASBESTOS-ST1-8/25/06	030628093-0001	Southwest Area (sidewalk bridge level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	0.00083	No			
ASBESTOS-ST2-8/25/06	030628093-0002	Southeast Area (sidewalk bridge level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST4-8/25/06	030628093-0003	Northwest Area (street-level)	8/25/06	1	3.020	Asbestos	PCME	EMSL	8/28/06	< 0.00082	No	No		
ASBESTOS-ST5-8/25/06	030628093-0004	Firehouse #10 (roof level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST6-8/25/06	030628094-0001	Southwest Area (roof level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST7-8/25/06	030628094-0002	Southeast Area (roof level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST8-8/25/06	030628094-0003	Northeast Area (roof level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST9-8/25/06	030628094-0004	Northwest Area (roof level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST10-8/25/06	030628093-0005	North Side Sidewalk Bridge	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST11-8/25/06	030628093-0006	90 Trinity Place (roof level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST12-8/25/06	030628093-0007	110 Greenwich Street (roof level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST13-8/25/06	030628093-0008	Marriott Hotel, 38th Floor (roof level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST14-8/25/06	030628093-0009	West Face - South end at corner (scaffolding level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST15-8/25/06	030628093-0010	South Face - East end at corner (scaffolding level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST16-8/25/06	030628093-0011	East Face - North end at corner (scaffolding level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST17-8/25/06	030628093-0012	North Face - West end at corner (scaffolding level)	8/25/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST1-8/26/06	030628095-0001	Southwest Area (sidewalk bridge level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST2-8/26/06	030628095-0002	Southeast Area (sidewalk bridge level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST4-8/26/06	030628095-0003	Northwest Area (street-level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST5-8/26/06	030628095-0004	Firehouse #10 (roof level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST6-8/26/06	030628096-0001	Southwest Area (roof level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST7-8/26/06	030628096-0002	Southeast Area (roof level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST8-8/26/06	030628096-0003	Northeast Area (roof level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST9-8/26/06	030628096-0004	Northwest Area (roof level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST10-8/26/06	030628095-0005	North Side Sidewalk Bridge	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST11-8/26/06	030628095-0006	90 Trinity Place (roof level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST12-8/26/06	030628095-0007	110 Greenwich Street (roof level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST13-8/26/06	030628095-0008	Marriott Hotel, 38th Floor (roof level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST14-8/26/06	030628095-0009	West Face - South end at corner (scaffolding level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST15-8/26/06	030628095-0010	South Face - East end at corner (scaffolding level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST16-8/26/06	030628095-0011	East Face - North end at corner (scaffolding level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST17-8/26/06	030628095-0012	North Face - West end at corner (scaffolding level)	8/26/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST1-8/27/06	030628097-0001	Southwest Area (sidewalk bridge level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST2-8/27/06	030628097-0002	Southeast Area (sidewalk bridge level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST4-8/27/06	030628097-0003	Northwest Area (street-level)	8/27/06	1	3.150	Asbestos	PCME	EMSL	8/28/06	< 0.00078	No	No		
ASBESTOS-ST5-8/27/06	030628097-0004	Firehouse #10 (roof level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST6-8/27/06	030628098-0001	Southwest Area (roof level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	0.00083	No	No		
ASBESTOS-ST7-8/27/06	030628098-0002	Southeast Area (roof level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST8-8/27/06	030628098-0003	Northeast Area (roof level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST9-8/27/06	030628098-0004	Northwest Area (roof level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST10-8/27/06	030628097-0005	North Side Sidewalk Bridge	8/27/06	1	3.020	Asbestos	PCME	EMSL	8/28/06	< 0.00082	No	No		
ASBESTOS-ST11-8/27/06	030628097-0006	90 Trinity Place (roof level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST12-8/27/06	030628097-0007	110 Greenwich Street (roof level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST13-8/27/06	030628097-0008	Marriott Hotel, 38th Floor (roof level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST15-8/27/06	030628097-0009	South Face - East end at corner (scaffolding level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST16-8/27/06	030628097-0010	East Face - North end at corner (scaffolding level)	8/27/06	1	2.970	Asbestos	PCME	EMSL	8/28/06	< 0.00083	No	No		
ASBESTOS-ST1-8/28/06	030628251-0001	Southwest Area (sidewalk bridge level)	8/28/06	1	2.970	Asbestos	PCME	EMSL	8/29/06	< 0.00083	No	No		
ASBESTOS-ST2-8/28/06	030628251-0002	Southeast Area (sidewalk bridge level)	8/28/06	1	2.970	Asbestos	PCME	EMSL	8/29/06	< 0.00083	No	No		
ASBESTOS-ST4-8/28/06	030628251-0003	Northwest Area (street-level)	8/28/06	1	3.020	Asbestos	PCME	EMSL	8/29/06	< 0.00082	No	No		
ASBESTOS-ST5-8/28/06	030628251-0004	Firehouse #10 (roof level)	8/28/06	1	2.970	Asbestos	PCME	EMSL	8/29/06	< 0.00083	No	No		
ASBESTOS-ST6-8/28/06	030628252-0001	Southwest Area (roof level)	8/28/06	1	3.060	Asbestos	PCME	EMSL	8/29/06	< 0.00081	No	No		
ASBESTOS-ST7-8/28/06	030628252-0002	Southeast Area (roof level)	8/28/06	1	2.970	Asbestos	PCME	EMSL	8/29/06	< 0.00083	No	No		
ASBESTOS-ST8-8/28/06	030628252-0003	Northeast Area (roof level)	8/28/06	1	3.020	Asbestos	PCME	EMSL	8/29/06	< 0.00082	No	No		
ASBESTOS-ST9-8/28/06	030628252-0004	Northwest Area (roof level)	8/28/06	1	2.970	Asbestos	PCME	EMSL	8/29/06	< 0.00083	No	No		
ASBESTOS-ST10-8/28/06	030628251-0005	North Side Sidewalk Bridge	8/28/06	1	2.970	Asbestos	PCME	EMSL	8/29/06	< 0.00083	No	No		
ASBESTOS-ST11-8/28/06	030628251-0006	90 Trinity Place (roof level)	8/28/06	1	2.750	Asbestos	PCME	EMSL	8/29/06	< 0.00083	No	No		
ASBESTOS-ST12-8/28/06	030628251-0007	110 Greenwich Street (roof level)	8/28/06	1	2.880	Asbestos	PCME	EMSL	8/29/06	< 0.00086	No	No		
ASBESTOS-ST13-8/28/06	030628251-0008	Marriott Hotel, 38th Floor (roof level)	8/28/06	1	2.930	Asbestos	PCME	EMSL	8/29/06	< 0.00084	No	No		
ASBESTOS-ST14-8/28/06	030628251-0009	West Face - South end at corner (scaffolding level)	8/28/06	1	3.060	Asbestos	PCME	EMSL	8/29/06	< 0.00081	No	No		
ASBESTOS-ST15-8/28/06	030628251-0010	South Face - East end at corner (scaffolding level)	8/28/06	1	2.930	Asbestos	PCME	EMSL	8/29/06	< 0.00084	No	No		
ASBESTOS-ST16-8/28/06	030628251-0011	East Face - North end at corner (scaffolding level)	8/28/06	1	2.970	Asbestos	PCME	EMSL	8/29/06	< 0.00083	No	No		
ASBESTOS-ST17-8/28/06	030628251-0012	North Face - West end at corner (scaffolding level)	8/28/06	1	2.970	Asbestos	PCME	EMSL	8/29/06	< 0.00083	No	No		

Note:
1. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]) on August 27, 2006 were not available for analysis on account of pump failure.