

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Site Specific	
										NA	Levels	Trigger Levels	
ASBESTOS-ST1-8/28/07	030729658-0001	Southwest Area (sidewalk bridge level)	8/28/07	1	2.100	Asbestos	PCME	EMSL	8/29/07	< 0.00088	No	No	
ASBESTOS-ST2-8/28/07	030729658-0002	Southeast Area (sidewalk bridge level)	8/28/07	1	2.090	Asbestos	PCME	EMSL	8/29/07	< 0.00089	No	No	
ASBESTOS-ST4-8/28/07	030729658-0003	Northwest Area (street-level)	8/28/07	1	2.070	Asbestos	PCME	EMSL	8/29/07	< 0.00089	No	No	
ASBESTOS-ST5-8/28/07	030729658-0004	Firehouse #10 (roof level)	8/28/07	1	3.000	Asbestos	PCME	EMSL	8/29/07	< 0.00082	No	No	
ASBESTOS-ST10-8/28/07	030729658-0005	North Side Sidewalk Bridge	8/28/07	1	2.970	Asbestos	PCME	EMSL	8/29/07	< 0.00083	No	No	
ASBESTOS-ST11-8/28/07	030729658-0006	90 Trinity Place (roof level)	8/28/07	1	3.090	Asbestos	PCME	EMSL	8/29/07	< 0.00080	No	No	
ASBESTOS-ST12-8/28/07	030729658-0007	110 Greenwich Street (roof level)	8/28/07	1	2.960	Asbestos	PCME	EMSL	8/29/07	< 0.00083	No	No	
ASBESTOS-ST13-8/28/07	030729658-0008	Marriott Hotel, 38th Floor (roof level)	8/28/07	1	2.970	Asbestos	PCME	EMSL	8/29/07	< 0.00083	No	No	
ASBESTOS-ST14-8/28/07	030729658-0009	West Face - South end at corner (scaffolding level)	8/28/07	1	3.070	Asbestos	PCME	EMSL	8/29/07	< 0.00080	No	No	
ASBESTOS-ST15-8/28/07	030729658-0010	South Face - East end at corner (scaffolding level)	8/28/07	1	2.930	Asbestos	PCME	EMSL	8/29/07	< 0.00084	No	No	
ASBESTOS-ST16-8/28/07	030729658-0011	East Face - North end at corner (scaffolding level)	8/28/07	1	3.010	Asbestos	PCME	EMSL	8/29/07	< 0.00082	No	No	
ASBESTOS-ST17-8/28/07	030729658-0012	North Face - West end at corner (scaffolding level)	8/28/07	1	3.010	Asbestos	PCME	EMSL	8/29/07	< 0.00082	No	No	
ASBESTOS-ST1-8/29/07	030729839-0001	Southwest Area (sidewalk bridge level)	8/29/07	1	3.060	Asbestos	PCME	EMSL	8/30/07	< 0.00081	No	No	
ASBESTOS-ST2-8/29/07	030729839-0002	Southeast Area (sidewalk bridge level)	8/29/07	1	2.990	Asbestos	PCME	EMSL	8/30/07	< 0.00083	No	No	
ASBESTOS-ST4-8/29/07	030729839-0003	Northwest Area (street-level)	8/29/07	1	3.030	Asbestos	PCME	EMSL	8/30/07	< 0.00081	No	No	
ASBESTOS-ST5-8/29/07	030729839-0004	Firehouse #10 (roof level)	8/29/07	1	3.000	Asbestos	PCME	EMSL	8/30/07	< 0.00082	No	No	
ASBESTOS-ST10-8/29/07	030729839-0005	North Side Sidewalk Bridge	8/29/07	1	2.950	Asbestos	PCME	EMSL	8/30/07	< 0.00084	No	No	
ASBESTOS-ST11-8/29/07	030729839-0006	90 Trinity Place (roof level)	8/29/07	1	3.000	Asbestos	PCME	EMSL	8/30/07	< 0.00082	No	No	
ASBESTOS-ST12-8/29/07	030729839-0007	110 Greenwich Street (roof level)	8/29/07	1	3.090	Asbestos	PCME	EMSL	8/30/07	< 0.00087	No	No	
ASBESTOS-ST13-8/29/07	030729839-0008	Marriott Hotel, 38th Floor (roof level)	8/29/07	1	3.060	Asbestos	PCME	EMSL	8/30/07	< 0.00088	No	No	
ASBESTOS-ST14-8/29/07	030729839-0009	West Face - South end at corner (scaffolding level)	8/29/07	1	3.030	Asbestos	PCME	EMSL	8/30/07	< 0.00081	No	No	
ASBESTOS-ST15-8/29/07	030729839-0010	South Face - East end at corner (scaffolding level)	8/29/07	1	3.040	Asbestos	PCME	EMSL	8/30/07	< 0.00089	No	No	
ASBESTOS-ST16-8/29/07	030729839-0011	East Face - North end at corner (scaffolding level)	8/29/07	1	3.060	Asbestos	PCME	EMSL	8/30/07	< 0.00088	No	No	
ASBESTOS-ST17-8/29/07	030729839-0012	North Face - West end at corner (scaffolding level)	8/29/07	1	3.060	Asbestos	PCME	EMSL	8/30/07	< 0.00088	No	No	
ASBESTOS-ST1-8/30/07	030730020-0001	Southwest Area (sidewalk bridge level)	8/30/07	1	3.050	Asbestos	PCME	EMSL	8/31/07	< 0.00081	No	No	
ASBESTOS-ST2-8/30/07	030730020-0002	Southeast Area (sidewalk bridge level)	8/30/07	1	3.040	Asbestos	PCME	EMSL	8/31/07	< 0.00081	No	No	
ASBESTOS-ST4-8/30/07	030730020-0003	Northwest Area (street-level)	8/30/07	1	3.030	Asbestos	PCME	EMSL	8/31/07	< 0.00081	No	No	
ASBESTOS-ST5-8/30/07	030730020-0004	Firehouse #10 (roof level)	8/30/07	1	3.150	Asbestos	PCME	EMSL	8/31/07	< 0.00078	No	No	
ASBESTOS-ST10-8/30/07	030730020-0005	North Side Sidewalk Bridge	8/30/07	1	2.970	Asbestos	PCME	EMSL	8/31/07	< 0.00083	No	No	
ASBESTOS-ST11-8/30/07	030730020-0006	90 Trinity Place (roof level)	8/30/07	1	3.000	Asbestos	PCME	EMSL	8/31/07	< 0.00082	No	No	
ASBESTOS-ST12-8/30/07	030730020-0007	110 Greenwich Street (roof level)	8/30/07	1	2.920	Asbestos	PCME	EMSL	8/31/07	< 0.00085	No	No	
ASBESTOS-ST13-8/30/07	030730020-0008	Marriott Hotel, 38th Floor (roof level)	8/30/07	1	3.040	Asbestos	PCME	EMSL	8/31/07	< 0.00081	No	No	
ASBESTOS-ST14-8/30/07	030730020-0009	West Face - South end at corner (scaffolding level)	8/30/07	1	3.040	Asbestos	PCME	EMSL	8/31/07	< 0.00081	No	No	
ASBESTOS-ST15-8/30/07	030730020-0010	South Face - East end at corner (scaffolding level)	8/30/07	1	3.040	Asbestos	PCME	EMSL	8/31/07	< 0.00081	No	No	
ASBESTOS-ST16-8/30/07	030730020-0011	East Face - North end at corner (scaffolding level)	8/30/07	1	3.060	Asbestos	PCME	EMSL	8/31/07	< 0.00081	No	No	
ASBESTOS-ST17-8/30/07	030730020-0012	North Face - West end at corner (scaffolding level)	8/30/07	1	3.060	Asbestos	PCME	EMSL	8/31/07	< 0.00081	No	No	
ASBESTOS-ST1-8/31/07	030730103-0001	Southwest Area (sidewalk bridge level)	8/31/07	1	2.970	Asbestos	PCME	EMSL	9/1/07	< 0.00083	No	No	
ASBESTOS-ST2-8/31/07	030730103-0002	Southeast Area (sidewalk bridge level)	8/31/07	1	3.020	Asbestos	PCME	EMSL	9/1/07	< 0.00082	No	No	
ASBESTOS-ST4-8/31/07	030730103-0003	Northwest Area (street-level)	8/31/07	1	2.970	Asbestos	PCME	EMSL	9/1/07	< 0.00083	No	No	
ASBESTOS-ST5-8/31/07	030730103-0004	Firehouse #10 (roof level)	8/31/07	1	3.020	Asbestos	PCME	EMSL	9/1/07	< 0.00082	No	No	
ASBESTOS-ST10-8/31/07	030730103-0005	North Side Sidewalk Bridge	8/31/07	1	3.040	Asbestos	PCME	EMSL	9/1/07	< 0.00081	No	No	
ASBESTOS-ST11-8/31/07	030730103-0006	90 Trinity Place (roof level)	8/31/07	1	2.960	Asbestos	PCME	EMSL	9/1/07	< 0.00083	No	No	
ASBESTOS-ST12-8/31/07	030730103-0007	110 Greenwich Street (roof level)	8/31/07	1	3.020	Asbestos	PCME	EMSL	9/1/07	< 0.00082	No	No	
ASBESTOS-ST13-8/31/07	030730103-0008	Marriott Hotel, 38th Floor (roof level)	8/31/07	1	3.010	Asbestos	PCME	EMSL	9/1/07	< 0.00082	No	No	
ASBESTOS-ST14-8/31/07	030730103-0009	West Face - South end at corner (scaffolding level)	8/31/07	1	3.030	Asbestos	PCME	EMSL	9/1/07	< 0.00081	No	No	
ASBESTOS-ST15-8/31/07	030730103-0010	South Face - East end at corner (scaffolding level)	8/31/07	1	3.040	Asbestos	PCME	EMSL	9/1/07	< 0.00081	No	No	
ASBESTOS-ST16-8/31/07	030730103-0011	East Face - North end at corner (scaffolding level)	8/31/07	1	3.060	Asbestos	PCME	EMSL	9/1/07	< 0.00081	No	No	
ASBESTOS-ST17-8/31/07	030730103-0012	North Face - West end at corner (scaffolding level)	8/31/07	1	3.040	Asbestos	PCME	EMSL	9/1/07	< 0.00081	No	No	