

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-8/29/09	030922673-0001	Southwest Area (sidewalk bridge level)	8/29/09	1	3.120	Asbestos	PCME	EMSL	8/31/09	< 0.00079	No	No	
ASBESTOS-ST2-8/29/09	030922673-0002	Southeast Area (sidewalk bridge level)	8/29/09	1	3.030	Asbestos	PCME	EMSL	8/31/09	< 0.00081	No	No	
ASBESTOS-ST4-8/29/09	030922673-0003	Northwest Area (street-level)	8/29/09	1	3.060	Asbestos	PCME	EMSL	8/31/09	< 0.00081	No	No	
ASBESTOS-ST5-8/29/09	030922673-0004	Firehouse #10 (roof level)	8/29/09	1	2.980	Asbestos	PCME	EMSL	8/31/09	< 0.00083	No	No	
ASBESTOS-ST10-8/29/09	030922673-0005	North Side Sidewalk Bridge	8/29/09	1	3.030	Asbestos	PCME	EMSL	8/31/09	< 0.00081	No	No	
ASBESTOS-ST11-8/29/09	030922673-0006	90 Trinity Place (roof level)	8/29/09	1	3.050	Asbestos	PCME	EMSL	8/31/09	< 0.00081	No	No	
ASBESTOS-ST12-8/29/09	030922673-0007	110 Greenwich Street (roof level)	8/29/09	1	3.060	Asbestos	PCME	EMSL	8/31/09	< 0.00081	No	No	
ASBESTOS-ST13-8/29/09	030922673-0008	Marriott Hotel, 38th Floor (roof level)	8/29/09	1	3.020	Asbestos	PCME	EMSL	8/31/09	< 0.00082	No	No	
ASBESTOS-ST1-8/30/09	030922672-0001	Southwest Area (sidewalk bridge level)	8/30/09	1	3.060	Asbestos	PCME	EMSL	8/31/09	< 0.00081	No	No	
ASBESTOS-ST2-8/30/09	030922672-0002	Southeast Area (sidewalk bridge level)	8/30/09	1	2.990	Asbestos	PCME	EMSL	8/31/09	< 0.00083	No	No	
ASBESTOS-ST4-8/30/09	030922672-0003	Northwest Area (street-level)	8/30/09	1	3.050	Asbestos	PCME	EMSL	8/31/09	< 0.00081	No	No	
ASBESTOS-ST5-8/30/09	030922672-0004	Firehouse #10 (roof level)	8/30/09	1	3.010	Asbestos	PCME	EMSL	8/31/09	< 0.00082	No	No	
ASBESTOS-ST10-8/30/09	030922672-0005	North Side Sidewalk Bridge	8/30/09	1	3.020	Asbestos	PCME	EMSL	8/31/09	< 0.00082	No	No	
ASBESTOS-ST11-8/30/09	030922672-0006	90 Trinity Place (roof level)	8/30/09	1	3.150	Asbestos	PCME	EMSL	8/31/09	< 0.00078	No	No	
ASBESTOS-ST12-8/30/09	030922672-0007	110 Greenwich Street (roof level)	8/30/09	1	3.200	Asbestos	PCME	EMSL	8/31/09	< 0.00077	No	No	
ASBESTOS-ST13-8/30/09	030922672-0008	Marriott Hotel, 38th Floor (roof level)	8/30/09	1	2.980	Asbestos	PCME	EMSL	8/31/09	< 0.00083	No	No	
ASBESTOS-ST1-8/31/09	030922754-0001	Southwest Area (sidewalk bridge level)	8/31/09	1	3.110	Asbestos	PCME	EMSL	9/1/09	< 0.00079	No	No	
ASBESTOS-ST2-8/31/09	030922754-0002	Southeast Area (sidewalk bridge level)	8/31/09	1	3.020	Asbestos	PCME	EMSL	9/1/09	< 0.00082	No	No	
ASBESTOS-ST4-8/31/09	030922754-0003	Northwest Area (street-level)	8/31/09	1	3.070	Asbestos	PCME	EMSL	9/1/09	< 0.00080	No	No	
ASBESTOS-ST5-8/31/09	030922754-0004	Firehouse #10 (roof level)	8/31/09	1	3.010	Asbestos	PCME	EMSL	9/1/09	< 0.00082	No	No	
ASBESTOS-ST10-8/31/09	030922754-0005	North Side Sidewalk Bridge	8/31/09	1	3.010	Asbestos	PCME	EMSL	9/1/09	< 0.00082	No	No	
ASBESTOS-ST11-8/31/09	030922754-0006	90 Trinity Place (roof level)	8/31/09	1	2.910	Asbestos	PCME	EMSL	9/1/09	< 0.00085	No	No	
ASBESTOS-ST12-8/31/09	030922754-0007	110 Greenwich Street (roof level)	8/31/09	1	3.080	Asbestos	PCME	EMSL	9/1/09	< 0.00080	No	No	
ASBESTOS-ST13-8/31/09	030922754-0008	Marriott Hotel, 38th Floor (roof level)	8/31/09	1	3.070	Asbestos	PCME	EMSL	9/1/09	< 0.00080	No	No	