

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-9/12/07	030731127-0001	Southwest Area (sidewalk bridge level)	9/12/07	1	2.840	Asbestos	PCME	EMSL	9/13/07	< 0.00087	No	No	
ASBESTOS-ST2-9/12/07	030731127-0002	Southeast Area (sidewalk bridge level)	9/12/07	1	2.960	Asbestos	PCME	EMSL	9/13/07	< 0.00083	No	No	
ASBESTOS-ST4-9/12/07	030731127-0003	Northwest Area (street-level)	9/12/07	1	2.880	Asbestos	PCME	EMSL	9/13/07	< 0.00086	No	No	
ASBESTOS-ST5-9/12/07	030731127-0004	Firehouse #10 (roof level)	9/12/07	1	3.040	Asbestos	PCME	EMSL	9/13/07	< 0.00081	No	No	
ASBESTOS-ST10-9/12/07	030731127-0005	North Side Sidewalk Bridge	9/12/07	1	3.010	Asbestos	PCME	EMSL	9/13/07	< 0.00082	No	No	
ASBESTOS-ST100-9/12/07	030731127-0013	Station 10 Field Duplicate	9/12/07	1	3.070	Asbestos	PCME	EMSL	9/13/07	< 0.00080	No	No	
ASBESTOS-ST11-9/12/07	030731127-0006	90 Trinity Place (roof level)	9/12/07	1	3.000	Asbestos	PCME	EMSL	9/13/07	< 0.00082	No	No	
ASBESTOS-ST12-9/12/07	030731127-0007	110 Greenwich Street (roof level)	9/12/07	1	3.090	Asbestos	PCME	EMSL	9/13/07	< 0.00080	No	No	
ASBESTOS-ST13-9/12/07	030731127-0008	Marriott Hotel, 38th Floor (roof level)	9/12/07	1	3.040	Asbestos	PCME	EMSL	9/13/07	< 0.00081	No	No	
ASBESTOS-ST14-9/12/07	030731127-0009	West Face - South end at corner (scaffolding level)	9/12/07	1	2.280	Asbestos	PCME	EMSL	9/13/07	< 0.00087	No	No	
ASBESTOS-ST15-9/12/07	030731127-0010	South Face - East end at corner (scaffolding level)	9/12/07	1	2.250	Asbestos	PCME	EMSL	9/13/07	< 0.00088	No	No	
ASBESTOS-ST16-9/12/07	030731127-0011	East Face - North end at corner (scaffolding level)	9/12/07	1	2.300	Asbestos	PCME	EMSL	9/13/07	< 0.00086	No	No	
ASBESTOS-ST17-9/12/07	030731127-0012	North Face - West end at corner (scaffolding level)	9/12/07	1	2.230	Asbestos	PCME	EMSL	9/13/07	< 0.00089	No	No	
ASBESTOS-ST1-9/13/07	030731242-0001	Southwest Area (sidewalk bridge level)	9/13/07	1	3.060	Asbestos	PCME	EMSL	9/14/07	< 0.00081	No	No	
ASBESTOS-ST2-9/13/07	030731242-0002	Southeast Area (sidewalk bridge level)	9/13/07	1	3.050	Asbestos	PCME	EMSL	9/14/07	< 0.00081	No	No	
ASBESTOS-ST4-9/13/07	030731242-0003	Northwest Area (street-level)	9/13/07	1	2.990	Asbestos	PCME	EMSL	9/14/07	< 0.00083	No	No	
ASBESTOS-ST5-9/13/07	030731242-0004	Firehouse #10 (roof level)	9/13/07	1	3.090	Asbestos	PCME	EMSL	9/14/07	< 0.00080	No	No	
ASBESTOS-ST10-9/13/07	030731242-0005	North Side Sidewalk Bridge	9/13/07	1	2.990	Asbestos	PCME	EMSL	9/14/07	< 0.00083	No	No	
ASBESTOS-ST11-9/13/07	030731242-0006	90 Trinity Place (roof level)	9/13/07	1	3.060	Asbestos	PCME	EMSL	9/14/07	< 0.00081	No	No	
ASBESTOS-ST12-9/13/07	030731242-0007	110 Greenwich Street (roof level)	9/13/07	1	3.020	Asbestos	PCME	EMSL	9/14/07	< 0.00082	No	No	
ASBESTOS-ST13-9/13/07	030731242-0008	Marriott Hotel, 38th Floor (roof level)	9/13/07	1	3.040	Asbestos	PCME	EMSL	9/14/07	< 0.00081	No	No	
ASBESTOS-ST14-9/13/07	030731242-0009	West Face - South end at corner (scaffolding level)	9/13/07	1	3.000	Asbestos	PCME	EMSL	9/14/07	< 0.00082	No	No	
ASBESTOS-ST15-9/13/07	030731242-0010	South Face - East end at corner (scaffolding level)	9/13/07	1	3.060	Asbestos	PCME	EMSL	9/14/07	< 0.00081	No	No	
ASBESTOS-ST16-9/13/07	030731242-0011	East Face - North end at corner (scaffolding level)	9/13/07	1	3.000	Asbestos	PCME	EMSL	9/14/07	< 0.00082	No	No	
ASBESTOS-ST17-9/13/07	030731242-0012	North Face - West end at corner (scaffolding level)	9/13/07	1	3.010	Asbestos	PCME	EMSL	9/14/07	< 0.00082	No	No	