

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-9/15/08	030832434-0001	Southwest Area (sidewalk bridge level)	9/15/08	1	3.130	Asbestos	PCME	EMSL	9/16/08	< 0.00079	No	No	
ASBESTOS-ST2-9/15/08	030832434-0002	Southeast Area (sidewalk bridge level)	9/15/08	1	3.190	Asbestos	PCME	EMSL	9/16/08	< 0.00077	No	No	
ASBESTOS-ST4-9/15/08	030832434-0003	Northwest Area (street-level)	9/15/08	1	2.860	Asbestos	PCME	EMSL	9/16/08	< 0.00086	No	No	
ASBESTOS-ST5-9/15/08	030832434-0004	Firehouse #10 (roof level)	9/15/08	1	3.050	Asbestos	PCME	EMSL	9/16/08	< 0.00081	No	No	
ASBESTOS-ST10-9/15/08	030832434-0005	North Side Sidewalk Bridge	9/15/08	1	3.090	Asbestos	PCME	EMSL	9/16/08	< 0.00080	No	No	
ASBESTOS-ST100-9/15/08	030832434-0013	Station 10 Field Duplicate	9/15/08	1	3.160	Asbestos	PCME	EMSL	9/18/08	< 0.00078	No	No	
ASBESTOS-ST11-9/15/08	030832434-0006	90 Trinity Place (roof level)	9/15/08	1	3.060	Asbestos	PCME	EMSL	9/16/08	< 0.00081	No	No	
ASBESTOS-ST12-9/15/08	030832434-0007	110 Greenwich Street (roof level)	9/15/08	1	3.100	Asbestos	PCME	EMSL	9/16/08	< 0.00080	No	No	
ASBESTOS-ST13-9/15/08	030832434-0008	Marriott Hotel, 38th Floor (roof level)	9/15/08	1	3.060	Asbestos	PCME	EMSL	9/16/08	< 0.00081	No	No	
ASBESTOS-ST14-9/15/08	030832434-0009	West Face - South end at corner (scaffolding level)	9/15/08	1	3.050	Asbestos	PCME	EMSL	9/16/08	< 0.00081	No	No	
ASBESTOS-ST15-9/15/08	030832434-0010	South Face - East end at corner (scaffolding level)	9/15/08	1	3.090	Asbestos	PCME	EMSL	9/16/08	< 0.00080	No	No	
ASBESTOS-ST16-9/15/08	030832434-0011	East Face - North end at corner (scaffolding level)	9/15/08	1	3.170	Asbestos	PCME	EMSL	9/16/08	< 0.00078	No	No	
ASBESTOS-ST17-9/15/08	030832434-0012	North Face - West end at corner (scaffolding level)	9/15/08	1	3.110	Asbestos	PCME	EMSL	9/16/08	< 0.00079	No	No	
ASBESTOS-ST1-9/16/08	030832620-0001	Southwest Area (sidewalk bridge level)	9/16/08	1	3.010	Asbestos	PCME	EMSL	9/17/08	< 0.00082	No	No	
ASBESTOS-ST2-9/16/08	030832620-0002	Southeast Area (sidewalk bridge level)	9/16/08	1	2.980	Asbestos	PCME	EMSL	9/17/08	< 0.00083	No	No	
ASBESTOS-ST4-9/16/08	030832620-0003	Northwest Area (street-level)	9/16/08	1	3.070	Asbestos	PCME	EMSL	9/17/08	< 0.00080	No	No	
ASBESTOS-ST5-9/16/08	030832620-0004	Firehouse #10 (roof level)	9/16/08	1	3.080	Asbestos	PCME	EMSL	9/17/08	< 0.00080	No	No	
ASBESTOS-ST10-9/16/08	030832620-0005	North Side Sidewalk Bridge	9/16/08	1	3.050	Asbestos	PCME	EMSL	9/17/08	< 0.00081	No	No	
ASBESTOS-ST11-9/16/08	030832620-0006	90 Trinity Place (roof level)	9/16/08	1	3.000	Asbestos	PCME	EMSL	9/17/08	< 0.00082	No	No	
ASBESTOS-ST12-9/16/08	030832620-0007	110 Greenwich Street (roof level)	9/16/08	1	3.050	Asbestos	PCME	EMSL	9/17/08	< 0.00081	No	No	
ASBESTOS-ST13-9/16/08	030832620-0008	Marriott Hotel, 38th Floor (roof level)	9/16/08	1	3.000	Asbestos	PCME	EMSL	9/17/08	< 0.00082	No	No	
ASBESTOS-ST14-9/16/08	030832620-0009	West Face - South end at corner (scaffolding level)	9/16/08	1	2.990	Asbestos	PCME	EMSL	9/17/08	< 0.00083	No	No	
ASBESTOS-ST15-9/16/08	030832620-0010	South Face - East end at corner (scaffolding level)	9/16/08	1	2.970	Asbestos	PCME	EMSL	9/17/08	< 0.00083	No	No	
ASBESTOS-ST16-9/16/08	030832620-0011	East Face - North end at corner (scaffolding level)	9/16/08	1	3.070	Asbestos	PCME	EMSL	9/17/08	< 0.00080	No	No	
ASBESTOS-ST17-9/16/08	030832620-0012	North Face - West end at corner (scaffolding level)	9/16/08	1	2.980	Asbestos	PCME	EMSL	9/17/08	< 0.00083	No	No	
ASBESTOS-ST1-9/17/08	030832775-0001	Southwest Area (sidewalk bridge level)	9/17/08	1	3.000	Asbestos	PCME	EMSL	9/18/08	< 0.00082	No	No	
ASBESTOS-ST2-9/17/08	030832775-0002	Southeast Area (sidewalk bridge level)	9/17/08	1	3.060	Asbestos	PCME	EMSL	9/18/08	< 0.00081	No	No	
ASBESTOS-ST4-9/17/08	030832775-0003	Northwest Area (street-level)	9/17/08	1	3.140	Asbestos	PCME	EMSL	9/18/08	< 0.00086	No	No	
ASBESTOS-ST5-9/17/08	030832775-0004	Firehouse #10 (roof level)	9/17/08	1	3.020	Asbestos	PCME	EMSL	9/18/08	< 0.00082	No	No	
ASBESTOS-ST10-9/17/08	030832775-0005	North Side Sidewalk Bridge	9/17/08	1	3.050	Asbestos	PCME	EMSL	9/18/08	< 0.00081	No	No	
ASBESTOS-ST11-9/17/08	030832775-0006	90 Trinity Place (roof level)	9/17/08	1	3.040	Asbestos	PCME	EMSL	9/18/08	< 0.00081	No	No	
ASBESTOS-ST12-9/17/08	030832775-0007	110 Greenwich Street (roof level)	9/17/08	1	3.120	Asbestos	PCME	EMSL	9/18/08	< 0.00086	No	No	
ASBESTOS-ST13-9/17/08	030832775-0008	Marriott Hotel, 38th Floor (roof level)	9/17/08	1	3.010	Asbestos	PCME	EMSL	9/18/08	< 0.00082	No	No	
ASBESTOS-ST14-9/17/08	030832775-0009	West Face - South end at corner (scaffolding level)	9/17/08	1	3.010	Asbestos	PCME	EMSL	9/18/08	< 0.00082	No	No	
ASBESTOS-ST15-9/17/08	030832775-0010	South Face - East end at corner (scaffolding level)	9/17/08	1	3.230	Asbestos	PCME	EMSL	9/18/08	< 0.00083	No	No	
ASBESTOS-ST16-9/17/08	030832775-0011	East Face - North end at corner (scaffolding level)	9/17/08	1	3.100	Asbestos	PCME	EMSL	9/18/08	< 0.00087	No	No	
ASBESTOS-ST17-9/17/08	030832775-0012	North Face - West end at corner (scaffolding level)	9/17/08	1	3.010	Asbestos	PCME	EMSL	9/18/08	< 0.00082	No	No	
ASBESTOS-ST1-9/18/08	030832948-0001	Southwest Area (sidewalk bridge level)	9/18/08	1	2.990	Asbestos	PCME	EMSL	9/19/08	< 0.00083	No	No	
ASBESTOS-ST2-9/18/08	030832948-0002	Southeast Area (sidewalk bridge level)	9/18/08	1	3.080	Asbestos	PCME	EMSL	9/19/08	< 0.00080	No	No	
ASBESTOS-ST4-9/18/08	030832948-0003	Northwest Area (street-level)	9/18/08	1	3.030	Asbestos	PCME	EMSL	9/19/08	< 0.00081	No	No	
ASBESTOS-ST5-9/18/08	030832948-0004	Firehouse #10 (roof level)	9/18/08	1	2.990	Asbestos	PCME	EMSL	9/19/08	< 0.00083	No	No	
ASBESTOS-ST10-9/18/08	030832948-0005	North Side Sidewalk Bridge	9/18/08	1	3.030	Asbestos	PCME	EMSL	9/19/08	< 0.00081	No	No	
ASBESTOS-ST11-9/18/08	030832948-0006	90 Trinity Place (roof level)	9/18/08	1	3.090	Asbestos	PCME	EMSL	9/19/08	< 0.00080	No	No	
ASBESTOS-ST12-9/18/08	030832948-0007	110 Greenwich Street (roof level)	9/18/08	1	3.060	Asbestos	PCME	EMSL	9/19/08	< 0.00081	No	No	
ASBESTOS-ST13-9/18/08	030832948-0008	Marriott Hotel, 38th Floor (roof level)	9/18/08	1	3.030	Asbestos	PCME	EMSL	9/19/08	< 0.00081	No	No	
ASBESTOS-ST14-9/18/08	030832948-0009	West Face - South end at corner (scaffolding level)	9/18/08	1	3.000	Asbestos	PCME	EMSL	9/19/08	< 0.00082	No	No	
ASBESTOS-ST15-9/18/08	030832948-0010	South Face - East end at corner (scaffolding level)	9/18/08	1	3.060	Asbestos	PCME	EMSL	9/19/08	< 0.00081	No	No	
ASBESTOS-ST16-9/18/08	030832948-0011	East Face - North end at corner (scaffolding level)	9/18/08	1	3.050	Asbestos	PCME	EMSL	9/19/08	< 0.00081	No	No	
ASBESTOS-ST17-9/18/08	030832948-0012	North Face - West end at corner (scaffolding level)	9/18/08	1	3.020	Asbestos	PCME	EMSL	9/19/08	< 0.00082	No	No	