

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target | Exceeds EPA | Comments |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|----------------|----------------|----------|
| | | | | | | | | | | 0.0009 | Air Quality | Site Specific | |
| | | | | | | | | | | NA | Levels | Trigger Levels | |
| Target Air Quality Levels | | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | | |
| ASBESTOS-ST1-9/19/09 | 030924196-0001 | Southwest Area (sidewalk bridge level) | 9/19/09 | 1 | 3.060 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00081 | No | No | |
| ASBESTOS-ST2-9/19/09 | 030924196-0002 | Southeast Area (sidewalk bridge level) | 9/19/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00082 | No | No | |
| ASBESTOS-ST4-9/19/09 | 030924196-0003 | Northwest Area (street-level) | 9/19/09 | 1 | 3.150 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00078 | No | No | |
| ASBESTOS-ST5-9/19/09 | 030924196-0004 | Firehouse #10 (roof level) | 9/19/09 | 1 | 3.170 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00078 | No | No | |
| ASBESTOS-ST10-9/19/09 | 030924196-0005 | North Side Sidewalk Bridge | 9/19/09 | 1 | 3.120 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00079 | No | No | |
| ASBESTOS-ST11-9/19/09 | 030924196-0006 | 90 Trinity Place (roof level) | 9/19/09 | 1 | 3.060 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00081 | No | No | |
| ASBESTOS-ST12-9/19/09 | 030924196-0007 | 110 Greenwich Street (roof level) | 9/19/09 | 1 | 3.190 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00077 | No | No | |
| ASBESTOS-ST13-9/19/09 | 030924196-0008 | Marriott Hotel, 38th Floor (roof level) | 9/19/09 | 1 | 3.120 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00079 | No | No | |
| ASBESTOS-ST1-9/20/09 | 030924195-0001 | Southwest Area (sidewalk bridge level) | 9/20/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00080 | No | No | |
| ASBESTOS-ST2-9/20/09 | 030924195-0002 | Southeast Area (sidewalk bridge level) | 9/20/09 | 1 | 3.090 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00080 | No | No | |
| ASBESTOS-ST4-9/20/09 | 030924195-0003 | Northwest Area (street-level) | 9/20/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00080 | No | No | |
| ASBESTOS-ST5-9/20/09 | 030924195-0004 | Firehouse #10 (roof level) | 9/20/09 | 1 | 2.840 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00087 | No | No | |
| ASBESTOS-ST10-9/20/09 | 030924195-0005 | North Side Sidewalk Bridge | 9/20/09 | 1 | 3.050 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00081 | No | No | |
| ASBESTOS-ST11-9/20/09 | 030924195-0006 | 90 Trinity Place (roof level) | 9/20/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00080 | No | No | |
| ASBESTOS-ST12-9/20/09 | 030924195-0007 | 110 Greenwich Street (roof level) | 9/20/09 | 1 | 2.980 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00083 | No | No | |
| ASBESTOS-ST13-9/20/09 | 030924195-0008 | Marriott Hotel, 38th Floor (roof level) | 9/20/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 9/21/09 | < 0.00081 | No | No | |
| ASBESTOS-ST1-9/21/09 | 030924310-0001 | Southwest Area (sidewalk bridge level) | 9/21/09 | 1 | 2.920 | Asbestos | PCME | EMSL | 9/22/09 | < 0.00085 | No | No | |
| ASBESTOS-ST2-9/21/09 | 030924310-0002 | Southeast Area (sidewalk bridge level) | 9/21/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 9/22/09 | < 0.00082 | No | No | |
| ASBESTOS-ST4-9/21/09 | 030924310-0003 | Northwest Area (street-level) | 9/21/09 | 1 | 3.000 | Asbestos | PCME | EMSL | 9/22/09 | < 0.00082 | No | No | |
| ASBESTOS-ST5-9/21/09 | 030924310-0004 | Firehouse #10 (roof level) | 9/21/09 | 1 | 2.990 | Asbestos | PCME | EMSL | 9/22/09 | < 0.00083 | No | No | |
| ASBESTOS-ST10-9/21/09 | 030924310-0005 | North Side Sidewalk Bridge | 9/21/09 | 1 | 2.990 | Asbestos | PCME | EMSL | 9/22/09 | < 0.00083 | No | No | |
| ASBESTOS-ST11-9/21/09 | 030924310-0006 | 90 Trinity Place (roof level) | 9/21/09 | 1 | 3.060 | Asbestos | PCME | EMSL | 9/22/09 | < 0.00081 | No | No | |
| ASBESTOS-ST12-9/21/09 | 030924310-0007 | 110 Greenwich Street (roof level) | 9/21/09 | 1 | 2.990 | Asbestos | PCME | EMSL | 9/22/09 | < 0.00083 | No | No | |
| ASBESTOS-ST13-9/21/09 | 030924310-0008 | Marriott Hotel, 38th Floor (roof level) | 9/21/09 | 1 | 3.070 | Asbestos | PCME | EMSL | 9/22/09 | < 0.00080 | No | No | |
| ASBESTOS-ST1-9/22/09 | 030924418-0001 | Southwest Area (sidewalk bridge level) | 9/22/09 | 1 | 3.070 | Asbestos | PCME | EMSL | 9/23/09 | < 0.00080 | No | No | |
| ASBESTOS-ST2-9/22/09 | 030924418-0002 | Southeast Area (sidewalk bridge level) | 9/22/09 | 1 | 3.100 | Asbestos | PCME | EMSL | 9/23/09 | < 0.00080 | No | No | |
| ASBESTOS-ST4-9/22/09 | 030924418-0003 | Northwest Area (street-level) | 9/22/09 | 1 | 3.090 | Asbestos | PCME | EMSL | 9/23/09 | < 0.00080 | No | No | |
| ASBESTOS-ST5-9/22/09 | 030924418-0004 | Firehouse #10 (roof level) | 9/22/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 9/23/09 | < 0.00082 | No | No | |
| ASBESTOS-ST10-9/22/09 | 030924418-0005 | North Side Sidewalk Bridge | 9/22/09 | 1 | 3.060 | Asbestos | PCME | EMSL | 9/23/09 | < 0.00081 | No | No | |
| ASBESTOS-ST11-9/22/09 | 030924418-0006 | 90 Trinity Place (roof level) | 9/22/09 | 1 | 3.050 | Asbestos | PCME | EMSL | 9/23/09 | < 0.00081 | No | No | |
| ASBESTOS-ST12-9/22/09 | 030924418-0007 | 110 Greenwich Street (roof level) | 9/22/09 | 1 | 3.110 | Asbestos | PCME | EMSL | 9/23/09 | < 0.00079 | No | No | |
| ASBESTOS-ST13-9/22/09 | 030924418-0008 | Marriott Hotel, 38th Floor (roof level) | 9/22/09 | 1 | 3.030 | Asbestos | PCME | EMSL | 9/23/09 | < 0.00081 | No | No | |