

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-9/23/09	030924503-0001	Southwest Area (sidewalk bridge level)	9/23/09	1	3.030	Asbestos	PCME	EMSL	9/24/09	< 0.00081	No	No	
ASBESTOS-ST2-9/23/09	030924503-0002	Southeast Area (sidewalk bridge level)	9/23/09	1	3.010	Asbestos	PCME	EMSL	9/24/09	< 0.00082	No	No	
ASBESTOS-ST4-9/23/09	030924503-0003	Northwest Area (street-level)	9/23/09	1	3.040	Asbestos	PCME	EMSL	9/24/09	< 0.00081	No	No	
ASBESTOS-ST5-9/23/09	030924503-0004	Firehouse #10 (roof level)	9/23/09	1	3.090	Asbestos	PCME	EMSL	9/24/09	< 0.00080	No	No	
ASBESTOS-ST10-9/23/09	030924503-0005	North Side Sidewalk Bridge	9/23/09	1	3.130	Asbestos	PCME	EMSL	9/24/09	< 0.00079	No	No	
ASBESTOS-ST11-9/23/09	030924503-0006	90 Trinity Place (roof level)	9/23/09	1	3.010	Asbestos	PCME	EMSL	9/24/09	< 0.00082	No	No	
ASBESTOS-ST12-9/23/09	030924503-0007	110 Greenwich Street (roof level)	9/23/09	1	3.040	Asbestos	PCME	EMSL	9/24/09	< 0.00081	No	No	
ASBESTOS-ST13-9/23/09	030924503-0008	Marriott Hotel, 38th Floor (roof level)	9/23/09	1	3.010	Asbestos	PCME	EMSL	9/24/09	< 0.00082	No	No	
ASBESTOS-ST1-9/24/09	030924606-0001	Southwest Area (sidewalk bridge level)	9/24/09	1	2.930	Asbestos	PCME	EMSL	9/25/09	< 0.00084	No	No	
ASBESTOS-ST2-9/24/09	030924606-0002	Southeast Area (sidewalk bridge level)	9/24/09	1	2.970	Asbestos	PCME	EMSL	9/25/09	< 0.00083	No	No	
ASBESTOS-ST4-9/24/09	030924606-0003	Northwest Area (street-level)	9/24/09	1	3.070	Asbestos	PCME	EMSL	9/25/09	< 0.00080	No	No	
ASBESTOS-ST5-9/24/09	030924606-0004	Firehouse #10 (roof level)	9/24/09	1	2.940	Asbestos	PCME	EMSL	9/25/09	< 0.00084	No	No	
ASBESTOS-ST10-9/24/09	030924606-0005	North Side Sidewalk Bridge	9/24/09	1	2.980	Asbestos	PCME	EMSL	9/25/09	< 0.00083	No	No	
ASBESTOS-ST100-9/24/09	030924606-0009	Station 10 Field Duplicate	9/24/09	1	3.020	Asbestos	PCME	EMSL	9/25/09	< 0.00082	No	No	
ASBESTOS-ST11-9/24/09	030924606-0006	90 Trinity Place (roof level)	9/24/09	1	2.970	Asbestos	PCME	EMSL	9/25/09	< 0.00083	No	No	
ASBESTOS-ST12-9/24/09	030924606-0007	110 Greenwich Street (roof level)	9/24/09	1	3.030	Asbestos	PCME	EMSL	9/25/09	< 0.00081	No	No	
ASBESTOS-ST13-9/24/09	030924606-0008	Marriott Hotel, 38th Floor (roof level)	9/24/09	1	3.100	Asbestos	PCME	EMSL	9/25/09	< 0.00087	No	No	
ASBESTOS-ST1-9/25/09	030924666-0001	Southwest Area (sidewalk bridge level)	9/25/09	1	3.050	Asbestos	PCME	EMSL	9/26/09	< 0.00081	No	No	
ASBESTOS-ST2-9/25/09	030924666-0002	Southeast Area (sidewalk bridge level)	9/25/09	1	2.970	Asbestos	PCME	EMSL	9/26/09	< 0.00083	No	No	
ASBESTOS-ST4-9/25/09	030924666-0003	Northwest Area (street-level)	9/25/09	1	2.960	Asbestos	PCME	EMSL	9/26/09	< 0.00083	No	No	
ASBESTOS-ST5-9/25/09	030924666-0004	Firehouse #10 (roof level)	9/25/09	1	3.010	Asbestos	PCME	EMSL	9/26/09	< 0.00082	No	No	
ASBESTOS-ST10-9/25/09	030924666-0005	North Side Sidewalk Bridge	9/25/09	1	3.110	Asbestos	PCME	EMSL	9/26/09	< 0.00079	No	No	
ASBESTOS-ST11-9/25/09	030924666-0006	90 Trinity Place (roof level)	9/25/09	1	3.000	Asbestos	PCME	EMSL	9/26/09	< 0.00082	No	No	
ASBESTOS-ST12-9/25/09	030924666-0007	110 Greenwich Street (roof level)	9/25/09	1	2.920	Asbestos	PCME	EMSL	9/26/09	< 0.00085	No	No	
ASBESTOS-ST13-9/25/09	030924666-0008	Marriott Hotel, 38th Floor (roof level)	9/25/09	1	3.010	Asbestos	PCME	EMSL	9/26/09	< 0.00082	No	No	