

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-9/30/09	030925124-0001	Southwest Area (sidewalk bridge level)	9/30/09	1	3.050	Asbestos	PCME	EMSL	10/1/09	< 0.00081	No	No	
ASBESTOS-ST2-9/30/09	030925124-0002	Southeast Area (sidewalk bridge level)	9/30/09	1	2.790	Asbestos	PCME	EMSL	10/1/09	< 0.00088	No	No	Note 1
ASBESTOS-ST4-9/30/09	030925124-0003	Northwest Area (street-level)	9/30/09	1	2.970	Asbestos	PCME	EMSL	10/1/09	< 0.00083	No	No	
ASBESTOS-ST5-9/30/09	030925124-0004	Firehouse #10 (roof level)	9/30/09	1	2.780	Asbestos	PCME	EMSL	10/1/09	< 0.00089	No	No	Note 1
ASBESTOS-ST10-9/30/09	030925124-0005	North Side Sidewalk Bridge	9/30/09	1	3.000	Asbestos	PCME	EMSL	10/1/09	< 0.00082	No	No	
ASBESTOS-ST11-9/30/09	030925124-0006	90 Trinity Place (roof level)	9/30/09	1	3.090	Asbestos	PCME	EMSL	10/1/09	< 0.00080	No	No	
ASBESTOS-ST12-9/30/09	030925124-0007	110 Greenwich Street (roof level)	9/30/09	1	2.970	Asbestos	PCME	EMSL	10/1/09	< 0.00083	No	No	
ASBESTOS-ST13-9/30/09	030925124-0008	Marriott Hotel, 38th Floor (roof level)	9/30/09	1	3.030	Asbestos	PCME	EMSL	10/1/09	< 0.00081	No	No	
ASBESTOS-ST1-10/1/09	030925237-0001	Southwest Area (sidewalk bridge level)	10/1/09	1	2.960	Asbestos	PCME	EMSL	10/2/09	< 0.00083	No	No	
ASBESTOS-ST2-10/1/09	030925237-0002	Southeast Area (sidewalk bridge level)	10/1/09	1	2.990	Asbestos	PCME	EMSL	10/2/09	< 0.00083	No	No	
ASBESTOS-ST4-10/1/09	030925237-0003	Northwest Area (street-level)	10/1/09	1	3.140	Asbestos	PCME	EMSL	10/2/09	< 0.00079	No	No	
ASBESTOS-ST5-10/1/09	030925237-0004	Firehouse #10 (roof level)	10/1/09	1	3.100	Asbestos	PCME	EMSL	10/2/09	< 0.00080	No	No	
ASBESTOS-ST10-10/1/09	030925237-0005	North Side Sidewalk Bridge	10/1/09	1	2.980	Asbestos	PCME	EMSL	10/2/09	< 0.00083	No	No	
ASBESTOS-ST11-10/1/09	030925237-0006	90 Trinity Place (roof level)	10/1/09	1	3.070	Asbestos	PCME	EMSL	10/2/09	< 0.00080	No	No	
ASBESTOS-ST12-10/1/09	030925237-0007	110 Greenwich Street (roof level)	10/1/09	1	3.020	Asbestos	PCME	EMSL	10/2/09	< 0.00082	No	No	
ASBESTOS-ST13-10/1/09	030925237-0008	Marriott Hotel, 38th Floor (roof level)	10/1/09	1	3.040	Asbestos	PCME	EMSL	10/2/09	< 0.00081	No	No	
ASBESTOS-ST1-10/2/09	030925303-0001	Southwest Area (sidewalk bridge level)	10/2/09	1	3.020	Asbestos	PCME	EMSL	10/3/09	< 0.00082	No	No	
ASBESTOS-ST2-10/2/09	030925303-0002	Southeast Area (sidewalk bridge level)	10/2/09	1	2.980	Asbestos	PCME	EMSL	10/3/09	< 0.00083	No	No	
ASBESTOS-ST4-10/2/09	030925303-0003	Northwest Area (street-level)	10/2/09	1	2.980	Asbestos	PCME	EMSL	10/3/09	< 0.00083	No	No	
ASBESTOS-ST5-10/2/09	030925303-0004	Firehouse #10 (roof level)	10/2/09	1	3.020	Asbestos	PCME	EMSL	10/3/09	< 0.00082	No	No	
ASBESTOS-ST10-10/2/09	030925303-0005	North Side Sidewalk Bridge	10/2/09	1	3.080	Asbestos	PCME	EMSL	10/3/09	< 0.00080	No	No	
ASBESTOS-ST100-10/2/09	030925303-0009	Station 10 Field Duplicate	10/2/09	1	3.080	Asbestos	PCME	EMSL	10/3/09	< 0.00080	No	No	
ASBESTOS-ST11-10/2/09	030925303-0006	90 Trinity Place (roof level)	10/2/09	1	3.040	Asbestos	PCME	EMSL	10/3/09	< 0.00081	No	No	
ASBESTOS-ST12-10/2/09	030925303-0007	110 Greenwich Street (roof level)	10/2/09	1	3.090	Asbestos	PCME	EMSL	10/3/09	< 0.00080	No	No	
ASBESTOS-ST13-10/2/09	030925303-0008	Marriott Hotel, 38th Floor (roof level)	10/2/09	1	3.050	Asbestos	PCME	EMSL	10/3/09	< 0.00081	No	No	

Note:

1. The asbestos sample volumes from Station 2 (Southeast Area [sidewalk bridge level]) and Station 5 (Firehouse #10 [roof level]) on September 30, 2009 were reduced on account of a 180 minute power outage.