

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-10/8/07	030733443-0001	Southwest Area (sidewalk bridge level)	10/8/07	1	3.340	Asbestos	PCME	EMSL	10/10/07	< 0.00074	No	No	
ASBESTOS-ST2-10/8/07	030733443-0002	Southeast Area (sidewalk bridge level)	10/8/07	1	3.020	Asbestos	PCME	EMSL	10/10/07	< 0.00082	No	No	
ASBESTOS-ST4-10/8/07	030733443-0003	Northwest Area (street-level)	10/8/07	1	3.020	Asbestos	PCME	EMSL	10/10/07	< 0.00082	No	No	
ASBESTOS-ST5-10/8/07	030733443-0004	Firehouse #10 (roof level)	10/8/07	1	2.920	Asbestos	PCME	EMSL	10/10/07	< 0.00085	No	No	
ASBESTOS-ST10-10/8/07	030733443-0005	North Side Sidewalk Bridge	10/8/07	1	3.040	Asbestos	PCME	EMSL	10/10/07	< 0.00081	No	No	
ASBESTOS-ST11-10/8/07	030733443-0006	90 Trinity Place (roof level)	10/8/07	1	3.010	Asbestos	PCME	EMSL	10/10/07	< 0.00082	No	No	
ASBESTOS-ST12-10/8/07	030733443-0007	110 Greenwich Street (roof level)	10/8/07	1	3.010	Asbestos	PCME	EMSL	10/10/07	< 0.00082	No	No	
ASBESTOS-ST13-10/8/07	030733443-0008	Marriott Hotel, 38th Floor (roof level)	10/8/07	1	3.050	Asbestos	PCME	EMSL	10/10/07	< 0.00081	No	No	
ASBESTOS-ST14-10/8/07	030733443-0009	West Face - South end at corner (scaffolding level)	10/8/07	1	3.050	Asbestos	PCME	EMSL	10/10/07	< 0.00081	No	No	
ASBESTOS-ST15-10/8/07	030733443-0010	South Face - East end at corner (scaffolding level)	10/8/07	1	2.960	Asbestos	PCME	EMSL	10/10/07	< 0.00083	No	No	
ASBESTOS-ST16-10/8/07	030733443-0011	East Face - North end at corner (scaffolding level)	10/8/07	1	3.050	Asbestos	PCME	EMSL	10/10/07	< 0.00081	No	No	
ASBESTOS-ST17-10/8/07	030733443-0012	North Face - West end at corner (scaffolding level)	10/8/07	1	3.020	Asbestos	PCME	EMSL	10/10/07	< 0.00082	No	No	
ASBESTOS-ST1-10/9/07	030733441-0001	Southwest Area (sidewalk bridge level)	10/9/07	1	3.010	Asbestos	PCME	EMSL	10/10/07	< 0.00082	No	No	
ASBESTOS-ST2-10/9/07	030733441-0002	Southeast Area (sidewalk bridge level)	10/9/07	1	2.990	Asbestos	PCME	EMSL	10/10/07	< 0.00083	No	No	
ASBESTOS-ST4-10/9/07	030733441-0003	Northwest Area (street-level)	10/9/07	1	3.030	Asbestos	PCME	EMSL	10/10/07	< 0.00081	No	No	
ASBESTOS-ST5-10/9/07	030733441-0004	Firehouse #10 (roof level)	10/9/07	1	3.090	Asbestos	PCME	EMSL	10/10/07	< 0.00080	No	No	
ASBESTOS-ST10-10/9/07	030733441-0005	North Side Sidewalk Bridge	10/9/07	1	2.920	Asbestos	PCME	EMSL	10/10/07	< 0.00085	No	No	
ASBESTOS-ST100-10/9/07	030733441-0013	Station 10 Field Duplicate	10/9/07	1	3.070	Asbestos	PCME	EMSL	10/10/07	< 0.00080	No	No	
ASBESTOS-ST11-10/9/07	030733441-0006	90 Trinity Place (roof level)	10/9/07	1	3.060	Asbestos	PCME	EMSL	10/10/07	< 0.00081	No	No	
ASBESTOS-ST12-10/9/07	030733441-0007	110 Greenwich Street (roof level)	10/9/07	1	3.040	Asbestos	PCME	EMSL	10/10/07	< 0.00081	No	No	
ASBESTOS-ST13-10/9/07	030733441-0008	Marriott Hotel, 38th Floor (roof level)	10/9/07	1	3.090	Asbestos	PCME	EMSL	10/10/07	< 0.00080	No	No	
ASBESTOS-ST14-10/9/07	030733441-0009	West Face - South end at corner (scaffolding level)	10/9/07	1	2.920	Asbestos	PCME	EMSL	10/10/07	< 0.00085	No	No	
ASBESTOS-ST15-10/9/07	030733441-0010	South Face - East end at corner (scaffolding level)	10/9/07	1	3.000	Asbestos	PCME	EMSL	10/10/07	< 0.00082	No	No	
ASBESTOS-ST16-10/9/07	030733441-0011	East Face - North end at corner (scaffolding level)	10/9/07	1	3.040	Asbestos	PCME	EMSL	10/10/07	< 0.00081	No	No	
ASBESTOS-ST17-10/9/07	030733441-0012	North Face - West end at corner (scaffolding level)	10/9/07	1	3.000	Asbestos	PCME	EMSL	10/10/07	< 0.00082	No	No	